Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

**SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

\	OMB No. 1004-0135 Expires November 30, 2000 STATE
١	Lease Scrial No.
,	1.m/c 1261936-A

If Indian, Allottee or Tribe Name

	· · · · · · · · · · · · · · · · · · ·			/		
Supplier No.	PERSONAL PROPERTY		Sec.	7. If Unit or CA/Agreement, Name and/or No. #1		
1. Type of Well			30-025-0819)			
Q Oil Well Gas Well		8. Well Name and No.				
2. Name of Operator		Cotton Draw Unit				
Pogo Producing		9. API Well No.				
3a. Address	: area code)	30-025-08195				
PO Box 10340, Mi	10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec.		Paduca				
660 from North	∍	11. County or Parish, State				
Sec. 16, T-25 S		Lea County, N.M.				
12. CHECK AF	PROPRIATE BOX(ES	S) TO INDICATE NATU	RE OF NOTICE, RE	PORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
	Acidize	Deepen	Production (Start/	Resume)		
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

Temporarily Abandon

Water Disposal

1. Move in Open Top Pit to circulate into.

☐ Change Plans

Convert to Injection

2. Set CIBP at 4,650'.

Final Abandonment Notice

- Circulate hole w/ mud.
- 4. Cap CIBP w/ 45 sx of cement. Top of cement 50' above Base of Salt.
- 5. Perforate casing at 1,300'.
- 6. Sqz perforation w/ 45 sx of cement. Top of cement at 1,048'Tag
- 7. Perforate casing at 405'.
- 8. Sqz perforation w/ 125 sx of cement, circulate cement to Surf.
- 9. Install Dry Hole Marker

THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE

14. I bereby certify that the foregoing is true and correct	BEGINNING OF PLUGGING OPERATIO			
Name (Printed/Typed)	1			
Howard Boatright	Title Age	nt		
Signature // South	Date	2/22/06	t.	
A CHURCH STARTS OF REDER				
Approved by	Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		1		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for	any person know	ingly and willfully to make to	any department or agency of the United	

255, 32E Sec. 15-K 1980/S 1980/W GWW

## **MAVERICK WELL PLUGGERS**

**COMPANY:** Pogo Producing Co.

WELL NAME: Cotton Draw

WELL #: #8

COUNTY: Lea County, N. M.

**LEASE ID:** 

SURFACE CASING								
OD	WT/FT	GRADE	SET AT	TOC				
8-5/8"	24	K 55	355'	Surface				
INTERMEDIATE CASING								
OD	WT/FT	GRADE	SET AT	TOC				
PRODUCTION CASING								
OD	WT/FT	GRADE	SET AT	TOC				
4-1/2"	9.5	K 55	4,852'	4,200'				
TUBING								
OD	WT/FT	GRADE	SET AT	TAC				

