Conditions of Approval, if any:

Lou Worthan No. 15 Downhole Commingle Tubb, Drinkard, & Wantz Abo

01/05/2006 MIRU PU. Unseat pump. POOH w/ rods and pump. Remove well head. Install BOP. Unset TAC. POOH w/ 184 jts 2 7/8" tgb. RIH w/ bailer BHA & 172 jts tbg.

01/06/2006 FIH w/ tbg. Tag top of sand @ 6134'. Bailed 30' sand of RBP @ 6164'. Wait one hour. RIH tagged RBP clean. No fill. POOH w/ 191 jts tbg & BHA. RIH w/ retrieving head, bailer BHA & 172 jts. SI.

01/09/2006 FIH w/ tbg. Tag top of sand @ 6158'. Bailed 6' sand off RBP @ 6164'. Unset RBP. POOH w/ 191 jts tbg, bailer, retrieving head, & RBP. Close blind rams and leave casing open to flowline.

01/10/2006 Kill well. LD 8 jts tbg. RIH w/ cavens desander w/ 3 ½" Mother Hubbard Gas Separator / mud joint cavity, 2 3/8" seating nipple, 2 3/8" special Enduro alloy jt, and 222 jts 2 3/8" tbg. Tag PBTD @ 7069' on 225 jts. POH lay down 2 jts. Bottom of Cavins Desander gas separator @ 7013'. Seating Nipple @ 6962'. Remove BOP. Flange up wellhead.

01/11/2006 RIH w/ rods & pump. Hang well on. Load and test pump to 1000 psi. Held w/ good pump action. Leave well producing to facilities.

