OCD-HOBBS Form 3160-5 (August 1999) FORM APPROVED OMB No. 1004-0135 UNITED STATES DEPARTMENT OF THE INTERIOR Expires November 30, 2000 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS 061869 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other Instructions on mysers sich 7. If Unit or CA/Agreement, Name and/or No. Type of Well Oil Well Gas Well Other 8. Well Name and No. Cotton Draw Unit #25 2. Name of Operator 9. API Well No. Pogo Producing Company 3b. Phone No. (include area code) 30-02508203 PO Box 10340, Midland, TX 79702 432-617-0208 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 660 from North & 660 from East 5-S-R 32 E Lea County, N.M. 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Deepen Water Shut-Off Production (Start/Resume) Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. Move in Steel Pit to circulate into. 2. Set CIBP at 4,565'. 3. Circulate Hole w/ mud. 4. Cap CIBP w/ 30 sx of cement, cover Base of Salt. Perforate casing at 1,300 ft. 5. Sqz perforation w/ 45 sx of cement, cover Top of Salt, WOC. 6. 7. Tag top of Plug at 1,042 ft. 8. Perforate casing at 400 ft. Sqz perforation w/ 25 sx of cement, circulate cement to Surf. Install Dry Hole Marker. APPROVED 2006 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) LES BABYAK Boatright <u>Agent</u> PETROLEUM ENGINEER 2/22/06 CALSTOTE OFFICE Title Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW

## MAVERICK WELL PLUGGERS

COMPANY: Pogo Producing Co.

WELL NAME: Cotton Draw

WELL #: # 25

COUNTY: Lea County, N. M.

**LEASE ID: 61869** 

				4.7.3
	S	URFACE CASIN	NG	/: [,
OD	WT/FT	GRADE	SET AT	TOC\ ∂
8-5/8"	24	K 55	325'	Surface
	INTE	RMEDIATE CA	SING	
OD	WT/FT	GRADE	SET AT	TOC
<u>_</u>	PRO	ODUCTION CAS	SING	
OD	WT/FT	GRADE	SET AT	TOC
4-1/2"	9.5	K 55	4,785'	4,000' Cal.
		TUBING		
OD	WT/FT	GRADE	SET AT	TAC

