

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-07005
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MARK OWEN
8. Well Number: 6
9. OGRID Number 4323
10. Pool name or Wildcat PENROSE SKELLY GRAYBURG

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☒ Other
2. Name of Operator Chevron USA INC.
3. Address of Operator 15 Smith Rd. Midland, TX 79705
4. Well Location Unit Letter O : 554 feet from the South line and 2086 feet from the East line Section 34 Township 21S Range 37E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Call and notify NMOCD 24 hrs. before operations begin.
2. MIRU.
3. POH w/rods. NDWH and NU BOPE. POH w/tubing.
4. Set CIBP@3,590' over perforations 3650' to 3855'.
5. RIH w/workstring and spot 25sx of class "C" cement on top of CIBP. PUH.
6. Load and test casing to 550 psi for 30 minutes and chart. Give NMOCD 48 hr notice to witness.
7. Displace hole w/2% KCL w/corrosion inhibitor.
8. POH and LD workstring. ND BOPE. NUWH.

**Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Lee Roark TITLE Project Manager DATE 11/03/15

Type or print name M. Lee Roark E-mail address: LRoark@Chevron.com PHONE: (432)-687-7279


For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 11/12/2015
Conditions of Approval (if any):

NOV 18 2015


Chevron U.S.A. Inc. Wellbore Diagram : MARKOWEN 06GH

Lease: OEU EUNICE FMT		Well No.: OWEN MARK 6H	Field: FLD-PENROSE SKELLY	
Location: 554FSL2086FEL		Sec.: N/A	Blk:	Survey: N/A
County: Lea	St.: New Mexico	Refno: FA8102	API: 3002507005	Cost Center: UCU490
Section: 34		Township: 021 S		Range: 037 E
Current Status: ACTIVE			Dead Man Anchors Test Date: 08/09/200	
Directions:				



Chevron U.S.A. Inc. Wellbore Diagram : MARKOWEN 06GH

Lease: OEU EUNICE FMT		Well No.: OWEN MARK 6H	Field: FLD-PENROSE SKELLY	
Location: 554FSL2086FEL		Sec.: N/A	Blk:	Survey: N/A
County: Lea	St.: New Mexico	Refno: FA8102	API: 3002507005	Cost Center: UCU490400
Section: 34		Township: 021 S		Range: 037 E
Current Status: ACTIVE			Dead Man Anchors Test Date: 08/09/2005	
Directions:				



Ground Elevation (MSL): 3433.00	Spud Date: 09/24/1970	Compl. Date: 01/01/1970
Well Depth Datum: Kelly Bushing	Elevation (MSL): 0.00	Correction Factor: 12.00
Last Updated by: rodgekl	Date: 08/05/2015	