## HOBBS OCD

		DEC 1 6 2015
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		30-025-01153
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		315181
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Abalone AMB State
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	JCATION FOR PERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well	Gas Well 🗌 Other	8. Well Number #001
2. Name of Operator Foundation	ation Energy Management, LLC	9. OGRID Number 370740
3. Address of Operator		10. Pool name or Wildcat
16000 North Dallas Parkwa	ay, Suite 875, Dallas, TX 75248	Saunders Permo Upper Penn
4. Well Location	660 North 6	60 Woot
Unit Letter D	660feet from the Northline and _60	60feet from the Westline
Section 26	Township 14S Range 33E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	2.)
	4209' DF	
12. Check	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF I	NTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		
PULL OR ALTER CASING		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
	pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co ecompletion.	
	atta ala al mua aa duwa a	and succellla and all analysis
Please see	attached procedures a	and wellbore digram
		•
Spud Date:	Rig Release Date:	
oput but.	rig release bate.	
I hereby certify that the information	above is true and complete to the best of my knowled	ge and helief
Thereby certify that the internation	above is the and complete to the best of my knowled	ge and benef.
SIGNATURE ( auto O'll	HSE/Pogulator	y Tech 12/16/2015
	TITLE HSE/Regulator	y Tech DATE 12/10/2015
Caitlin O'	Hair	
Type or print name	Hair E-mail address:	
Type or print name	Hair E-mail address: regulatory@found	dationenergy.com PHONE: 918-526-5591
For State Use Only R. M.	Hair E-mail address: regulatory@found	dationenergy.com PHONE: 918-526-5591
For State Use Only APPROVED BY: Sill	Hair	dationenergy.com PHONE: 918-526-5591
For State Use Only R. M.	Hair E-mail address: regulatory@found	dationenergy.com PHONE: 918-526-5591

DEC 2 1 2015

## Overall plan for the Abalone #1:

- Conduct a workover to pull the tubing & ESP pump within the next two weeks. Target date of December 21 or sooner, depending on rig availability.
- Once the tubing & pump have been removed, run a pulsated neutron log to determine the exact
  recompletion interval in the Wolf camp. During the same WO we will also swab test each Bough
  interval to see if we can identify were the current water production is coming from.
- Upon determining the recompletion interval 2-3 weeks after running the log (target date is second week of January), regroup and commence the recompletion workover. Depending on the Swabbing results we will decide whether or not to co-mingle the Bough and the Wolcamp

Below is the procedure for the first WO; the second WO procedure will vary depending on the results of the first WO.


## Day 1

- MIRU (include laying of a flare or flare trailer hooked up, in case the need to get rid of the h2s gas is needed.)
- 2. ND WH, NU BOP
- 3. Pressure test BOP to 5000 PSI
- 4. POOH TBG + Cord + ESP

## Day 2-4

- 5. RIH w/ TBG & PKR + RBP as needed to isolate Bough intervals and swab to determine inflow
  - a. Hydro test while running in hole with tools
  - b. Move RBP + PKR to each bough zones and swab 2 bottoms up. Record results.
- 6. POOH w/ tools and TBG, laying TBG on the ground.
- 7. RU wireline,
- 8. Run RPM Log, use CBL to correlate logging tool
  - a. Analyze results on location with analyst and geology
- 9. Based on results, decide what intervals to swab test
- 10. ND BOP, ND WH
- 11. RDMO

138 12/17/15



B8 12/17/15