<u>District I</u> 1625 N. French D District II	Dr., Hobbs,	NM 88240	Е		State of Ne Minerals &	w Mexico Natural Resou		HOBBS O	CD		Form C-104 Revised August 1, 2011
811 S. First St., A District III 1000 Rio Brazos District IV 1220 S. St. Franci	Rd., Aztec	, NM 87410 ta Fe, NM 875	505	Oi 122	l Conservat 20 South St Santa Fe, N	ion Division Francis Dr. IM 87505	D	RECEIVE	D		ropriate District Office
<sup>1</sup> Operator na CHEVRON U	U.S.A. IN	Address	EST FO	RALL	OWABLE	AND AUTH		<sup>2</sup> OGRID N 4323		ANSI	PORT
15 SMITH R MIDLAND, 7		79705						<sup>3</sup> Reason for RECOMPL			tive Date
<sup>4</sup> API Numbe 3002526250	6		Name		H; WOLFCAN	IP NORTH		KECONIFL		Code	4500
<sup>7</sup> Property Co			oerty Nan		DSDALE D F	EDERAL				- 70	001
	face Lo Section 4		Range 32E	Lot Idn	Feet from the	e North/South Lin SOUTH	ne ]	Feet from th 660	e East/We EAS		County LEA
		le Locatio Township	n Range	Lot Idn	Feet from the	e North/South lin	ie ]	Feet from th	e East/We	est line	County
<sup>12</sup> Lse Code FEDERAL		ing Method LOWING	Da	onnection ate /2015	<sup>15</sup> C-129 Per	rmit Number	<sup>6</sup> C-	129 Effectiv	e Date	<sup>17</sup> C-12	29 Expiration Date
III. Oil a		Transpor			10						20
<sup>18</sup> Transport OGRID	ter					orter Name ddress					<sup>20</sup> O/G/W
					PLA	AINS					OIL
											GAS
				F	OUR STAR (	OIL & GAS CO.					
							_				
		*:	**well na			A 'COM' WELL)	FE	DERAL #00	1		
IV. Well	Comple	etion Data									
<sup>21</sup> Spud Dat 08/06/2015	te	<sup>22</sup> Ready 1 08/25/20	Date 015	1	<sup>23</sup> TD 13,000	<sup>24</sup> <b>PBTD</b> 12,968		<sup>25</sup> Perfor 10,585 –		14	<sup>26</sup> <b>DHC, MC</b>
<sup>27</sup> Hol	le Size		<sup>28</sup> Casing	g & Tubin	ng Size	<sup>29</sup> Depth	Set		4	<sup>30</sup> Sack	s Cement
NO CH	IANGE										
1. 1. 1.	<u>Rs</u>				1.1.1	1.1					
	in o		7/8" TB	G SET @	10,687'	" Gille				N. T.	
V. Well 7 <sup>31</sup> Date New 0 08/31/2015	Oil <sup>32</sup>	ta <sup>2</sup> Gas Delive 08/31/20			Fest Date /31/2015	<sup>34</sup> Test Len 24 HRS		35 -	Гbg. Pressu	re	<sup>36</sup> Csg. Pressure
<sup>37</sup> Choke Siz	ze	<sup>38</sup> Oil 185		39	Water 31	<sup>40</sup> Gas 404				6 - 4 - F	<sup>41</sup> Test Method FLOWING
<sup>42</sup> I hereby certible been complied complete to the Signature:	with and	that the infor	mation gi	ven above		Approved by:		OIL CONSE	RVATION	DIVISIO	N
Printed name: DENISE PINK	EPTON	~14		CIUI		Title: Petrol	eur	n Engine	er /	-	
Title: REGULATOR	Y SPECIA	ALIST				Approval Date:	0	1/0	7/16		
E-mail Address Leakejd@chevn Date:	ron.com		one:					_			
	2/2015		-687-737	5				2n	-,	2363	Martin Langell

2PP LUSK; MORROW, NORTH (GAS) (80800) 8/20/15 ACTIVATE BAISH; WOLFCAMP, NORTH [4500] 8/20/15

en

	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAG	TERIOR	HOBBS OC EC 30 20	FORM OMB N	APPROVED IO. 1004-0135 ; July 31, 2010
	NOTICES AND REPOR is form for proposals to o ell. Use form 3160-3 (APD		RECEIVED	6. If Indian, Allottee	or Tribe Name
SUBMIT IN TR	IPLICATE - Other instruct	tions on reverse side.		7. If Unit or CA/Agre	eement, Name and/or No
<ol> <li>Type of Well</li> <li>☑ Oil Well</li> <li>☑ Gas Well</li> <li>☑ Ot</li> </ol>	her			8. Well Name and No LANDSDALE D F	
2. Name of Operator CHEVRON U.S.A. INC. √	Contact: [ E-Mail: leakejd@ch	DENISE PINKERTON		9. API Well No. 30-025-26256	N.
3a. Address 15 SMITH ROAD MIDLAND, TX 79705		3b. Phone No. (include area coo Ph: 432-687-7375	le)	10. Field and Pool, or BAISH;WOLFC	Exploratory
4. Location of Well <i>(Footage, Sec., T</i> Sec 4 T19S R32E Mer NMP		/		11. County or Parish, and State LEA COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE	OF ACTION		
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> <li>13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 08/06/2015: MIRU.</li> <li>08/06/2015: MIRU.</li> <li>08/06/2015: TIH W/CIBP &amp; S 08/10/2015: SET CMT RET ( 08/11/2015: TAG TOC @ 44 08/12/2015: TAG CMT @ 44 08/13/2015: TAG CIBP P @ 08/17/2015: TAG TOC @ 12 08/20/2015: SET CIBP @ 10 PERFORATE 10585-10610'.</li> <li>08/25/2015: ACIDIZE W/48 B</li> </ul>	ally or recomplete horizontally, g ork will be performed or provide i d operations. If the operation resi- bandonment Notices shall be file final inspection.) SET @ 4610'.TAG TOP OF @ 4435'. 28;. DRILL OUT CMT RET 40'. DRILL OUT CMT @ 4 4600'. DRILL OUT CMT @ 4	give subsurface locations and mea the Bond No. on file with BLM/B sults in a multiple completion or re ed only after all requirements, incl E CIBP @ 4600. F. EOT @ 4403'. 522'. EOT @ 4553'. TAG TOP OF PKR @ 1250	□ Reclam ⊠ Recomp □ Tempor □ Water D ing date of any prisured and true very PIA. Required sub- completion in a truding reclamation 6'.	olete arily Abandon Disposal roposed work and appro rtical depths of all pertin sequent reports shall be new interval, a Form 316 n, have been completed,	nent markers and zones
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG					
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG	Electronic Submission #3 For CHEV	327024 verified by the BLM W RON U.S.A. INC., sent to the	Hobbs		
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG	Electronic Submission #3 For CHEV	RON U.S.A. INC., sent to the	Vell Information Hobbs		
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG 14. I hereby certify that the foregoing i Name ( <i>Printed/Typed</i> ) DENISE I	Electronic Submission #3 For CHEV PINKERTON Submission)	RON U.S.A. INC., sent to the Title REGL Date 12/22	Hobbs JLATORY SP /2015	ECIALIST	
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG 14. I hereby certify that the foregoing i Name ( <i>Printed/Typed</i> ) DENISE I	Electronic Submission #3 For CHEV PINKERTON Submission)	RON U.S.A. INC., sent to the Title REGL	Hobbs JLATORY SP /2015	ECIALIST	
08/29/2015: WELL IS FLOW 09/14/2015: SET 2 7/8" TBG 14. I hereby certify that the foregoing i Name ( <i>Printed/Typed</i> ) DENISE I	Electronic Submission #3 For CHEV PINKERTON Submission) THIS SPACE FO	RON U.S.A. INC., sent to the Title REGL Date 12/22 DR FEDERAL OR STATI 	Hobbs JLATORY SP /2015	ECIALIST	Date

orl

#### Additional data for EC transaction #327024 that would not fit on the form

#### 32. Additional remarks, continued

09/15/2015: TIH W/PMP & RODS. RIG DOWN.

08/31/2015: ON 24 HR OPT. 185 OIL, 404 GAS, 31 WATER. GOR-2189.

\*\*\*\*attached: SUMMARY REPORTS, TBG SUMMARY, WELLBORE DIAGRAM

\*\*\*\*\*NOTE\*\*\*\*\*The well name has been changed from LANDSDALE D FEDERAL COM #1 to LANDSDALE D FEDERAL #1, dropping the COM due to recompletion in the WOLFCAMP. Also, is now an OIL well.

Chevron	Summa	_	ort OBBS OCD	Major Rig Work Over (MRWO) Casing Repair Job Start Date: 8/6/2015 Job End Date: 9/16/2015
Well Name Lease Lease Landsdale 'D' FEDERAL COM 001	Federal	Field Name Lusk North	DEC 30 2015	Business Unit Mid-Continent
Ground Elevation (ft) Original RKB (ft) Current RKB Elevati 3,666.00 3,682.00 3,682.00, 4/23/				Mud Line Elevation (ft) Water Depth (ft)
Report Start Date: 8/6/2015	2014		RECEIVED	
Report Start Date: 0/0/2015	Co	im .		
CREW TRAVEL TO LOCATION FROM MARK 002H TO CREW LUNCH	LANDSDALE COM FED	#01		
JSA TGSM FOR RIG UP. POA. RIG MOVE CHECKLIS HAZARD WHEEL #6 REVIEWED. PROPER LIFTING/R	IGGING FOR HEAVY EQ			DURES. SWA-SWP-TENET #6 AND
MIRU KEY 307 WORKOVER RIG. SPOT TANKS, PITS, CHECK PRESSURE ON WELL"ZERO" / MONITOR FO				1
SHUT IN WELL / PU TOOLS AND EQUIPMENT, ISOL/ PRIOR TO LEAVING FOR THE DAY.				MED LOCATION WALK AROUND
CONDUCTED DRILLS WITH CREW. H2S, MAN DOWN AND DISCUSSED POA FOR TOMORROW AND THE U	N, EVACUATION, BOP, H IPCOMING DAYS.	IGH ANGLE RE	SCUE, FIRE DRILLS. DI	EBRIEF WITH CREW ON RIG MOVE
CREW TRAVEL HOME.		A		
NO OPERATIONS TAKING PLACE ON LOCATION AT	THIS TIME.	<u> 2 </u>		
Report Start Date: 8/7/2015	Co	m		
NO OPERATIONS TAKING PLACE ON LOCATION AT				
CREW WAS HELD UP AT RIG YARD WAITING WHILE TEXAS SO CREW WAS DISPATCHED TO LOCATION ORIGINAL DERRICK MAN HAD A FAMILY EMERGENC	WHILE RELIEF EMPLOY	EE ARRIVING I	ATER THAT MORNING	
CREW TRAVE TO LOCATION.				
JSA TGSM FOR CHECKING PSI, NDWH-NUBOP, PRE SUSPENDED LOADS, RESTRICTED AREAS AND JOE B FORM POSTED.	SSURED LINES, EXTRE SCOPE FOR THE DAY	ME HEAT ADVI REVIEWED / E	SORY, SWA, SWP, TEN MERGENCY ACTION PI	IET AND HAZARD WHEEL #7, AN SET IN PLACE AND APENDEX
PERFORMED RIG WALK AROUND / SET COFO / CAL	IPER 2 7/8" TBG ELEVAT	ORS / CHECK	ED PRESSURE ON WEL	L "STATIC"
NDWH (SURFACE TREE) / BOLTS WERE HARD TO B	REAK SO THIS JOB PHA	SE TOOK US L	ONGER THEN EXPECT	ED.
**PRODUCTION TREE WAS SENT TO WSI TO GET P	RESSURE TESTED AND	INSPECTED		
FUNCTION TEST CLASS II HYDRAULIC BOP WITH 2			OP OVER WELL AND S	SECURED
PERFORM PRESSURE TEST ON BOP BLINDS SINCE				
RD WORK FLOOR, INSTALL TBG TONGS, PREP TBG				
PU 1- 2 7/8" L-80 6.5# WS TBG WITH 5 1/2" TENSION (PASSED- CHARTED) / RELEASE PACKER AND POOL	PACKER AND SET ~25 E H.	BELOW BOP / F	RESSURE TESTED LO	W 250psi AND HIGH 500 psi
CREW LUNCH				
RIH WITH 4 3/4" RETRIEVING TOOL ON 2 7/8" L-80 W				
INSTALLED 7 1/16" TBG STRIPPER WITH STRIPPER WASH OUT SAND WHILE WORKING TBG DOWN OVE	ER 5 1/2" RBP (TAGGED		ISTALLED TBG SWIVE	AND REVERSE UNIT HOSE TO
DISPLACE PACKER FLUID FROM WELL WITH 8.4# FI LATCHED ON AND APPLIED 500 psi POSITIVE PRES TO ENSURE IT WAS RELEASED / PRESSURE BLED	SURE WHILE RELEASIN			
POOH WITH 5 1/2" RBP ON 2 7/8" WS TBG FROM 4,4			VER NIGHT.	
PU TOOLS AND EQUIPMENT, ISOLATE, SECURE AN				
DEBRIEF WITH ALL ABOUT THE IMPORTANCE OF S ACHIEVING ANOTHER IFO DAY.	TAYING HYDRATED ANI	D COOLING DO	WN. THANKED EVERY	ONE FOR WORKING SAFE AND
CREW TRAVEL HOME.			- Andrew Contraction of the second	
Report Start Date: 8/8/2015	THIS TIME.			
Report Start Date. 0/0/2013	Co	m		
NO OPERATIONS TAKING PLACE ON LOCATION AT	THIS TIME.			
CREW TRAVE TO LOCATION.		Sec. 1		
JSA TGSM FOR CHECKING PSI, TRIPPING PIPE, WIF HAZARD WHEEL #8, SUSPENDED LOADS, RESTRIC	TED AREAS AND JOB SC	OPE FOR THE	DAY	
PERFORMED RIG WALK AROUND / SET COFO / CAL POOH WITH 74 JOINTS OF 2-7/8" WS. L/D RBP	IPER 2 7/8" TBG ELEVAT	ORS / CHECKE	ED PRESSURE ON WEL	L: 30 PSI
PJSM WITH ROTARY WIRELINE. DISCUSSED HAZAR		AND GOOD CO	MMUNICATION	
MIRU ROTARY WIRELINE. SPOT IN TRUCKS, WINCH		Service Andrew		
R/U LUBRICATOR. TEST LUBRICATOR TO 250 LOW/	1000 HIGH: GOOD TEST			

any

Chevron

0

Well Name			
LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent
round Elevation (ft) Original RKB (ft) 3,666.00 3,682.00	Current RKB Elevation 3,682.00, 4/23/2014		Mud Line Elevation (ft) Water Depth (ft)
		Com	
RIH WITH 4.3" GAUGE RING TO 4700'. 3HA: 4.3" GAUGE RING 1) 5', 3-1/2" BASKET 1) 1-1/2', 3-1/8" CCL 1) 1', 1-7/16" ROPE SOCKET	РООН	Com	
REMOVE LUBRICATOR, INSTALL 4.24 NSTALL LUBRICATOR AND TEST: 250			
	PLUG AND SET @ 4610' (WIR	ELINE DEPTH). PULLED OFF AND	WENT BACK DOWN TO VERIFY PLUG WAS
R/D LUBRICATOR AND ROTARY WIRE	ELINE.	AND STREET	
2/U 5-1/2" PACKER AND RIH ON 141 J HOLE WAS FULL SO WERE DISPLAC TAGGED TOP CBP @ 4600'. L/D 1 JOII	ING WATER FROM WELL INT		
R/U LINES TO TEST. TEST CBP TO 20	00 PSI FOR 15 MIN-GOOD TES	ST.	
RELEASE PACKER AND L/D 4 JOINTS		2 6 SOZ 0	
SET PACKER @ 4439'. TEST PACKER	TO 500 DOL ON PACKODE EC	B B LULL G G G B B B G B	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU	S 700 PSI 0 TO 1500 PSI.	R 5 MIN-GOOD TEST.	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI	FORE BLEEDING OFF	Y WHAT SECTION IT WAS FROM. BLED OFF
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRE NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JO	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED.	Y WHAT SECTION IT WAS FROM. BLED OFF
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291'	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED. LE AS A KLL STRING.	Y WHAT SECTION IT WAS FROM. BLED OFF
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO	S 700 PSI D TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT.	Y WHAT SECTION IT WAS FROM. BLED OFF
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME.	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT.	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT.	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME.	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT.	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC COT: 2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 CREW DAY OFF. NO OPERATIONS AT	S 700 PSI D TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC COT: 2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 CREW DAY OFF. NO OPERATIONS AT	S 700 PSI D TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA Com	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC EOT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 CREW DAY OFF. NO OPERATIONS AT Report Start Date: 8/10/2015	S 700 PSI D TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF NING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEL DRTANCE OF STAYING HYDR. LOCATION AT THIS TIME.	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA	
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC COT: 2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 CREW DAY OFF. NO OPERATIONS AT Report Start Date: 8/10/2015 NO OPERATIONS TAKING PLACE ON CREW TRAVE TO LOCATION. ISA TGSM FOR CHECKING PSI, TRIP WHEEL #10, SUSPENDED LOADS, RE	S 700 PSI TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR. LOCATION AT THIS TIME. TWELLSITE LOCATION AT THIS TIME. PING PIPE, PRESSURE TEST STRICTED AREAS AND JOB S	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA Com Com	NKED EVERYONE FOR WORKING SAFE AND
GIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS FTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU OTAL BBLS PUMPED=20 FTER SHUTTING DOWN PUMPS PRE IOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED REW LUNCH RELEASE PACKER. POOH WITH 70 JC COT:2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. REW TRAVEL HOME. IO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 REW DAY OFF. NO OPERATIONS AT Report Start Date: 8/10/2015 IO OPERATIONS TAKING PLACE ON REW TRAVE TO LOCATION. SA TGSM FOR CHECKING PSI, TRIP VHEEL #10, SUSPENDED LOADS, RE PERFORMED RIG WALK AROUND / S	S 700 PSI D TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR LOCATION AT THIS TIME. TWELLSITE LOCATION AT THIS TIME. PING PIPE, PRESSURE TEST STRICTED AREAS AND JOB S ET COFO / CALIPER 2 7/8" TB	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PPED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA Com Com	NKED EVERYONE FOR WORKING SAFE AND
BEGIN INJECTION TEST: PUMPED @ 2.5 BPM, PRESSURE WAS AFTER 10 BBLS PRESSURE CLIMBED PUMPED @ 1.75 BPM @ 1500 PSI. PU TOTAL BBLS PUMPED=20 AFTER SHUTTING DOWN PUMPS PRI NOTE: OBSERVED SMALL LEAK COM CASING AND STILL HAD LEAK, BLED CREW LUNCH RELEASE PACKER. POOH WITH 70 JC COT: 2291' PU TOOLS AND EQUIPMENT, ISOLAT DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY. CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON Report Start Date: 8/9/2015 CREW DAY OFF. NO OPERATIONS AT Report Start Date: 8/10/2015 NO OPERATIONS TAKING PLACE ON CREW TRAVE TO LOCATION. SA TGSM FOR CHECKING PSI, TRIP	S 700 PSI 0 TO 1500 PSI. MPED 10 BBLS. ESSURE HELD AT 800 PSI BEF IING FROM ONE OF THE CASI OFF TUBING AND LEAK STOP DINTS. LEFT 70 JOINTS IN HO E, SECURE AND SHUT IN WEI DRTANCE OF STAYING HYDR LOCATION AT THIS TIME. TWELLSITE LOCATION AT THIS TIME. FING PIPE, PRESSURE TEST STRICTED AREAS AND JOB S ET COFO / CALIPER 2 7/8" TBI L/D 5-1/2" PACKER 136 JOINTS OF 2-7/8" L-80 WS	FORE BLEEDING OFF ING VALVES, COULD NOT VERIFY PED. LE AS A KLL STRING. LL FOR THE NIGHT. ATED AND COOLING DOWN. THA Com Com Com Com Com Com Com Com	NKED EVERYONE FOR WORKING SAFE AND

.

Chevron

2

Major Rig Work Over (MRWO) Casing Repair Job Start Date: 8/6/2015 Job End Date: 9/16/2015

			Job End Date: 9/16/2015
Well Name LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation	Luok Holdi	Mud Line Elevation (ft) Water Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014		
PRESSURE TEST LINES TO 3500 PSI. PRESSURED UP BACKSIDE TO 500 P PUMPED 11 BBLS TO GET RATE OF 1 DISPLACE: PUMPED 15 BBLS AND S/ PUMPED 3 BBLS, S/D FOR 20 MIN @ 9 PUMPED 3 BBLS, S/D FOR 15 MIN @ 99 PUMPED 1 BBL, S/D FOR 15 MIN @ 99 PUMPED 1 BBL, S/D FOR 15 MIN @ 10 REVERSE OUT 50 BBLS OF FRESH W	SI .8 @1340 PSI. PUMPED 200 S D FOR 15 MIN @ 837 PSI, CLE 819 PSI 901 PSI 958 PSI 958 PSI 54 PSI 54 PSI	SACKS (47.4 BBLS) OF 14.8 PPC AN LINES.	
R/D HALLIBURTON LINES, EQUIPMEN			
POOH WITH 136 JOINTS OF 2-7/8" L-8			
DEBRIEF WITH ALL ABOUT THE IMPO ACHIEVING ANOTHER IFO DAY.	ORTANCE OF STAYING HYDR	RATED AND COOLING DOWN. 1	THANKED EVERYONE FOR WORKING SAFE AND
CREW TRAVEL HOME.		and the	
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		
Report Start Date: 8/11/2015		Com	
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		
CREW TRAVE TO LOCATION. JSA TGSM FOR CHECKING PSI, TRIP SWA, SWP, TENET AND HAZARD WH			WIVEL, EXTREME HEAT ADVISORY, HIGH WINDS,
PERFORMED RIG WALK AROUND / SI	ET COFO / CALIPER 2 7/8" TB	G ELEVATORS / CHECKED PR	ESSURE ON WELL: 0
P/U BHA AND RIH: (1) .34', 4-3/4" MILL TOOTH BIT (1) 1.99', 3-3/4" BIT SUB XO (6) 182.14' 3-1/2" DCs (1) .90', 3-5/8" XO TOTAL BHA LENGTH: 185.36'			
RIH WITH 130 JOINTS OF 2-7/8" L-80 V		and the second second	
R/U POWER SWIVEL, CONNECT ALL			
			TABLISH CIRCULATION AND DRILL OUT CEMENT ARD CEMENT BACK IN RETURNS. DRILLED OUT 5
BPM- 2-3 WOB- 4-8K			
(ADJUSTED PARAMETERS TO SEE IF	WE COULD GET A BETTER F	ROP. GOT BETTER ROP WITH	MORE WEIGHT AND SLOWER RPMs.)
P/U OFF BOTTOM AND CIRCULATE H			
DEBRIEF WITH CREW. THANKED EVE CREW TRAVEL HOME.	RYONE FOR WORKING SAFI	E, AND ACHIEVING ANOTHER I	FO DAY.
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		
Report Start Date: 8/12/2015		No. NO. CONTRACTOR	
NO OPERATIONS TAKING PLACE ON		Com	
CREW TRAVE TO LOCATION.	LOCATION AT THIS TIME.	the second s	
		POWER SWIVEL, EXTREME HE	EAT ADVISORY, HIGH WINDS, SWA, SWP, TENET
PERFORMED RIG WALK AROUND / SI			
ESTABLISH CIRCULATION. TAG CEMI 4553' (CEMENT WAS GREEN/SOFT WHEN I		TO DRILL OUT CEMENT. FELL	OUT OF CEMENT @ 4522'. P/U 1 JOINT RIH. EOT-
CIRCULATED 1 BOTTOMS UP. ~95 BB			
PERFORMED CASING TEST (WELL W		CK SLIGHTLY).	
PUMPED AT .5 BPM NO CHANGE IN F	PRESSURE AFTER 2 BBLS. IN	ICREASE PUMP RATE TO 1.5 B	PM, AFTER 4 BBLS PUMPED PRESSURE STARTED 5 BBLS. (SHUT IN DURING THIS TIME AND HAD
RETRY CASING TEST: PUMPED TOTA	L 5 BBLS @ 1.5 BPM AND PR	ESSURE WAS 350-400 PSI	

Page 3/15

Chevron

				d Date: 9/16/2
Vell Name ANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	· · · · · · · · · · · · · · · · · · ·
round Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft)	Water Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014			
		Com		
R/D POWER SWIVEL, LINES AND EQU				
VU LINES AND CIRCULATE AND COI VELL WAS STATIC.	NDITION HOLE. PUMPED TOT	AL OF 95 BBLS OF FW @ 3.5 BP	M. S/D AND FLOWED BACK 5-6 E	BLS BEFORE
CASING TEST: STARTED PUMPING @ .5 BPM, PUMP NCREASED TO 1.0 BPM, PUMPED 3 B PRESSURE=300 PSI, AFTER 1 BBL PR PUMPED TOTAL OF 10 BBLS SD/SI. PRESSURE HELD @ 450 PSI FC	BBLS PRESSURE=200 PSI, ST RESSURE-500 PSI.	AYED AT 1 BPM, PUMPED 2 BBL	S PRESSURE=250 PSI, AFTER 2	BBLS
PEFORMED INJECTION TEST. SLOWL NT 1 BPM, PUMPED 5 BBLS PRESSUR NT 1.5 BPM, PUMPED 5 BBLS- PRESS NT 1.5 BPM, PUMPED 5 BBLS AND PR PUMPED TOTAL OF 15 BBLS	RE-300 PSI URE-400 PSI	S/D AND SI WELL. PRESSURE HI	ELD AT 1000 FOR 5 MIN.	•
POOH WITH 60 JOINTS OF WS. LEFT	BIT AT ~2600'			
DEBRIEF WITH CREW. DISCUSSED P	OA FOR TOMORROW.			
CREW TRAVEL HOME.				
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.	and the second second		
Report Start Date: 8/13/2015				
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME	Com		
CREW TRAVE TO LOCATION.	LOCATION AT THIS TIME.		the second s	
ISA TGSM FOR TRIPPING PIPE, DRILI SCOPE FOR THE DAY	LING, POWER SWIVEL, EXTR	EME HEAT ADVISORY, SWA, SW	/P, TENET AND HAZARD WHEEL	#3, AND JOB
PERFORMED RIG WALK AROUND / SE	ET COFO / CALIPER 2 7/8" TB	G ELEVATORS / CHECKED PRES	SURE ON WELL: 0	1 10 10 10
RIH WITH 61 JOINTS OF WS TO 4553'.				
VU POWER SWIVEL, INSTALL STRIP	PER HEAD, RAISE RIG FLOOF	, CONNECT LINES AND EQUIPM	ENT	N. P. L.
P/U 1 JOINT AND TAG CBP @4600'. E	STABLISH CIRCULATION AND	DRILL OUT CBP. AFTER CBP DI	RILLED OUT, P/U 1 JOINT AND RI	IH AND VERIFIE
CIRCULATE HOLE CLEAN.				Sector (SIS)
R/D POWER SWIVEL. DISCONNECT L	INES/HOSES. REMOVE STRIP	PER HEAD, LOWER RIG FLOOR		and property
P/U 133 JOINTS OF 2-7/8" TUBING AND	) RIH TO ~8825'.			A
CREW LUNCH		a second the second second		
TALLY AND P/U 2-7/8" L-80 TUBING A		CKER @ 12506' WITH JOINT 381.	L/D 1 JOINT	
R/U LINES AND CIRCULATE 275 BBLS				
DEBRIEF WITH CREW. DISCUSSED PO	DA FOR TOMORROW.			
CREW TRAVEL HOME.		1		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			19. 19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Report Start Date: 8/14/2015		Com		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.	Com		
CREW TRAVE TO LOCATION.				
ISA TGSM FOR TRIPPING PIPE, WOR FOR THE DAY	KING AT HEIGHTS, EXTREME	HEAT ADVISORY, SWA, SWP, T	ENET AND HAZARD WHEEL #4, A	AND JOB SCOPE
PERFORMED RIG WALK AROUND / SE		3 ELEVATORS / CHECKED PRES	SURE ON WELL: 0	
POOH WITH 380 JOINTS OF 2-7/8" WS				No. Constant
/D XO, (6) 3-1/2" DCs, BIT SUB, AND 4	-3/4" MILL TOOTH BIT. (~185' (	OF BHA)	10.114.03	
REW LUNCH				
U PERFORATED SUB, AND RIH WIT			01= 12496'	
IIRU HALLIBURTON CEMENTERS. SF			MUNICATION DESCOURS	A Destroy
PJSM WITH HALLIBURTON, KEY, SLB			IMUNICATION, PRESSURE.	100 - 100 - 100 E
FILL LINES, AND PRESSURE TEST LIN PUMP 20 BBL SPACER @ 2.5 BPM, @ PUMP 10.5 BBLS (55 SACKS) OF 16.4 I PUMP 20 BBL SPACER @ 3 BPM @ 19	480 PSI PPG CEMENT @ 1.9 BPM. SHU	JT DOWN AND CLEAN LINES.		
			OM COMING UP ANNULUS	
MONITORED BACKSIDE WHILE PUMP	ING AND ADJUSTED PRESSU	THE TO HELF KEEF GEWENT FR		

Chevron

				Date: 9/16/2015
Well Name LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft)	Water Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014			
		Com		
R/U LINES TO REVERSE CIRCULATE.	CIRCULATED A TOTAL OF 115 BBLS	@ 4 BPM @ 440 PSI		
(DID SEE SOME CEMENT IN RETURN	S AFTER 65 BBLS WAS PUMPED SO	CONTINUED TO PUMPED UNTIL RETUI	RNS WERE CLEAN	
RDMO HALLIBURTON CEMENTERS.			THE WERE OLEAN,	
	M FOR STAYING OUT AND WORKING	G LATE. DISCUSSED POA FOR MONDA	Y	
CREW TRAVEL HOME.				1.1
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			
Report Start Date: 8/15/2015		LT INR	C. C. States	
		Com		
CREW SCHEDULED DAY OFF, NO OPI	ERATIONS AT WELLSITE			
Report Start Date: 8/16/2015			and the second second	
CREW SCHEDULED DAY OFF, NO OPI		Com		
Report Start Date: 8/17/2015		the state of the s	State 1 - State	
and the second		Com		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		1. 1. 1. 1.	
CREW TRAVE TO LOCATION.	in the second		1. 1. 1. 1. 1.	
JSA TGSM FOR TRIPPING PIPE, WOR DAY	KING AT HEIGHTS, PRESSURE TEST	, SWA, SWP, TENET AND HAZARD WH	EEL #7, AND JOB S	COPE FOR THE
the second se	ET COEO / CALIPER 2 7/8" TBG ELEV	ATORS / CHECKED PRESSURE ON WE		
		ATOKS / CHECKED FRESSURE ON WE	LL. SLIGHT FRESS	ORE ON CASING
TIH AND TAG TOP OF CEMENT @ 12,	137' (WHICH GAVE US 369' OF CEME	NT ON TOP OF PACKER, BLM WAS OU	T HERE TO WITNES	SS TAGGING)
POOH AND L/D 61 JOINTS OF TUBING	i.			
POOH AND STAND BACK 314 JOINTS				
P/U 5-1/2" PACKER AND RIH WITH 150	JOINTS OF 2-7/8" TUBING.			
CREW LUNCH				in the second
CONTINUE TO RIH WITH 172 JOINTS				A State State State
R/U LINES AND PERFORMED CHARTE BLED OFF PRESSURE.	ED CASING TEST. FILLED UP BACKSI	DE , PRESSURED UP TO 2700 PSI AND	HELD FOR 30 MIN	- GOOD TEST.
	D 28 JOINTS OF WORK STRING LEA	VING 294 JOINTS IN THE HOLE, EOT	0261' SWEN	Contraction of the second
DEBRIEF WITH CREW. DISCUSSED P		WING 234 JOINTS IN THE HOLE, LOT-	5201. SWIN	the second s
CREW TRAVEL HOME.				
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			
Report Start Date: 8/18/2015				1000
		Com		
No ops @ well			8-16-18-18-18-18-18-18-18-18-18-18-18-18-18-	
Crew Travel				
Safety Meeting				
TOH laying down 2 7/8" L-80 WS				
Change pipe rams, tong and slip dies, ma Lunch	ove out 2 7/8" tubing, Set in 329 jts 3 1/2	2 L-80 tubing & tally.		
Wait on Haliburton Wireline due to scope	change(Didn't know we needed a gam	ma ray to correlate to unit!! today)		
RU HAL WL unit	change(Didn't know we needed a gami	ha ray to correlate to unitil today)		
				Section 18 generation
SI & Secure well, SDFN				a farmer a
Crew Travel				
No ops @ well				
Report Start Date: 8/19/2015		-	1	
NO OPERATIONS TAKING PLACE ON		Com		
CREW TRAVEL FROM RIG YARD TO L		and the second design of the second		
JSA TGSM FOR RU-RD HALLIBURTON	/ EXPLOSIVES ON LOCATION / RES	TRICTED AREAS / SUSPENDED LOADS / JOB SCOPE DISCUSSED AND REVIEW		
PERFORMED WALK AROUND LOCATI CHECK PRESSURE ON WELL "ZERO"	ON BEFORE INITIATING WORK / FUN	ICTION TESTED BOP MANIFOLD / CALI	PER 3 1/2" TBG ELE	EVATORS /
SPOTTED IN HALLIBURTON EQUIPMI CLEARANCE ON LUBRICATOR.	ENT / RU WIRELINE EQUIPMENT OVE	ER WELL, HOISTED LINE & SHEAVE TH	ROUGH TRAVEL BI	LOCKS FOR
have seen a second and the second sec			the second s	

3.685.00       3.682.00, 4/23/2014         Com         Com <t< th=""><th>evron</th><th>Sum</th><th>mary Report</th><th>Major Rig Work Over (MRWO Casing Repai Job Start Date: 8/6/201 Job End Date: 9/16/201</th></t<>	evron	Sum	mary Report	Major Rig Work Over (MRWO Casing Repai Job Start Date: 8/6/201 Job End Date: 9/16/201
Grand Evention (ft)         Commentation (ft)         Multiple Evention (ft)         Multiple Evention (ft)         Multiple Evention (ft)         Multiple Evention (ft)           RIF FROM SURFACE TO 11 000° TVD WITH 4.65° X 5.10° JUNK BASKET-GAGE RING / 3.376° X 6.95° GAMMA ON 9/32° E-LINE CABLE / NO         Commentation (ft)	the second se			
Com       Com         RIH FROM SURFACE TO 11.000 TVD WITH 4.65" x 5.10" JUNK BASKET-GAGE RING / 3.375" x 6.95" GAMMA ON 9/32" E-LINE CABLE 7/NO         RESTRICTIONS OR DRAG IDENTIFIED.       Com         POOL FROM TUDW RINGE AND ATTEMPTING TO MAKE UP THE 5 10" CIBP MALLIBURTON SUPERVISOR NOTICED HE HAD THE         APER POOL WITH JUWK BASKET AND ATTEMPTING TO MAKE UP THE 5 10" CIBP MALLIBURTON SUPERVISOR NOTICED HE HAD TH         APER POOL WITH JUWK BASKET AND ATTEMPTING TO MAKE UP THE 5 10" CIBP MALLIBURTON SUPERVISOR NOTICED HE HAD TH         AND HALLIBURTON BROUGHT OUT 1 10", WANTED FOR CORRECT EQUIPMENT TO ARRIVE.         Wrong Crossover was brought the first time. Wreline operator had to meet holshot in Eurice with right connection. Got parts to location and still d right one.         SI & Secure well, SDFN         Crew Travel         Sorge @ well         Crew Travel         Safety Meeting         RU Wreline & make up setting tool to CIBP         Test Lubricator 2007000 Good, RH w/ GIBP, Sorelate w/ Gamma, set plug @ 10925 due to casing colar @ 10932. FU & Tag CIBP(Good), POC setting tool.         Dump bail 4 set orhin 12 runs from 10925-10880.         Test Lubricator 2007000 Good, RH w/ GIBP, Sorelate w Gamma, set plug @ 10935 due to casing colar @ 10932. FU & Tag CIBP(Good), POC setting tool.         PUP bask 5 K Tension fV# 2 KH w 1 JI. Test 3 1/2 pipe rams to 350/1050(Good), Release pir & LD         RU Hydrostatic tester         Si & Secure well, SDFN      <	und Elevation (ft) Original RKB (ft) Cu	rrent RKB Elevation		
RIH FROM SURFACE TO 11.000 TVD WITH 4.63" x 5.10" JUNK BASKET-GAGE RINK / 3.375" x 6.95" GAMMA ON 9/32" E-LINE CABLE / NO RESTRICTIONS ON DPAGA IDENTIFIED. POOH FROM 11.000 TO SURFACE WITH 5.40% IDENTIFIED. POOH FROM 11.000 TO SURFACE WITH 5.40% IDENTIFIED. PACHER POOH WITH JUNK BASKET AND ATTEMPTING TO MAKE UP THE 5.12% CIBP FALLIBURTON SUPERVISOR NOTICED HE HAD TH ADAPTOR (THIS ADAPTOR CONNECTS THE 5.12% CIBP TO THE C.CL IN ORDER TO BE RAN IN THE HOLE / CIBP CALLS FOR 2" REGUL ADAPALLER FOOK WITH JUNK BASKET AND ATTEMPTING TO MAKE UP THE 5.12% CIBP ADARNUE. With JUNK BASKET AND ATTEMPTING TO MAKE UP THE 5.12% CIBP AT ON PARIVE. With JUNK BASKET AND ATTEMPTING TO MAKE UP THE 5.12% CIBP ALLIBURTON SUPERVISOR NOTICED HE HAD TH ADAPTOR ON BOUGHT OUT 11% / VIAITED FOR CORRECT CEUDIMENT TO ARRIVE. With JUNK BASKET AND ATTEMPTING TO MAKE UP THE 5.12% CIBP ALLIBURTON SUPERVISOR NOTICED HE HAD TH ADAPTOR SURFACE TO 11% / VIAITE FOR CORRECT CEUDIMENT TO ARRIVE. With JUNK BASKET JUNK SUPERVISOR AND ADDAPTING TO AND ADDAPTING AND ADDAPTING AND ADDAPTING SI & Secure well. Secure VIAI No ops @ well Crew Travel Safery Meeting RI WI 3001000 GOOD, RIBE ADDAPTING ADDAPTING ADDAPTING ADDAPTING ADDAPTING RIB WI 3001000 GOOD, RIBE ADDAPTING ADDAPTING ADDAPTING ADDAPTING RIB WI 3001000 GOOD, RIBE ADDAPTING ADDAPTING ADDAPTING ADDAPTING RIB WI 300 SINK gun VI SPF & 50 deg phasing. Correlate & perforate @ 10585-106(0. Well stayed static, but showed good indication that gun POOH ALLD Guns. RIB WI 30 SINK gun VI SPF & 50 deg phasing. Correlate & perforate @ 10585-106(0. Well stayed static, but showed good indication that gun POOH ALLD Guns. RIB WI 30 SINK gun VI SPF & 50 deg phasing. Correlate & perforate @ 10585-106(0. Well stayed static, but showed good indication that gun RIB WI 30 SINK gun VI JUNK SHOWED VIEL SECOND SUBJECT S	3,666.00 3,682.00 3,	382.00, 4/23/2014		
Crew Travel No ops @ well Report Start Date: 8/20/2015 Com No ops @ well Crew Travel Start Date: 8/20/2015 Com No ops @ well Crew Travel Start Date: 8/20/2015 Com No ops @ well Crew Travel Start Date: 8/20/2015 Com No ops @ well Crew Travel Start Date: 8/20/2015 Com Crew Travel Start Date: 8/21/2015 Com Crew Travel C	STRICTIONS OR DRAG IDENTIFIED. DOH FROM 11,000' TO SURFACE WITH TER POOH WITH JUNK BASKET AND DAPTOR / THIS ADAPTOR CONNECTS ID HALLIBURTON BROUGHT OUT 1 1/2 rong Crossover was brought the first time ht one.	SAME E-LINE BHA / NO RE ATTEMPTING TO MAKE UP THE 5 1/2" CIBP TO THE C( 2" / WAITED FOR CORRECT	ET-GAGE RING / 3.375" x 6.95' GAMMA STRICTIONS NO DRAG. THE 5 1/2" CIBP HALLIBURTON SUPE CL IN ORDER TO BE RAN IN THE HOLE EQUIPMENT TO ARRIVE.	RVISOR NOTICED HE HAD THE WRONG E / CIBP CALLS FOR 2" REGULAR THREADS
No ops @ well Report Start Date: 8/20/2015 Com No ops @ well Com	& Secure well, SDFN			
Report Start Date: #2012015       Com         No ops @ well       Com         Crew Travel       Safely Meeting         RU Wireline & make up setting tool to CIBP       Test Lubricator 200/1000 Good, RiH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool.         Dump bail 4 sex cmt in 2 runs from 10925-10890       Test and PU Guns         RIH w/ 3 38 Slick gun w/ SPF & 50 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur         POOH & LD Guns, All 100 shots fired.       Joint SS 5-10.0, Joint O         RD Hallburton Wireline       PUPeak 54 Tension pkr & RIH w/ 1], Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD         RU Hydrostatic Testers       Start TiH w/ ASLX Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast Jt, on 3 1/2 L-80 WS hydrotesting 8000 psl.         RD Hydrostatic Testers       Start TiH w/ ASLX Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast Jt, on 3 1/2 L-80 WS hydrotesting 8000 psl.         RD Hydrostatic Testers       Start TiH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psl.         RD ops @ well       Com         Crew Travel       Seeure well, SDFN         Crew Travel       Safety Meeting         Safety Meeting       Com         Safety Meeting       Com         Cont TIH hydrotesting to 8000 psl. Crame back down and ran 1 more jt	ew Travel			
Com         Open @ well         Crew Travel         Safety Meeting         RU Wrieline & make up setting tool to CIBP         Test Lubricator 300/1000 Good, RIH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool.         Damp Bail 4 as critin 12 runs from 10925-10880.         Test and PU Guns         POOH & LD Guns, All 100 shots fired.         RIH wi 3 30 & Slick gun wi 4 SPF & 50 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static. but showed good indication that gur         POOH & LD Guns, All 100 shots fired.         RU Hydrostatic Testers         Start TIH w/ X51-X Peak 10K Frac packer wi 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast Jt. on 3 1/2 L-80 WS hydrotesting 8000 psi.         RD Hydrostatic tester         SI & Secure well, SDFN         Crew Travel         No ops @ well         Cont TIH w/ 33 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi. Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt         Crewal Tavel         Safety Meeting         Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi. Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt         Cricutate 60 bib Sclean FV/@ 21 B MP @ 2000 Pri serveres. Saw no trash in retruns	ops @ well		State Charles and a second second	
No ops @ well         Crew Travel         Safety Meeting         RU Wrellne & make up setting tool to CIBP         Test Lubricator 300/100 Good, RIH w/ CIBP, correlate w/ Gamma, set plug @ 10825 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool.         Dump bail 4 sex cont in 2 runs from 10925-10890.         Test and PU Guns         RIH w/ 3 3/8 Slick gun w/ 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10810. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired.         RD Hallburton Wireline         PU Peak 5 k Tension pkr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD         RU Hydrostatic Testers         Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8*X 2.441* Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psl.         RD Hydrostatic tester         Si & Secure well, SDFN         Crew Travel         Safety Meeting         Cont TIH w/ 33 1/2 L-80 WS hydrotesting to 8000 psl, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 morg it         Crew Travel         Safety Meeting         Cont TIH w/ 33 tore jts 3 1/2 L-80 WS hydrotesting to 8000 psl, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 morg it         Crever Travel	port Start Date: 8/20/2015			
Crew Travel Safety Meeting RU Wreline & make up setting tool to CIBP Test Lubricator 300/1000 Good, RIH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool. Dump bail 4 sixs criter in 2 runs from 10925-10890. Test and PU Guns RIH wi 3 308 (kick gun wi 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static. but showed good indication that gur POOH & LD Guns, All 100 shots fired. RD Halliburton Wireline PU Peak 5 K Tension ptr & RIH wi 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Start TiH wi A 51-X Peak 10K Frac packer wi 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt. on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel Safety Meeting Com No aps @ well Com No aps @ well Com RD Good psi. 7 and Fugged again after 2 jts. Decision made to TOH & look @ packer RD Hydrostesting to Silvers of metal that were stuck in the packer. Silvers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the manded seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bits Clean FVW @ 3.75 EPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH will 31/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bits Clean FVW @ 3.75 EPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH will 31/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bits Clean FVW @ 3.75 EPK M@ 500 psi conventional and got back a few more of the same metal slivers. SI & Secure well, SDFN Circw Travel SI & Secure well so slivers of metal that were stuck in the packer. Slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal			Com	
Safety Meeting RU Wreline & make up setting tool to CIBP Test Lubricator 300/1000 Good, RiH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool. Test and PU Guns RIH w/ 3 3/8 Slick gun v/ 4 SPF & 60 deg phasing. Correlate & perforate @ 10585-106(0. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired. RD Haliburton Wireline PU Peak 5 transion pkr & RiH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Star TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel Safety Meeting Com No ops@ well Crew Travel Safety Meeting Com No ops@ well Crew Travel RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. Com Sub ray of the marker sub in the packer. silvers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area onings and in the jsalot. Unrole TIH wy AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting to 8000 psi. Test Targel Safety Meeting Com No ops@ well Crew Travel RD Hydrotesting to 8000 psi. Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Criculate 60 biol cean F W@ 2 Pier Yee 20 psi reverse. Saw to trash in refurms. Com TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RD Hydrotester RD Hydrotester SI & Secure well,				
RU Wireline & make up setting tool to CIBP Test Lubricator 300/1000 Good, RIH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool. Test and PU Guns RIH w/ 3 3/8 Slick gun w/ 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired. RD Halliburton Wireline PU Peak 5 k Tension pkr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Start TiH w/ 3.871. X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psl. RD Hydrostatic tester S & Secure well, SDFN Crew Travel No ops @ well Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TiH w/ 38 more jits 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten traging the third films and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TiH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer, slivers were 1/8" wide and 1.5" long and almost identical. There were more sluck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended W 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 56 lost Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ 351.X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. Sl & Secure well, SDFN Crew Travel No ops@ well Crew Travel No Ops@ Wel			and the state of the second	
Test Lubricator 300/1000 Good, RIH w/ CIBP, correlate w/ Gamma, set plug @ 10925 due to casing collar @ 10932. PU & Tag CIBP(Good), POC setting tool.         Dump bail 4 sex cmt in 2 runs from 10925-10890.         Test and PU Guns         RIH w/ 3 3/8 Slick gun w/ 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired.         POH & LD Guns, All 100 shots fired.         PU Peak 6 K rension pkr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD         RU Hydrostatic Testers         Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psl.         RD Hydrostatic tester         Si & Secure well, SDFN         Crew Travel         Safet Meeting         Cont TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Krac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psl.         RD bydrostatic tester         Si & Secure well, SDFN         Crew Travel         Safety Meeting         Cont TIH w/ aster is 3 1/2 L-80 WS hydrotesting to 8000 psl, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt         Circulate 60 bbls clean FW@ 2 E PM@ 200 psi reverse. Saw no trash in retruns.         Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer </td <td>, ,</td> <th></th> <td>and the second second</td> <td></td>	, ,		and the second	
Dump bail 4 sxs cmt in 2 runs from 10925-10890.         Test and PU Guns         RIH w/ 3 3/8 Slick gun w/ 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur         POOH & LD Guns, All 100 shots fired.         PUT and ST Fransion pkr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD         RU Hydrostatic Testers         Star TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi.         RO Hydrostatic tester         SI & Secure well, SDFN         Crew Travel         No ops @ well         Cerw Travel         Safety Meeting         Corn TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi. Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt         Circuitate 60 bbis clean FV@ 2 BPM @ 200 psi reverse. Saw no trash in retruns.         Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer         RD Hydrotester         RU denimino & TOH w/ 92 jts 3 1/2 UX9 & frac packer. We only dragged 1 time on the way out.         We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more sluck along the mandre lease area orings and in the j-slot.         Lunch       TIH hydrotestic	st Lubricator 300/1000 Good, RIH w/ CIE		plug @ 10925 due to casing collar @ 109	32. PU & Tag CIBP(Good), POOH & LD
Test and PU Guns RIH wi 3 3/8 Slick gun wi 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired. Wy JD, SS, S-JD, GUD RD Halliburton Wireline PU Peak 5 K Tension pkr & RIH wi 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Start TIH wi AS1-X Peak 10K Frac packer wi 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH wi 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 65 blo clean FW @ 2 PEM @ 200 pai reverse. Saw no trash in refuns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH wi 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 alivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended wi 3 1/2 collar on bottom wi 92 jts and did not tag anything Circulate 65 blos Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH wi 3 1/2 & collar win no drag Start TIH wi AS1-X Peak 10K Frac packer wi 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. Start Star		0890		and the second second
RIH w/ 3 3/8 Slick gun w/ 4 SPF & 90 deg phasing. Correlate & perforate @ 10585-10610. Well stayed static, but showed good indication that gur POOH & LD Guns, All 100 shots fired. RD Halliburton Wireline PU Peak 5 k Tension pkr & RIH w/ 1 jt. Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Slitan TIH w/ A S1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester Sl & Secure well, SDFN Crew Travel No ops @ well Crew Travel Safety Meeting Com No ops @ well Crew Travel Safety Meeting Com TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 silvers of metal that were stuck in the packer. silvers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-sit. Lunch TIH open ended w/ 3		0000.		
POOH & LD Guns, All 100 shots fired. RD Halliburton Wireline RD Peak 5 K Tension ptr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well <b>Report Start Date:</b> 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Attent tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbis clean FVW @ 2 EPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerlinno & TOH w/ 92 jts 3 1/2 LVS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 silvers of metal that were stuck in the packer. silvers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended wi 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbis Clean FVW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal silvers. TOH w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbis Clean FVW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal silvers. TOH w/ 3 1/2 collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well		phasing, Correlate & perforate	@ 10585-10610, Well staved static, but	showed good indication that guns went off.
PU Peak 5 k Tension pkr & RIH w/ 1 jt, Test 3 1/2 pipe rams to 350/1050(Good), Release pkr & LD RU Hydrostatic Testers Start TiH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well <b>Report Start Date:</b> 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TiH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TiH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 silvers of metal that were stuck in the packer. silvers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TiH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ A51-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN			Perf 10,58	15-10,610
RU Hydrostatic Testers Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well Crew Travel Safety Meeting Com No ops @ well Crew Travel Safety Meeting Com TNH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Com TIH w/ AS1 X Pack 10 S frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 silvers of metal that were stuck in the packer. silvers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	Halliburton Wireline	and the second se	Second Salar	and the second
Start TiH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS hydrotesting 8000 psi. RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well <b>Report Start Date:</b> 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TiH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Attent tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TiH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gernimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TiH open ended wi 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TiH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. Si & Secure well, SDFN Crew Travel No ops @ well	J Peak 5 k Tension pkr & RIH w/ 1 jt, Tes	t 3 1/2 pipe rams to 350/1050	(Good), Release pkr & LD	
RD Hydrostatic tester SI & Secure well, SDFN Crew Travel No ops @ well Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH wi 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Attent tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gernimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w' 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
SI & Secure well, SDFN Crew Travel No ops @ well Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more its 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well		w/ 2.25 F Frac hardened SN,	3 1/8"X 2.441" Blast jt, on 3 1/2 L-80 WS	hydrotesting 8000 psi.
Crew Travel No ops @ well Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FV @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
No ops @ well  Report Start Date: 8/21/2015 Com No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well			State of the second	
Com         No ops @ well         Com         Com         No ops @ well         Com         Com         No ops @ well         Com         Com         Safety Meeting         Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Attent tagging the third time and pulled 20 over. Came back down and ran 1 more jt         Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns.         Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer         RD Hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer         RD Hydrotesting         RD Hydrotester         RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out.         We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot.         Lunch         TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything         Circulate 65 bbls Clean FW @ 3.75 BPM			and the second s	and the second
Com No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
No ops @ well Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	port Start Date: 8/21/2015		Com	
Crew Travel Safety Meeting Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 31/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	o ops @ well		Com	
Cont TIH w/ 38 more jts 3 1/2 L-80 WS hydrotesting to 8000 psi, Tagged 3 different time w/ up to 15 pts but we were able to work through it. Atten tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
tagging the third time and pulled 20 over. Came back down and ran 1 more jt Circulate 60 bbls clean FW @ 2 BPM @ 200 psi reverse. Saw no trash in retruns. Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	fety Meeting		and a second second	
Cont TIH hydrotesting to 8000 psi. And tagged again after 2 jts. Decision made to TOH & look @ packer RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				ere able to work through it. Attempt to PU after
RD Hydrotester RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	rculate 60 bbls clean FW @ 2 BPM @ 20	0 psi reverse. Saw no trash ir	n retruns.	
RU Gerinimo & TOH w/ 92 jts 3 1/2 WS & frac packer. We only dragged 1 time on the way out. We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were mor stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well		jed again after 2 jts. Decision	made to TOH & look @ packer	
We were able to pull 8-10 slivers of metal that were stuck in the packer. slivers were 1/8" wide and 1.5" long and almost identical. There were more stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
stuck along the mandrel seal area orings and in the j-slot. Lunch TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	J Gerinimo & TOH w/ 92 jts 3 1/2 WS & f	ac packer. We only dragged	1 time on the way out.	
TIH open ended w/ 3 1/2 collar on bottom w/ 92 jts and did not tag anything Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well			slivers were 1/8" wide and 1.5" long and a	almost identical. There were more metal slivers
Circulate 65 bbls Clean FW @ 3.75 BPM @ 500 psi conventional and got back a few more of the same metal slivers. TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	nch			
TOH w/ 3 1/2 & collar w/ no drag Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well				
Start TIH w/ AS1-X Peak 10K Frac packer w/ 2.25 F Frac hardened SN, 3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80 WS hydrotesting 8000 psi. SI & Secure well, SDFN Crew Travel No ops @ well	rculate 65 bbls Clean FW @ 3.75 BPM @	500 psi conventional and go	t back a few more of the same metal slive	ITS.
SI & Secure well, SDFN Crew Travel No ops @ well				
Crew Travel No ops @ well		N/ 2.25 F Frac hardened SN,	3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-8	0 WS hydrotesting 8000 psi.
No ops @ well				
Benet Start Date: 9/22/2015				
Report Start Date: 0/22/2015	port Start Date: 8/22/2015			

	Sum	mary Report	Major Rig Work Over (MRWO Casing Repai Job Start Date: 8/6/201 Job End Date: 9/16/201	
	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation	Lusk North		Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014			
		Com		
No ops @ well				
Crew Travel		Hell Andrews		
Safety Meeting				
Cont TIH w/ AS1-X Peak 10K Frac packe	r w/ 2.25 F Frac hardened SN,	3 1/8"X 2.441" Blast jt, on 91 jts 3 1/2 L-80	WS hydrotesting 8000 psi.	
LD 1 jt due to galled threads.				
Lunch		A CONTRACTOR OF THE OWNER OWNE		
Cont TIH w/ 3 1/2 L-80 WS hydrotesting t	to 8000 psi.			
Tie back and RD Tongs				
PU Frac Stack and Test top joint of 3 1/2,	frac stack(XO, Adapter spool	2 frac valves) to 8000 psi(Good)		
Set pkr @ 10447 w/ 21 pts compression(3				
NU Frac Tree and Goat Head	010 (10)		and the second	
Test Goathead against top frac valve to 8	2000 psi/Good)	in the second		
no communication around packer(Tubing RD Key 307 & Reverse unit	was tuli)		and the states	
SI & Secure well, SDFN				
Crew Travel				
Crew Travel No ops @ well				
Crew Travel No ops @ well		Com		
Crew Travel No ops @ well Report Start Date: 8/23/2015		Com		
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well	pipe racks, reverse unit and tan		lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well <b>Report Start Date:</b> 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p	pipe racks, reverse unit and tan	Com Iks. Set 6 frac tanks and mountain mover. F	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well <b>Report Start Date:</b> 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well	pipe racks, reverse unit and tan		lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015	pipe racks, reverse unit and tan		lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well	pipe racks, reverse unit and tar	iks. Set 6 frac tanks and mountain mover. H	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel	pipe racks, reverse unit and tan	iks. Set 6 frac tanks and mountain mover. H	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel Safety Meeting	pipe racks, reverse unit and tar	iks. Set 6 frac tanks and mountain mover. H	lalliburton Dumped Biocide in all ta	nks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel Safety Meeting Finish RD Key 307.		iks. Set 6 frac tanks and mountain mover. F	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel Safety Meeting Finish RD Key 307. ***SWA- Forklift Ent Winch truck cable wa	as starting to fray. Mecanic call	iks. Set 6 frac tanks and mountain mover. F	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel Safety Meeting Finish RD Key 307. ***SWA- Forklift Ent Winch truck cable wa Load reverse unit, and tanks and haul to l	as starting to fray. Mecanic call	iks. Set 6 frac tanks and mountain mover. F	lalliburton Dumped Biocide in all ta	inks.
Crew Travel No ops @ well Report Start Date: 8/23/2015 No ops @ well RD Envirovac & Accumulator, Move out p No ops @ well Report Start Date: 8/24/2015 No ops @ well Crew travel Safety Meeting Finish RD Key 307. ***SWA- Forklift Ent Winch truck cable wa Load reverse unit, and tanks and haul to I Continue filling frac tanks	as starting to fray. Mecanic call Mark 2H	iks. Set 6 frac tanks and mountain mover. F		

Filling frac tanks

Report Start Date: 8/25/2015

No operations @ well.

Spotted in equipment and rigged up frac equipment. Inspected all equipment and ensured all restraints were properly installed.

Discussed days opreations of fraccing. Talked about keeping good communication with all frac crew members and other contractors. All personal gave input and were discussed and written in detail. Talked over heat conditions and to keep hydrating through day. Discussed in detail on taking breaks and to communicate to me as far as to rig down in heat or next morning.

Com

Chevron

<

			Job End Date:	9/16/2
Vell Name ANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
round Elevation (ft) Original RKB (ft) 3,666.00 3,682.00	Current RKB Elevation 3,682.00, 4/23/2014		Mud Line Elevation (ft) Water De	epth (ft)
0,000.00	0,002.00, 4/20/2014			
est lines to 8,000 psi		Com		
Stg 1 frac ("Wolfcamp", top perf 10,585' Shut-in Wellhead PSI = 0 psi	btm perf 10,610')	8-35-15 Irac		
. Breakdown: 4419 psi, 5 bpm, 22.67	obl	JANU		
2. Acid 10% HCL Acid: 47.62 bbls, 47 b	om, 7271 psi	Jan		
8. Spacer SWt: 123.43 bbls, 26.9 bpm,	7494 psi,	$\beta$		
. Pad SW 665 bbls, 33.7 bpm, 7901 ps	i	V		
5. 151 bbls, 30.2 bpm, 7529 psi, .5# (20	/40 Delta Frac 200), Expedite S	and		
5. 293 bbls, 30.5 bpm, 7563 psi, 1# (20/	40 Delta Frac 200), Expedite Sa	and		
7. 437.01 bbls, 29.1 bpm, 8071 psi, 2# (	20/40 Delta Frac 200), Expedite	e Sand.		
8. 3 bbls, 17.9 bpm, 8133 psi, 2.5# (20/4	10 Delta Frac 200), Expedite Sa	IND (SCREENED OUT)		
NOTE: At this point in stage 8, pressure minute or two, nothing could be done.	rose immediatley and rate was xpedite sand was to heavy and	dropped to save screen out. This thick. Screened out. Well was se	helped a little, but pressure kept rising and w cured.	vithin a
(Pressured up to 1000 psi and pressure	dropped down to 650 psi within	seconds. Decision was made not	to keep pressuring up.	
Shut in well.				
Max WHTP: 8206 psi, Avg WHTP: 7492 Max Rate: 34 bpm, Job Rate: 40 bpm	psi			
20/40 Delta Frac 200: 61,710 lbs				
Crew had to wash out lines full of sand to	half frac. Rigged down frac cr	rew. Debriefed with crew over day	s operations.	
No operations @ well.				
Report Start Date: 8/26/2015		Com		
Vell SI. No activity		Com		
Crew travel to location.		S. A. Statis		
GSM JSA review with crews. Discussed Good communication with all crews.	I RU and pressure while cleanin	ng out.	Contraction of the Contract	
Rig up Cudd CTU.		1.4		- Sec. 1
Nait for on word from tech team on what				6
Function test and Pressure test BOP. 50				
SITP 1750#. Trip in hole with 1.75' coil to Weld-on type connecter.) while circulatin		Carbide mill, Bit motor, Dual circ s	sub, Hydraulic disconnect, Dual back pressure	e valve,
Clean out with coil from surface to 4000'. down to 4000'. No hard tag was seen. At 4000', Circulated 2X capacity with 2 sv		weep with EZ mud was pumped ev	very 2000'. Sand was seen in returns from sur	rface
Trip out of hole while circulating at 1.75 b	ppm. Secure well. Debrief crew.			
Crew travel off location.	1. M			
Vell SI. No activity.				1
Report Start Date: 8/27/2015		0		
Vell SI. No activity.		Com		
Crew travel to location				
TGSM and JSA with all crews. Talked ab 360 Myspace.	out the hazard Chemical.			
360 Myspace.				

Chevron

	Lease	Field Name		End Date: 9/16
LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft) 3,666.00 3,682.00	Current RKB Elevation 3,682.00, 4/23/2014		Mud Line Elevation	(ft) Water Depth (ft)
			l	
SITP 2500#. Trip in hole with 1.75" coil Started to get sand and oil in returns at Maintained a 1,75 to 2bpm rate on coil w Cleaned up returns at 10,000' before pro- Cleaned out from 10,000' down to 1045 Recovered a total of 30 bbls of oil. Oil w Circulate 190 bbls with 2 EZ Mud sweep rip out of hole with coil tubing while pu Jn-Flange and lay down BHA. Flange u Crew travel off location. Vell SI. No activity. Report Start Date: 8/28/2015	4000' down to 10,000' while sto with 2-2.5bpm rate on return. oceeding down hole. 0' where packer profile was tage vas deposited to the bulk crude to os to clean up returns. ming at 2bpm rate.	ppping every 500' to short trip and ged. (3' off from tubing tally) ank on location. FMT FS was noti	pump a EZ mud sweep at 6000', a	3000' and 10,000'
ell SI. No activity	10			
Crew travel to location.	nt on location and using enotion	Heavy lifting and line of fire whi	le making up iron. Using good oor	unication
Talk with crew about moveing equipme SITP 2250# First thing this morning.	in on location and using spotter	s. neavy litting and line of fire whi	ie making up iron. Using good con	iunication.
Pull water off of frac tanks to be moved	on location to make room for fla	are stack. Moved in flow back equ	ipment and rig up. Pressure test a	Il lines.
Open up well to gas buster tank to bleed Gas head bled off while flowing 20bho Continue to monitor flow rate and return Report Start Date: 8/29/2015	rate at 750#.			
Continue flowing well down		Com		esta de la composición
720 psi/25/64 /1259MCFPD rate/22BPł 0500(Right before valve failed) 300 psi/ 31/64 /671 MCFPD rate/19BPł	H oil			
Vait on parts to fix pneumatic ESD valv SITP after 2.5 hrs 800 psi Open well & Continue flowback 1100 580 psi/ 22/64 /668MCFPD rate/18BPH 1800 220 psi/ 31/64 /680 MCFPD rate/19BP Midnight 180psi 32/64 670MCFPD rate / 13 BPH MCE sold vesterday: 2MCE	H oil/ 2 BPHwtr			
ITP after 2.5 hrs 800 psi Open well & Continue flowback 100 80 psi/ 22/64 /668MCFPD rate/18BPH 800 20 psi/ 31/64 /680 MCFPD rate/19BP Midnight 80psi 32/64 670MCFPD rate / 13 BPH MCF sold yesterday:2MCF MCF Sold today: 115 mcf MCF Flared yesterday:965MCF	H oil/ 2 BPHwtr			
ITP after 2.5 hrs 800 psi open well & Continue flowback 100 80 psi/ 22/64 /668MCFPD rate/18BPH 800 20 psi/ 31/64 /680 MCFPD rate/19BP lidnight 80psi 32/64 670MCFPD rate / 13 BPH ICF sold yesterday:2MCF ICF Sold today: 115 mcf ICF Flared yesterday: 965MCF otal oil Recovered:335 bbls	H oil/ 2 BPHwtr			
ITP after 2.5 hrs 800 psi open well & Continue flowback 100 80 psi/ 22/64 /668MCFPD rate/18BPH 800 20 psi/ 31/64 /680 MCFPD rate/19BP Idnight 80psi 32/64 670MCFPD rate / 13 BPH ICF sold yesterday:2MCF ICF Sold today: 115 mcf ICF Flared yesterday: 965MCF otal oil Recovered:335 bbls otal wtr recovered:152	H oil/ 2 BPHwtr H oil / 1BPH wtr	n, CO2 4.5%, API 41.6 60°F		
SITP after 2.5 hrs 800 psi Open well & Continue flowback 100 80 psi/ 22/64 /668MCFPD rate/18BPH 800 20 psi/ 31/64 /680 MCFPD rate/19BP Aidnight 80psi 32/64 670MCFPD rate / 13 BPH ACF sold yesterday:2MCF ACF Sold today: 115 mcf ACF Flared yesterday: 965MCF Total oil Recovered:335 bbls Total oil Recovered:152 20 1130hrs BS&W 1%, PH 7.5, chloride	H oil/ 2 BPHwtr H oil / 1BPH wtr	n, CO2 4.5%, API 41.6 60°F		
SITP after 2.5 hrs 800 psi Open well & Continue flowback 100 880 psi/ 22/64 /668MCFPD rate/18BPH 800 220 psi/ 31/64 /680 MCFPD rate/19BP Midnight 80psi 32/64 670MCFPD rate / 13 BPH MCF sold yesterday:2MCF MCF sold today: 115 mcf MCF Sold today: 115 mcf MCF Flared yesterday: 965MCF Total oil Recovered:335 bbls Total oil Recovered:152 2 1130hrs BS&W 1%, PH 7.5, chloride Seeing little to no sand	H oil/ 2 BPHwtr H oil / 1BPH wtr 42,000, H2O 8.5ppg, H2S 0ppr			
SITP after 2.5 hrs 800 psi Open well & Continue flowback 1100 580 psi/ 22/64 /668MCFPD rate/18BPH 1800 220 psi/ 31/64 /680 MCFPD rate/19BP Vidnight	H oil/ 2 BPHwtr H oil / 1BPH wtr 42,000, H2O 8.5ppg, H2S 0ppr			

Chevron	Sum	nmary Report	Major Rig Work Over (MRWC Casing Repa Job Start Date: 8/6/201 Job End Date: 9/16/201		
Well Name LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent		
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation 3.682.00, 4/23/2014		Mud Line Elevation (ft)	Water Depth (ft)	
3,666.00 3,682.00	3,002.00, 4/23/2014				
Flowing well		Com			
00:00 hrs - 16 hrs flowing well on a 32/6 End choke size 33/64	34 choke flowing well.				
Beginning psi 180psi 1800 psi: 160					
Ending psi: 150 psi Last BWPH 1 BPH Last BOPH 6 BPH					
Gas rate to flare 0 Mcf					
Gas rate to sales 530 MCF(580MCFPD Gas vol sold today 403 MCF	Total rate coming from well)				
Water Recovered Today 39 bbls					
Oil Recovered today 234 bbls					
Total wtr recovered 219 bbls TLLTR 1464 bbls					
Continue flowback operations w/ 24 hr s	upervision				
Chloride 42,000, H20 8.5ppg H2S 0ppm, C02 4.5%, API 41.6@60°F BSW 1% water, 99% oil					
Orfice plate in sales meter changed to 1 525 bbls oil sold today to Plains. 0.15%				all Sur	
Report Start Date: 8/31/2015					
Flowing well		Com			
lowing wen					
00:00 hrs - 8.5 hrs flowing well on a 33/	64 choke flowing well, 5 hrs on 3	34/64		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Beginning psi 155psi					
Ending psi: 50 psi					
Last BWPH 2 BPH Last BOPH 3 BPH					
Gas rate to flare 0 Mcf(Pressure low end	ough to sell all gas today				
Gas rate to sales 300-450 MCF					
Gas vol sold Yesterday 403 MCF Gas to flare yesterday: 142 MCF				The second second	
				Sound States	
Water Recovered Today 22 bbls Oil Recovered today 109 bbls					
Total wtr recovered 241 bbls				1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
TLLTR 1442 bbls Total oil recovered: 718 bbls				1.	
1130hrs Chloride 56,000, BS&W 2%, Pł	1 8, H2O 8.65ppg, API 42.2, H2	S 0ppm, CO2 4.5%			
RD Halliburton Flowback, Empty tanks,	Move out frac tanks and half frac	c	<u> </u>		
No ops @ well			1		
Report Start Date: 9/1/2015	and the second				
NO ACTIVITY AT WELLSITE		Com			
CREW TRAVEL TO LOCATION					
TGSM W/ RIG CREW, SLB REVERSE			and the state of the		
		NS. I CALLED OUT HOBBS ANCHOR TO	RETEST THE ANCHORS	ALL ANCHORS	
	CREW COULD MOVE THE NW AATIONS AND NOTIFIED WE.	ANCHOR BY HAND SIDEWAYS. AFTER			

PERFORMED RIG DRILLS. WAITING ON ORDERS.

OFFLOAD PROD STRING.SPOT TBG RACKS AND LAY DOWN MACHINE.

Chevron

Major Rig Work Over (MRWO) Casing Repair Job Start Date: 8/6/2015 Job End Date: 9/16/2015

				UCD EI	u Date. 3/10/2013
Well Name LANDSDALE 'D' FEDERAL COM 00		ase andsdale 'D' Federal '	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Cur	rrent RKB Elevation	Luok Holdi	Mud Line Elevation (ft)	Water Depth (ft)
3,666.00 3,682	2.00 3,6	682.00, 4/23/2014			
			Com		
RAISED DERRICK TO CHANGE OU TBG PSI 400#.	IT TBG	LINE. LOWERED DERRIC	К.		
CREW TRAVEL					
NO OPERATIONS AT WELLSITE.					
Report Start Date: 9/2/2015					
			Com		
NO ACTIVITY AT WELLSITE. CREW TRAVEL TO LOCATION.	S				A State Stat
TGSM, DISCUSSED WITH RIG CRI			DOWN MACHINE ODED THE		Ball and the
MIKE NORTHCUTT, JOE DUNN W					
AGREED THAT IT NEEDED TO BE			ATA, RIG SUPERVISOR CAME	JUT TO INSPECT THE NW ANCHO	
CREW TRAVEL					
NO OPERATIONS AT WELLSITE.					
Report Start Date: 9/3/2015			Com		
NO OPERATIONS TAKING PLACE	ON LO	CATION AT THIS TIME.			
CREW TRAVE TO LOCATION.	5				1.16
WAITING ON 48 HOUR ONE CALL (WENT OVER WELL SAFE WITH L			<del>.</del>	la la la	
JSA TGSM FOR INSTALLING ANCH PIPE, SWA, SWP, TENET AND HAZ				EEDING DOWN WELL AND KILLIN	IG, TRIPPING
MIRU HOBBS ANCHOR AND INSTA	ALL AN	CHORS. VERIFY WITH PU	LL TEST (23K). RDMO HOBBS A	NCHOR	
R/U KEY 307. SCOPE DERRICK, IN					Contraction of the
CHECKED PRESSURE ON WELL:	150 PS	I ON CASING, 700 PSI ON	TUBING. BLEW DOWN.		IS THE PARTY
KILLED WELL WITH 100 BBLS OF	10 PPG	BRINE			The second second
PERFORMED RIG WALK AROUND	/ SET	COFO / INSTALL AND CAL	IPER 3-1/2" TBG ELEVATORS. I	DISCONNECT BLOW DOWN LINES	
UNBOLT, LIFT UP FRAC VALVE AN	ID TES	T BOP: 250 LOW/1000 HIG	H-GOOD		Market Providence
(DUE TO HOLE IN CASING HAD TO					
FLOW BACK WELL AFTER BOP TE		F INTO BACKSIDE AND CH	IARGE OF AND BE ABLE TO HO	JED FRESSORE)	and the second second
N/D FRAC VALVE, INSTALL SLIPS			CKER AND BOOH		a state of the second
AFTER RELEASING PACKER, TRIE				TOP INCREASING TO 130K (COLIL	
OVER 130K). TROUBLESHOOT BY AGAIN- THIS TIME WITH TOOLPUS	WORK	KING PIPE, CIRCULATING-	NO RESULT. P/U 1 JOINT AND	WENT AND RESET PACKER AND	
POOH AND L/D 54 JOINTS OF 3-1/2	2" FRA	C STRING. SWFN. EOT=87	50'		Star Barrier
DEBRIEF WITH CREW ON SAFE D					
CREW TRAVEL HOME.					
NO OPERATIONS TAKING PLACE	ON LO	CATION AT THIS TIME.		5 2000	
Report Start Date: 9/4/2015	12				and the Barry March
	01110		Com		
NO OPERATIONS TAKING PLACE CREW TRAVE TO LOCATION.	UN LUC	CATION AT THIS TIME.			State State
JSA TGSM FOR TRIPPING PIPE, H WHEEL #4, AND JOB SCOPE FOR			RED SAFETY TOPICS FROM CC	MMS MEETING, SWA, SWP, TENE	T AND HAZARD
PERFORMED RIG WALK AROUND			G ELEVATORS / CHECKED PR	ESSURE ON WELL: CASING WAS	ON VACUUM AND
POOH LAYING DOWN 52 JOINTS O (TRICKLING BRINE IN HOLE WHILI					
ONCE RIG REACHED BELOW 70K	The second second		CK TO FAST LINE.		
POOH LAYING DOWN 219 JOINTS (OFFLOAD TUBING TO TRUCK WH	OF 3-1	/2" TUBING AND LAY DOW		- 17 - 1	
(TRICKLING BRINE IN HOLE WHILI					
REMOVE 3-1/2" PIPE RAMS AND R	EPLAC	CE WITH 2-7/8" RAMS.		12.24	
REPLACE ELEVATORS AND CALIF ONTO RACKS, INSTALL ENVIROVA			PIPE RACK, RELEASE L/D MACH	INE. INSTALL CAT WALK, MOVE 2	2-7/8" TUBING
P/U TEST PACKER, 1 JOINT AND F			1000 HIGH-GOOD, L/D TEST P/	ACKER	State of Land
P/U MILL TOOTH BIT AND RIH WIT	11000				
DEBRIEF WITH CREW ON SAFE E					AC THE REAL PROPERTY OF

Page 11/15

Chevron

~

			Job End	Date: 9/16/2015
	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation 3,682.00, 4/23/2014		Mud Line Elevation (ft)	Water Depth (ft)
0,000.00				
CREW TRAVEL HOME.		Com		
NO OPERATIONS TAKING PLACE ON I	OCATION AT THIS TIME.			
Report Start Date: 9/5/2015				1 Same
CREW DAY OFF. NO OPERATIONS ON		Com		
Report Start Date: 9/6/2015	LOOATION.			
ODENLEAN OFF NO ODERATIONS ON		Com		and a substitution
CREW DAY OFF, NO OPERATIONS ON Report Start Date: 9/7/2015	LUCATION			
Report Start Date. SH12013		Com		
CREW DAY OFF, NO OPERATIONS ON	LOCATION.			
Report Start Date: 9/8/2015		Com		
NO ACTIVITY AT WELLSITE.			*	
CREW TRAVEL TO LOCATION.				
PRE-JOB SAFETY MEETING W/RIG CR	EW AND REVERSE UNIT OP	PER.		
SITP: 0 SICP: 0				
PUMPED 24 BBLS BRINE.	TRING FROM BACKS			
STRAP AND PICK UP 2 7/8" L80 TBG S CREW LUNCH	TRING FROM RACKS.	and the second		
FINISH PICKING UP TBG, TAG FILL AT	10.608' LAY DOWN 2 JTS. E	OT AT 10 560' 25' ABOVE TOP P	FRF	1
INSTALL STRIPPER HEAD, TIED BACK CIRC W/ 280 BBLS @ 4 BPM AND 1,00 AND DECISION WAS MADE TO ORDER	TBG LINE. TIE IN REVERSE 0 PSI. SLOWED TO 2 BPM PS	UNIT HOSE TO SEE IF WE COUL	D ESTABLISH CIRC. W/FRESH W	
SWFN CREW TRAVEL .				the stand in the second
NO ACTIVITY ON LOCATION.				the second second
Report Start Date: 9/9/2015	3	States of the second		E 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
		Com		
NO OPERATIONS TAKING PLACE ON I	OCATION AT THIS TIME.		the second s	
JSA TGSM FOR TRIPPING PIPE, PRES AND HAZARD WHEEL #9, AND JOB SC		LOUD NOISE, WENT OVER WEE	KLY INCIDENTS WITH CREW, SV	VA, SWP, TENET
PERFORMED RIG WALK AROUND / SE NO PRESSURE ON TUBING	T COFO / CALIPER 2-7/8" TE	BG ELEVATORS / CHECKED PRES	SSURE ON WELL: CASING WAS (	ON VACUUM AND
MIRU WELL FOAM. SPOT IN TRUCKS,	HOOK UP LINES/RESTRAINT	TS, R/U MAINFOLD	and the second	
POOH WITH 16 STANDS OF 2-7/8" TUE RECOMMENDATION)				
ESTABLISH CIRCULATION. PUMPED T	OTAL OF 90 BBLS OF FRESH	H WATER: CASING PRESSURE-6	50 PSI,	
PUMPED @ .9 BPM (38 GPM) WITH FR PUMPED@ 900 CFM WITH AIR	ESH WATER			
RIH WITH 16 STANDS OF 2-7/8" TUBIN				
P/U 2 JOINTS AND R/U POWER SWIVE			· · · · · · · · · · · · · · · · · · ·	
TAG FILL @ 10608' AND CLEAN OUT V (TAGGED CEMENT @ 10888')	FULL TO 10888 USING FOAM	I/AIR UNIT.		
CIRCULATED BOTTOMS UP WITH WA	TER/FOAM MIX(165 BBLS IS	BOTTOMS UP CAPACITY ) WITH	AIR FOAM UNIT.	
PUMP RATE: .9 BPM (38 GPM) OF FRE	SH WATER			
WHILE PUMPING 900 SCFM OF AIR				
TOTAL FRESH WATER PUMPED FOR TOTAL SOAP PUMPED FOR JOB: 40 G USED 1 BAG OF CAUSTIC FOR JOB TO	ALS			
R/D WELL FOAM LINES AND RIG UP R	EVERSE UNIT. PUMPED 60	BBLS OF 10 PPG BRINE TO KILL	WELL. (60 BBLS IS TUBING CAPA	CITY)
R/D POWER SWIVEL				
POOH 5 STANDS, REMOVE CHECK V			JOINTS)	
DEBRIEF WITH CREW ON SAFE EFFIC	IENT DAY. DISCUSSED POA	A FOR TOMORROW		
CREW TRAVEL HOME. NO OPERATIONS TAKING PLACE ON I	OCATION AT THIS TIME			
Report Start Date: 9/10/2015	OUATION AT THIS TIME.			
	12. N. P	CONTRACTOR OF THE OWNER	P P P P P P P P P P P P	Sector State in the

Chevron

Major Rig Work Over (MRWO) Casing Repair Job Start Date: 8/6/2015 Job End Date: 9/16/2015

			Job End	Date: 9/16/2015
Well Name LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation	Luok Horan	Mud Line Elevation (ft)	Water Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014			
		Com		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			
CREW TRAVE TO LOCATION. JSA TGSM FOR TRIPPING PIPE, CHE	CKING, PRESSURE, HANDLING	G OF BHA, TRIPPING HAZARDS, S	SWA, SWP, TENET AND HAZARI	D WHEEL #10,
AND JOB SCOPE FOR THE DAY				
PERFORMED RIG WALK AROUND / S PUMPED 75 BBLS OF 10 PPG BRINE 1		3 ELEVATORS / CHECKED PRES	SURE ON WELL: 750 PSI ON CA	SING, BD
TIH WITH 2-7/8" TUBING AND TAG FIL				
L/D 11 JOINTS AND STAND BACK 18 S		C). CONSOLTED W.E. AND DECIS	SION WAS MADE TO NOT CLEAN	1001
ONCE UNDER 70K ON WEIGHT, SWIT		LINE		
POOH AND STAND BACK WITH 288 JO				
CREW LUNCH				
MIRU HYDROTESTERS, INSTALL SHE	EVE IN DERRICK. R/D WELL F	FOAM MANIFOLD, MOVE PIPE RA	CKS, OFFLOAD RODS	
P/U BHA AND RIH				
(1) 3" BPMAJT,				
(1) 2-7/8" SAND SCREEN (1) 2-7/8" MSN				
(2) 2-7/8" TK-99				
RIH WITH 2 JOINTS OF 2-7/8" L-80 TU 80 JOINTS OF 2-7/8" L-80 TUBING WH			KER SUB OF 2-7/8" TUBING AND	RIH. RIH WITH
DEBRIEF WITH CREW ON SAFE EFFIC	CIENT DAY. DISCUSSED POA	FOR TOMORROW		
CREW TRAVEL HOME.	- Alexandra - A		the second s	- the head of the second se
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		and the second se	renter and the
Report Start Date: 9/11/2015				
		Com		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			
CREW TRAVE TO LOCATION. JSA TGSM FOR TRIPPING PIPE, HIGH		TRIPRING HAZADDO CIALA CIAL		#4 AND 100
SCOPE FOR THE DAY	PRESSURE, HIDROTESTING	, TRIPPING HAZARDS, SVVA, SVV	P, TENET AND HAZARD WHEEL	#1, AND JOB
PERFORMED RIG WALK AROUND / SI	ET COFO / CALIPER 2-7/8" TB(	G ELEVATORS / CHECKED PRES	SURE ON WELL: 25 PSI ON CAS	ING. BD
PUMPED 25 BBLS OF 10 PPG BRINE T			17. T	
RIH WITH 241 JOINTS OF 2-7/8" 6.5# L	-80 PRODUCTION TUBING WI	HILE HYDROTESTING TO 6000 PS	SI. RDMO HYDROTESTERS	
TIE BACK FORM FAST LINE.				1997 - 10
VISIT FORM V&V TEAM/CREW LUNCH	1	1		122 4 13
CLEAN RIG FLOOR, RAISE RIG FLOOP	R. N/D ENVIRO PAN, AND N/D F	BOP		Section 1 1
TRIED TO SET TAC MULTIPLE TIMES, TIMES-DID NOT SET. L/D 1 JOINT AND	TOV AGAINI NO DEGUNT NO	TUDINO UEAD	O SET WITH TONGS IN HIGH G	EAR MULTIPLE
(CONSULTED WITH W.E. DECISION W	AS MADE TO POOH AND CHA	NGE OUT TAC)		
OPERATIONS SUSPENDED DUE TO L				
( CONSULTED WITH W.E. AND DECIS POOH GET UNDER 45K ON WEIGHT 1				BOP, NEED TO
DEBRIEF WITH CREW ON SAFE EFFIC				
CREW TRAVEL HOME.				State of the state of the
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			ALL ALL A
Report Start Date: 9/12/2015				
		Com		
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.			
CREW TRAVE TO LOCATION. JSA TGSM FOR TRIPPING PIPE, BOP	TESTING, WORKING AT HEIG	HTS, TRIPPING HAZARDS, SWA,	SWP, TENET AND HAZARD WH	EEL #2, AND
JOB SCOPE FOR THE DAY PERFORMED RIG WALK AROUND / SI				CUUM
SWITCH FROM TIE BACK TO FAST LIN		C LEVATORS / CHECKED FRES	OUNE ON WELL, CASING ON VA	
LIFT FLOOR AND N/D WELLHEAD.				
N/U BOP AND HOOK UP TO ACCUMUL	ATOR NULENVIROPAN PPE			A. 43
POOH WITH 114 JOINTS OF 2-7/8" TU		LOOK TO FOOT		
OPERATOR NOTICED ENGINE PROBL PERSONNEL TO ARRIVE FROM ODES	EMS AND USED SWA AND SH	IUT DOWN DUE TO ENGINE PRO	BLEMS WITH RIG. (WAIT FOR R	EPAIR
TROUBLESHOOT AND REPAIR ENGIN		A MARCH MARCH		and the second
AND REPAIR ENGIN		Contraction of the second second	and the second second second second	

Page 13/15

Chevron

		-		1 Date: 9/16/201
Well Name LANDSDALE 'D' FEDERAL COM 001	Lease Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft)	Water Depth (ft)
3,666.00 3,682.00	3,682.00, 4/23/2014			
		Com		
DEBRIEF WITH CREW. DISCUSSED F	POA FOR MONDAY			
CREW TRAVEL HOME.			Marine A.	
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		Land State	A starting and a starting of the
Report Start Date: 9/13/2015		Com		
CREW SCHEDULE DAY OFF. NO OPE		Com		
Report Start Date: 9/14/2015				
NO OPERATIONS TAKING PLACE ON		Com		
CREW TRAVE TO LOCATION.	LOCATION AT THIS TIME.			the second s
	• TESTING, WORKING AT HEIGHTS, T	RIPPING HAZARDS, SWA, SWP, TENE	T AND HAZARD WH	EEL #4, AND
PERFORMED RIG WALK AROUND / S N/D WELLHEAD	ET COFO / CALIPER 2-7/8" TBG ELEV	ATORS / CHECKED PRESSURE ON WE	ELL: CASING 20 PSI	
POOH WITH 106 JOINTS OF 2-7/8" TU	BING AND STAND BACK		- The second	
		AMS TO 250/1000 PSI FOR 5 MIN-GOOD	D. L/D PACKER	The second
POOH WITH 103 JOINTS OF 2-7/8" TU		AC WERE FLATTENED IN) CONSULTE		DISCUSSED
CREW LUNCH				
P/U NEW TAC AND RIH WITH 323 JOII		ING.		
SWITCH FROM FAST LINE TO TIE BAG			2 . 18 A.	
	ET NEW TAC WITH CARBIDE SLIPS @	2 10,506'. VERIFY TAC SET. (SET IN 201	( TENSION)	
N/D BOP AND RELEASE		14		121
N/U WELLHEAD, INSTALL ROD BOP, F			A 10,45	
DEBRIEF WITH CREW. DISCUSSED F	POA FOR MONDAY	2 10 144	0 10)0	
CREW TRAVEL HOME.		U		denter - Elige
NO OPERATIONS TAKING PLACE ON	LOCATION AT THIS TIME.		Section and the section of the secti	
Report Start Date: 9/15/2015		Com		
No ops @ well				
Crew Travel			1.1.1	
Safety Meeting				and the second second
RU Floor and rod running equipment				and the state of the
Start RIH w/ pump and rods			437.2	
Lunch				
Cont RIh w/ rods:				
25-150-RHBM-26-6 Pump w/ 4 ft 7/8" g 8- 1.5" sinker bars 297 - 7/8" Weatherford HD 8 - 7/8" Weatherford HD Guided rods(3 g 12 - 7/8" Weatherford HD 97 - 1" Weatherford HD 1 - 8" Pony Rod Weatherford HD 1.5" - 30ft SM polished rod w/ 1" pin				
Well should be hung on with 92" from the	e bottom of the rod coupling to the top of	f the stuffing box.		
RD Floor				
Load and test tubing: 12.5 bbls to load. Tested to 520 for 15 m	nins(Good)			
RD Pulling unit & Aux Equipment			1	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Crew Travel			Section Section &	1. 1. 1. 1. 1. 1.
No ops @ well				A CARLES AND
Report Start Date: 9/16/2015				
No ops @ well		Com		
No ops @ well Crew Travel	Contraction of the second s			
Safety Meeting	in the second	a fa	and the second second	

Chevron		nmary Report	Job Sta Job End	rk Over (MRWO) Casing Repair rt Date: 8/6/2015 Date: 9/16/2015
Well Name LANDSDALE 'D' FEDERAL COM	001 Landsdale 'D' Federal	Field Name Lusk North	Business Unit Mid-Continent	
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation 682.00 3,682.00, 4/23/2014		Mud Line Elevation (ft)	Water Depth (ft)
3,000.00 3,	562.00 5,062.00, 4/25/2014			
Load tanks and reverse unit, Road	d rig to Salado Draw pad	Com		
Perform Handover with Contract F	rield Specialist Sammy Licon	· · · · · · · · · · · · · · · · · · ·		
- 14				
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
Maria and Anna and An				
Reg Prairie Inc.				
5 3 P. P. T. S. P.				
(1995)-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1				



### **Wellbore Schematic**

	COM 001 Landsdale 'D' Federal	Fie	usk North				Busine Mid-0	Contine	nt	
Land - Original	Hole, 10/26/2015 9:38:30 AM	Job Details	Sec. and						Com Strangered	
V	ertical schematic (actual)		Job Cat				Start	Date	and the second se	End Date
		Major Rig Wo					2015		8/24/2015	
ARALIN, MARKEN		Major Rig Wo				8/2	6/2015		8/27/2015	
		Major Rig Wo	rk Over (N	MRWO)		8/2	8/2015		8/31/2015	
		Major Rig Wo	rk Over (N	MRWO)		9/1	2015		9/16/2015	
		Casing String	as							
		The second second	Section .						Land and the	Set Dep
	Casing Joint; 16-402; 386.00; 13 3/8;	Csg De Surface	S	OD	(in) 13 3/8	Wt/Len (lb/ft)	GI 0 H-40	rade	Top Thread	(MD) (fth
	12.715; 1-1		Oralia					1.1		
		Intermediate (	Casing		8 5/8	28.0	0 H-40			4,2
	ten and the definition and the set of the se	Production Ca	eina	-	5 1/2	17.0	0 S-95			13,0
	Casing Joint; 16-4,200; 4,184.00; 8	Tubing String	-	1	0 112	17.0	010-00			15,0
	5/8; 8.017; 2-1	Tubing - Prod		ot at 10	687 Off	(B on 9/1	4/2015 1	1.00		
		Tubing Description		et at Tu	,007.011	Run D		String Le	ngth (ft) Set De	epth (MD) (fi
		Tubing - Prod	uction			9/1	4/2015		10,670.97	10,68
	8		Item Des		Jts					Btm (ftKl
~~~~		Tubing			33				10,417.80	10,43
		Tubing Pup Jo	oint			1 27/	6.50	L-80	4.00	10,43
		Tubing				2 27/	6.50	L-80	65.41	10,50
		Anchor/catche	er			1 27/	3	1	2.75	10,50
		Tubing	1.1			2 27/	6.50	L-80	65.42	10,57
		Tubing TK-99	COATED	)		2 27/			65.15	10,63
	Tubing; 16-10,434; 10,417.80; 2 7/8;	Pump Seating		12 TEL		1 27/			0.80	10,63
a Armenia Arten da Ar	2.441; 1-1	Gas separato				1 27/		-	23.84	10,66
	Casing Joint; 16-13,000; 12,984.00; 5 1/2; 4.906; 3-1	Tail Joint	1997				3	-	25.80	10,68
		Rod Strings				<u>'</u>	1	-	20.00	10,00
an a		WEATHERFO		S on Ol	45/2045	12.00				
		Rod Description	JKD KUD	5 on 9/	15/2015	Run D	ate	String Le	noth (ft) Set De	pth (ftKB)
	Tubing Pup Joint; 10,434-10,438;	WEATHERFO	ORD ROD	S			5/2015		10.614.00	10.63
	4.00; 2 7/8; 2.441; 1-2		Item Des		Jts	OD (in	Wt (lb/ft)	Grade	Len (ft)	Btm (ftKl
	Tubing; 10,438-10,503; 65.41; 2 7/8; 2.441; 1-3	Polished Rod		C-1.		1 1 1/2	2		30.00	5
	Anchor/catcher; 10,503-10,506; 2.75;	Pony Rod	12.18			1	1 2.90	Speci	8.00	6
	2 7/8; 1-4		· ·	-			1. 16	al		1.12
	Tubing; 10,506-10,571; 65.42; 2 7/8; 2.441: 1-5	Sucker Rod			1	97	2.90	Speci	2,425.00	2,48
								al		15-13
	Shaped Charge; 10,585-10,610;	Sucker Rod				12 7/	3 2.22		300.00	2,78
100 H	Tubing TK-99 COATED; 10,571-					-		al		
	10,637; 65.15; 2 7/8; 2.441; 1-6	Guided Sucke	er Rod			8 7/	2.22	Speci al	200.00	2,98
		Qualitat Dad		- ja den de		7 7/	0.00	A COLORED IN	7 405 00	10.11
		Sucker Rod	60.272 J		- 29	97 7/8			7,425.00	10,41
		Sinker Bar	1	5		8 1 1/2	-	K	200.00	10,61
	an any management of the second state of the second state of the second state of the second state of the second					1 3	2		26.00	10,63
	Pump Seating Nipple; 10,637- 10,637: 0.80: 2 7/8: 1-7	Rod Pump								
	Pump Seating Nipple; 10,637- 10,637; 0.80; 2 7/8; 1-7	Rod Pump Perforations								
	10,637; 0.80; 2 7/8; 1-7		1		D		red Shot			
		Perforations	Top (ftKB		(ftKB) (sho	ens Ente ots/ft)	red Shot Total		Zone & Completio	n
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations	Тор (ftКВ 10,585.		(ftKB) (sho	ens Ente			Zone & Completio	n
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8	Perforations Date 8/20/2015	10,585.		(ftKB) (sho	ens Ente ots/ft)			Zone & Completio	n
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings	10,585.	.0 10,6	(ftKB) (sho	ens Ente ots/ft) 4.0				n
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015	10,585.	.0 10,6	(ftKB) (sho	ens Ente ots/ft) 4.0			Zone & Completio	20
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Date 8/20/2015 Other Strings Run Date	10,585.	.0 10,6	(ftKB) (sho	ens Ente ots/ft) 4.0				n
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings	10,585.	0 10,6 Date	(ftKB) (sho	ens Ente ots/ft) 4.0	Total	II Date		
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole	10,585.	0 10,6 Date	(ftKB) (shu 10.0 Set Deptt	A.0	Total	II Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des	10,585.	0 10,6 Date ρ (ftKB)	(ftKB) D (shu 10.0 Set Deptt Btm (ftKB)	A.O Run Date	Total	II Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925.	Btm (ftKB)         D           Set Deptt         10.0           Btm (ftKB)         10,926.	A.O Run Date	Total	li Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des CIBP	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925. 0	Btm (ftKB)         D           10.0            Set Dept!            Btm (ftKB)         10,926.           0         0	A.O Run Date	Total	II Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des CIBP	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925. 0 2,506.	D.           (shr           10.0           Set Depth           Btm (ftKB)           10,926.           0           12,509.	A.O Run Date	Total	ll Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des CIBP	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925. 0 2,506.	D.           (shr           10.0           Set Depth           Btm (ftKB)           10,926.           0           12,509.	A.O Run Date	Total	II Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des CIBP	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925. 0 2,506.	D.           (shr           10.0           Set Depth           Btm (ftKB)           10,926.           0           12,509.	A.O Run Date	Total	ll Date	Com	
	10,637; 0.80; 2 7/8; 1-7 Gas separator; 10,637-10,661; 23.84; 2 7/8; 1-8 Tail Joint; 10,661-10,687; 25.80; 3; 1	Perforations Date 8/20/2015 Other Strings Run Date Other In Hole Des CIBP	10,585. Pull Top 10	0 10,6 Date p (ftKB) 0,925. 0 2,506.	D.           (shr           10.0           Set Depth           Btm (ftKB)           10,926.           0           12,509.	A.O Run Date	Total	ll Date	Com	



# **Tubing Summary**

	D' FEDERAL COM 00		al	Lu	ld Name Isk North	-			N		ntinent		
round Elevation	(ft) 3,666	Original RKB Elevation (ft)		3,682.00 3,	rrent RKB I		4		N	lud Line	Elevation (ft)	Water Depth	(ft)
urrent KB to Gro	ound (ft)	Current KB to Mud Line (ft)			rrent KB to				C	Current K	B to Tubing He	ad (ft)	
	16 Land - Original Hole, 9/14/201		Tubl	na Ctringe				-					
	Land - Original Hole, 9/14/201	5 11.00.00 AM		Description	Pla	nned Run?			Set Depth (N	MD) (ftKB	3) Se	t Depth (TVD) (	ftKB)
tK (ftK Incl B) B) (°)	Vertical sch	ematic (actual)	Run Da	ng - Production		n Job	N		Pull Date		10,687.0	ll Job	
	<b>1</b> 28 <b>100 10 10 10 10 10 10 10</b> 20 1			9/14/2015	Ca 8/6	asing Re 6/2015 1	0:00		- day	14			
			Jts 321	Item Des Tubing	OD (in) 2 7/8	ID (in) 2.441	Wt (lb/ft)	Gra	Contraction of the second s	Thread	Len (ft) 10,417.	Top (ftKB) 16.0	Btm (ftK 10,433
											80		
				Tubing Pup Joint		2.441		L-80			4.00	10,433.8	10,437
					24.	2.441	6.50	L-80		-	65.41	10,437.8	10,503
81			2	Anchor/catc her Tubing	2 7/8	2.441	6.50	L-80			2.75 65.42	10,503.2	10,506
843			2	1.		2.441		L-80			65.15	10,506.0	10,571
HE.T				99 COATED	2 110	2.441	0.50	L-00			05.15	10,571.4	10,030
992.8		1-1; Tubing; 2 7/8; 2.441; 16; 10,417.80	1	Pump Seating Nipple	2 7/8						0.80	10,636.5	10,637
4117		1-2; Tubing Pup Joint; 2 7/8;	1	Gas separator	2 7/8						23.84	10,637.3	10,661
17.7		2.441; 10,434; 4.00		Tail Joint	3	1					25.80	10,661.2	10,687
		1-3; Tubing; 2 7/8; 2.441; 10,438; 65.41	Rod De	Strings escription	Pla	nned Run?			Set Depth (ft	KB)	Se	t Depth (TVD) (f	tKB)
81.1		1-4; Anchor/catcher; 2 7/8; 10,503; 2.75	ROD				N			1	10,637.0	1	
571.6		1-5; Tubing; 2 7/8; 2.441; 10,506; 65.42	Run Da	9/15/2015	Ca	n Job Ising Re 5/2015 1			Pull Date		Pu	ll Job	
				Components									
let.o			Jts 1	Item Polished Rod	Des		D (in)	Grade	Sprayloy	and the second second	Len (ft) 30.00	Top (ftKB) 23.0	Btm (ftK 53
101.5		1-6; Tubing TK-99 COATED; 2 7/8; 2.441; 10,571; 65.15	1	Pony Rod			1 S	pecial	HD		8.00	53.0	61
			11 1	Sucker Rod				pecial	HD		2,425.00		2,486
		1-7; Pump Seating Nipple; 2		Sucker Rod		1.	7/8 S		HD		300.00	a second second	1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
a7.5		7/8; 10,637; 0.80 1-8; Gas separator; 2 7/8;		Guided Sucke Sucker Rod	er Rod		7/8 S 7/8 H		HD HD		200.00 7,425.00		2,986 10,41
81.1		- 10,637; 23.84 - 1-9; Tail Joint; 3; 10,661; 25.80		Sinker Bar			1 1/2 K				200.00	10,411.0	10,611
147.0		. 9, Fair Sonn, 9, 10,001, 23.00		Rod Pump			2				26.00	10,611.0	10,637
					1	<u></u>			1		1		
94.9													
et s													
337.3													
.508.5	2 <u>1</u> 4 2 <u>14</u> 4												
1.588.5													1.5
			11										

								Н	OBBS C	CD				
Form 3160-4 (August 2007)			DUDEA	RTMENT	D STATES OF THE IN ND MANA	TERIOR	Т		30			O	MB No.	PROVED 1004-0137 Iy 31, 2010
	WELL	COMPL	ETION	OR REC	OMPLET	ION RE	PORT			FD		ease Seria		
1a. Type of		Oil Well				Other			L O'LI VI				_	or Tribe Name
b. Type o	f Completion	_	lew Well	U Work	Over	Deepen	Plug	Back	🛛 Diff. R	Resvr.	7. U	nit or CA	Agreen	nent Name and No.
2. N	0	Othe	er		Contrat	DENISE	DINIZEDI	CON						
	RON U.S.A.		E	E-Mail: lea	kejd@chev	ron.com		1	14			ease Name		FEDERAL 001
3. Address	15 SMITH MIDLAND		705			3a. Ph:	Phone No 432-687	. (include -7375	area code)	)	9. A	PI Well N	0.	30-025-26256
4. Location	of Well (Re	port locati	ion clearly a	nd in accor	dance with F	ederal requ	uirements)	*			10. I	Field and I	Pool, or	Exploratory AMP NORTH
At surfa	ce 1980F	SL 660F	EL								11. 5	Sec., T., R	., M., o	r Block and Survey
At top p	rod interval	reported b	elow 198	0FSL 660	FEL						-	County or	2.0	19S R32E Mer NMF 13. State
At total		OFSL 66		ate T.D. R			16 Data	Constate	4		L	EA	1	NM
14. Date Sp 08/06/2		in	15. D	ate I.D. K	eached		D&.	Complete A X I 5/2015	a Ready to P	Prod.	17. 1		(DF, K 666 GL	B, RT, GL)* -
18. Total D	epth:	MD TVD	1300	0 1	9. Plug Back	k T.D.:	MD TVD	129	68	20. Dep	oth Bri	dge Plug S	Set:	MD 10925 TVD
21. Type E N/A	lectric & Oth	er Mecha	nical Logs R	Run (Submi	t copy of eac	h)				well cored DST run? tional Sur	l? vev?	No No No	C Ye	es (Submit analysis) es (Submit analysis) es (Submit analysis)
23. Casing an	nd Liner Rec	ord (Repo	ort all strings	s set in wel	1)		1000	10.4	2. 4	_	de	12.25		
Hole Size	Size/G	rade	Wt. (#/ft.)	Top (MD)	Botton (MD)	-	Cementer Depth		Sks. & Cement	Slurry (BB)		Cemen	t Top*	Amount Pulled
			i she		-		1				-		1	
East							13.39							
					-		12.2	1					1	
24. Tubing						20.0			-		_	28.4		20. 205
Size 2.875	Depth Set (N	1D) P 0687	acker Depth	(MD)	Size D	epth Set (N	MD) P	acker Dep	th (MD)	Size	De	epth Set (N	MD)	Packer Depth (MD)
25. Produci						26. Perfora	ation Reco	rd			_			and a start of the
	ormation	DTU	Тор		Bottom	Р	erforated		10010	Size	1	No. Holes		Perf. Status
B)	FCAMP, NO		-	10585	10610			0585 TO	10610	1	+		PRC	DUCING
C)						S								
D)	racture, Treat	ment Cer	mant Squaaz	e Etc	- Junit	wie i	18.14	Spice			_	122		Constant States
	Depth Interv		nent Squeez	c, Etc.		- Ale	Ar	nount and	Type of N	Iaterial	1			
100 C	1058	5 TO 10	610 ACIDIZ	E W/48 BB	LS 10% HCL	ACID, & F	RAC W/61	,710 LBS 2	20/40 DEL	TA FRAC	200		12	and the second second
	(X 8)					-					- 6	1		
1.1.5		1				178	18-18	10			1	235		
	ion - Interval	-	Test	Oil	Gas	Water	010		Gas		Deadurat	ion Method	100	
Date First Produced 08/31/2015	Test Date 08/31/2015	Hours Tested 24	Production	BBL 185.0	Gas MCF 404.0	BBL 31.0	Oil Gr. Corr. A		Gravit		Product		WS FR	OM WELL
Choke Size	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas:O Ratio	2189	Well S	etatus POW				
28a. Produc	tion - Interva	al B		1			1	Page 1						10 S
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gr.		Gas Gravit	y	Product	ion Method		
			24 Hr.	Oil	Gas	Water	Gas:0			tatus	-	1000	-	Carry Contra State

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

	luction - Inter	varc	S. C. S.	diameter and					and the second sec	and the second
ate First roduced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API	Gas Gravity	Production Method	
noke ze	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF		Gas:Oil Ratio	Well Status		
8c. Proc	luction - Inter	val D		-	-					The Ville
ate First oduced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF		Oil Gravity Corr. API	Gas Gravity	Production Method	
noke ze	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF		Gas:Oil Ratio	Well Status		
9. Dispo	sition of Gas	Sold, used	for fuel, ven	ted, etc.)		No.	1. 1.		6.46CM	San Share
30. Sumr Show tests,	nary of Porous all important	zones of p	orosity and o	contents the	reof: Corec ne tool ope	d intervals and all m, flowing and sh	drill-stem ut-in pressures		Formation (Log) Markers	<u>),</u>
1.4	Formation		Тор	Bottom		Descriptions	, Contents, etc.		Name	Top Meas. Dep
										8
2. Addit	ional remarks	(include p	lugging proc	eedure):						
-	loise it		lugging proc	edure):						
3. Circle 1. El	ional remarks e enclosed atta ectrical/Mecha ndry Notice fr	anical Logs	s (1 full set r	eq'd.)	1	<ol> <li>Geologic Re</li> <li>Core Analys</li> </ol>		3. DST 7 Other.	1 444	Directional Survey
3. Circle 1. El 5. Su	e enclosed atta ectrical/Mech ndry Notice fo	achments: anical Logs or plugging	s (1 full set r g and cement bing and atta	eq'd.) t verification ched inform <b>ronic Subn</b>	ation is co	6. Core Analy	ct as determine y the BLM W	7 Other: d from all availa ell Information	ble records (see attached in	
3. Circle 1. El 5. Su 4. I here	e enclosed atta ectrical/Mech ndry Notice fo	ichments: anical Logs or plugging t the forego	s (1 full set r g and cement ping and atta Elect	eq'd.) t verification ched inform ronic Subn	ation is co	<ol> <li>Core Analys</li> <li>mplete and correct</li> <li>27036 Verified b</li> </ol>	ct as determine y the BLM W C., sent to th	7 Other: d from all availa ell Information	ble records (see attached in System.	

\*\* ORIGINAL \*\*