Summit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103	
District I - (575) 393-6161			Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240				/
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-20577	-
District III - (505) 334-6178	1220 South St. Francis Dr. BBS		5. Indicate Type of Lease STATE FEE □	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	-
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	1 ./AN 2			
87505		1 2 2 2	016	
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APP	TICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PL LICATION FOR PERMIT" (FORM C-101) FO	UG BACK TO A	7. Lease Name or Unit Agreement Name Cotton Tree State SWD	
PROPOSALS.)	Cas Wall Cother Salt Water I	N1	8. Well Number 1	1
1. Type of Well: Oil Well				_
2. Name of Operator			9. OGRID Number 245872	
Judah Oil, LLC			10. Pool name or Wildcat	\dashv
3. Address of Operator P. O. Box 568, Artesia, NM 88211-0568		SWD; Bell Canyon- Cherry Canyon		
	1-0308		SWD, Bell Callyon- Cherry Callyon	_
4. Well Location				
Unit LetterF	_:1980feet from the	North line and	1980feet from theWestline	V
Section 32	Township 25S	Range 32E	NMPM Lea County	
制度发展的 (1995年)	11. Elevation (Show whether DR	RKB, RT, GR, etc.)		
12 Check	Appropriate Box to Indicate N	Jature of Notice	Report or Other Data	
12. Check	Appropriate Box to indicate is	diatare of riotice,	report of Other Bata	
NOTICE OF I	NTENTION TO:	OLID	OF OUT OF DEPONT OF	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒				
TEMPORARILY ABANDON CHANGE PLANS INT TO PA			(DM.)	
PULL OR ALTER CASING MULTIPLE COMPL P&A NR			P&A R	
		_	TAAR	
DOWNHOLE COMMINGLE		RBDMS _	IA	
CLOSED-LOOP SYSTEM				
OTHER:				_
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
		C. For Multiple Cor	npletions: Attach wellbore diagram of	
proposed completion or r	ecompletion.			
MIRU PU & test BOP				
Set 50 sx Class "C" Plug @ 4370'	-4170' and tag	11	1 00 1 01 1700	
Pump HLM 4170'-1300'	Spot 65	SX Class L	CMT at 1 200	
Set 65 sx Class "C" plug from 410	'-surface.		in the late	
Set 50 sx Class "C" Plug @ 4370'-4170' and tag Pump HLM 4170'-1300' Set 65 sx Class "C" plug from 410'-surface. Spot 65 sx Class "C" plug from 410'-surface. Cut off well head and weld on name plate 3' below surface - Notify OCD prior to covering plate Cut off anchors and clean location				
Cut off anchors and clean location				
Will maintain surface location for	possible truck unloading station and	tank facility.		
			28	
Spud Date:	Rig Release Da	ate:	* B	
I hereby certify that the information	on above is true and complete to the b	est of my knowledge	e and helief	_
Thereby certify that the information	if above is true and complete to the b	est of my knowledge	c and benef.	
	2/			
SIGNATURE	TITLE me	ember/manager	DATE_1/19/2016	
OIOINAT ORE	THEE MICE	emoer/manager	DITTE_1/11//2010	e.
Type or print name James B. ('amnanella F-mail address	jbc@judahoil.com	PHONE: 575-748-4730	
For State Use Only	L-man address.	Joe W Jacanon Com	111011B. <u>313-140-4130</u>	
To State Use Only				
APPROVED BY: Wash	Mitale TITLE Petr	oleum Ench S	pecialist DATE 01/25/2016 P	WX
Conditions of Approval (if any):	TILL I	11-19110		+()
Conditions of Approval (if any).			JAN 2 5 2016	-

Judah OIL, LLC

COTTON TREE STATE SWD #1

Proposed P/A

API # 30-025-20577

1980' FNL, 1980' FWL, SE/4NW/4, Sec 32, T-25-S, R-32-E, Lea County New Mexico

KB 3305' GL 3297

