Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	Form C-103 Revised August 1, 2011 WELL API NO. 30-005-60601 5. Indicate Type of Lease STATE FEE XX 6. State Oil & Gas Lease No.
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS, DIFFERENT RESERVOIR. USE "APPLIC, PROPOSALS.) 1. Type of Well: Oil Well X G	 7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit 8. Well Number #3 	
2. Name of Operator State of New Mexico formerly Cany	9. OGRID Number	
3. Address of Operator 811 South 1 st Street Artesia, N	10. Pool name or Wildcat Twin Lakes; San Andres (Assoc)	
4. Well Location Unit LetterJ: Section 25	1650feet from theSouth line and Township 8S Range 28E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM Chaves County
	The Devalor (Show whether DR, RRB, RT, OR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

P INT TO PA P P&A NR P&A R P RBDMS TA]]]		RT OF: TERING CASING □ ND A XX
Оіпен:		OTHER:	
13. Describe proposed or completed operations. (Clear			

of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	_TITLE	_DATE
Type or print name	E-mail address:	PHONE:
APPROVED BY: Maluhitaha	TITLE Petroleum Eng. Specialist	DATE 02/01/2016
Conditions of Approval (if any):	Q_	

Plugging Report TLSAU #3

1/18/2016 Cleared location and rigged up. Dug out cellar and replaced damaged well head. Used the well head from the TLSA #302. No tubing in the well. Will use tubing from the TLSA #119 for a work string. SION

1/19/2016 Moved work string to location. Picked up 5 ½" scrapper & RIH to 3535'. Had to work past tight spot From 1650' to 1720'. POOH with scrapper. RIH and set CIBP at 2500'. Hauled in fresh and brine. SION

1/20/2016 Established circulation. Had communication up 5 ½" X * 5/8" annulus. Closed Valve to annulus and circulated MLF. Had good circulation. Spotted 50 sx cement on to of CIBP. POOH with setting tool and picked up an AD-1 packer. Found holes in the 5 ½" casing from 188' to 564'. Pulled packer and perforated casing at 1000'. RIH and set packer at 658' and squeezed perfs with 35 sx cement. WOC. RIH with wireline to 1050'. No tag. POOH with wireline and picked up packer. Packer started dragging going in the hole @ 313'. Stacked out at around 400'. Worked packer free and POOH. Called OCD. Ran tubing open ended to 1067' and spotted 35 sx cement across perfs at 1000'.

1/22/2016 RIH with tubing. No tag at 1067'. POOH with tubing and RIH with wireline and tagged cement at 1627'. RIH with tubing and spotted 35 sx cement with CaCl at 1067'. WOC. RIH with wireline and tagged cement at 1563'. RIH with tubing and spotted another 35 sx cement at 1067'. SION

1/25/2016 RIH with wire line and tagged cement at 1278'. RIH with tubing to 1067' and spotted 35 sx cement with CaCl. WOC and tagged cement at 878'. Laid down remaining tubing. Established circulation and pumped cement down 5 %" casing to holes below 188' and up annulus to surface. Took 90 sx to circulate. Rigged down. Cut off wellhead. Cement was at surface on both strings of casing. Installed marker and cut off anchors.