Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135

	Expires:			
0	Serial No	J day	,	

5. Lease NMLC029405B

SUNDRY	NMLC029405B 6. If Indian, Allottee or Tribe Name							
Do not use thi abandoned we								
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well ☐ Gas Well ☐ Other ☐ Other					8. Well Name and No. RVBY Fed #2/ MultipleSee Attached			
2. Name of Operator CONOCOPHILLIPS COMPANY ✓ E-Mail: rogerrs@conocophillips.com					9. API Well No. 30-025-40394 / Multiple-See Attached			
3a. Address	3b. Phone No. (include area code) Ph: 432-688-9174			10. Field and Pool, or Exploratory MALJAMAR				
MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State			
Multiple-See Attached	'			LEA COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF N	NOTICE, RE	EPORT, OR OTHER	RDATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	☐ Acidize	□ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off		
	☐ Alter Casing	□ Frac	ture Treat	☐ Reclama	ation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	lete	Other		
☐ Final Abandonment Notice	☐ Change Plans☐ Convert to Injection☐	☐ Plug ☐ Plug	and Abandon	☐ Tempora	arily Abandon			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ConocoPhillips Company would like to remove RBP & DHC per DHC-DHC-4680. Attached is the current/proposed wellbore schematic, a procedure to perform work and the 2014 field study. NM OIL CONSERVATION ARTESJA DISTRICT JAN 2 5 2016 SEE ATTACHED FOR CONDITIONS OF APPROVAL RECEIVED 14. I hereby certify that the foregoing is true and correct.								
	nitted to AFMSS for proces	321592 verifie PHILLIPS CO sing by JENN	FER SÁNCHEZ o	n 11/17/2015	(16VAS0137SE)			
Name (Printed/Typed) RHONDA ROGERS			Title STAFF	REGULATO	RY TECHNICIAN			
Signature (Electronic S	Submission)		Date 10/27/20	015				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE			
_Approved By EDWARD FERNAN			TitlePETROLE	UM ENGINE	EER	Date 01/22/2016		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivinch would entitle the applicant to condu-	uitable title to those rights in the	Office Hobbs		Kz				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ke to any department or a	agency of the United		

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #321592 that would not fit on the form

Wells/Facilities, continued

 Agreement
 Lease

 NMLC029405B
 NMLC029405B

 NMLC029405B
 NMLC029405B


Well/Fac Name, Number RUBY FEDERAL 2 RUBY FEDERAL 2 **API Number** 30-025-40394-00-S1 30-025-40394-00-S2

Location Sec 17 T17S R32E SWSE 1140FSL 2310FEL Sec 17 T17S R32E SWSE 1140FSL 2310FEL

ConocoPhillips

CURRENT SCHEMATIC

RUBY FEDERAL 02



Ruby Federal 002 API#30-025-40394 DHC per DHC-4680

Project Scope


Justification and Background: Recompletion

This well was fracked in the yeso then the SA10, then Grayburg San Andreas 7 &9 & the final step is to comingle all the zones.

Well Service Procedure:

- 1) Verify anchors have been tested before RU
- 2) MI review JSA prior to RU
- 3) Nipple down well head
- 4) TOOH with rods and pump. Visually inspect rods COOH for pitting and wear, change out as needed
- 5) Nipple up BOP, & pull out of hole with tubing and stand tubing.
- 6) Pick up and run in hole with
 - a. 4-3/4" Bit
 - b. (6) 28lb/ft drill collars
 - c. 2-7/8" 6.5 lb/ft J-55 production tubing (casing size: 5-1/2, 17#)
 - d. To composite bridge plug 5304 ft. drill out plug with 10 ppg brine
- 7) 10ppg column of brine above the CBP and our weight of string should be more than enough to drill out plug safely
- 8) Continue running in the hole with bit and collars to PBD 7174'. Drill out any restrictions as necessary
- 9) Circulate on bottom until we get clean returns to surface
- 10) Once complete pull out of hole with bit, collars and tubing.
- 11) Run in hole with 173 joints of 2-7/8" 6.5# J-55 production tubing, set tubing anchor at 3402 ft (above all perfs), set seating nipple at 5159 ft.
- 12) While running in hole test the tubing to 5000 psi below the slips.
- 13) Nipple down the BOP & Run in hole with rods and pump
- 14) Nipple up the well head
- 15) Surface equip the well with existing BPU and operate at 7.8 SPM & 170" stroke (no change)
- 16) Space out pump; hang well on, test pump action.
- 17) Place well on test

Ruby Federal 002 API#30-025-40394 DHC per DHC-4680



Conditions of Approval Ruby Federal 2 30-025-40394 ConocoPhillips January 22, 2016

- 1. Operator procedure approved as written.
- 2. Surface disturbance beyond the existing pad must have prior approval.
- 3. Closed loop system required.
- 4. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. <u>Subsequent sundry and Completion report with well test and wellbore schematic required.</u>
- 6. Work to be completed in 90 days.

EGF 012216