Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I	Energy Minerals and Nathral Resolutces		WELL ADINO	Revised March 25,	1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-11603			
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of	of Leage		
District III	1220 South St. Francis Dr.			STATE [FEE 🛛	į
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM				o. State on & G	as Lease 140.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or	Unit Agreement Na	me:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Langlie Mattix Queen Unit		
PROPOSALS.) 1. Type of Well:						
Oil Well Gas Well Other				٠		
2. Name of Operator				8. Well No.		
KELTON OPERATING				. 10		
3. Address of Operator				9. Pool name or Wildcat		
1510 HERITAGE BLVD, ANDREWS, TEXAS 79714-2309				LANGLIE MATTIX;7RVRS-Q-GRAYBURG		
4. Well Location						
The second of th						
Unit Letter C: 520 feet from the NORTH line and 2090 feet from the						
<u>WEST</u> line						
Section 15	Township	25S	Range 37E	NMPM	I LEA Coun	ity
Section 13	10. Elevation (Show wh					
10. Elevation (Show memor DI, 1915) 111, 111, 111, 111, 111, 111, 111, 1						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSE					PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					ALTERING CASING	
		_		_		
TEMPORARILY ABANDON	☐ CHANGE PLANS		COMMENCE DR	RILLING OPNS.	PLUG AND	
	C	_	CASING TEST A	ND []	ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION CEMENT J						
	COM LETION					_
OTHER:			1	N WELL TO PRODU		<u> </u>
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of						
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or						
recompilation.						
and an agreement policy to the state of the						
10-1-02 MIRU PU. POOH with rods and tubing. Found holes in bottom 3 joints and pump bad. Pressure test tubing in hole. Land SN at 3340' with 106 joints 2 7/8" tubing. Run pump and rods. Hang well on and put on pump.						
3340 With 100 joints 2	7/8 tubing. Kun pump and	Tous. Hai	ng wen on and put	on pump.	150 12 17 28 29 30 3	2
11-7-02 Tested well for production for 24 hours – 1.4 BO, 21.6 BW, Gas – TSTM.						
$\mathcal{A}_{\mathbf{V}}$						
				120	- 12 3	Caj
				/ Pr. C.	Ď.	50/
					(c)	V/ -
					NO THE PARTY OF TH	
					and a second second	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE		DATE <u>7-17-</u>	2003			
SIGNATURE S. 1			President			
Type or print name C. Dale K	Celton			T	elephone No. 432-52	<u>4-64</u> 00
(This space for State use)			· · · · · · · · · · · · · · · · · · ·		JUL 22	
(1110 space for suite ase)	7.1.		מו וסדדם	EUM ENGINEER	JUL A	
APPPROVED BY	13 Rang	TITLE	I LINUL	EUITI EITUIN	DATE	
Conditions of approval, if any:				-		