UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS OCCUPANT Do not use this form for proposals to drill or to re-enter and spandoned well. Use form 3450-3 (ARD) for such and the second state of the sec

5. Lease Serial No. NMLC031695B

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse 12 3 2010					7. If Unit or CA/Agreement, Name and/or No. W			
Type of Well			8. Well Name and No./ WARREN UNIT 84					
Name of Operator CONOCOPHILLIPS COMPAN	NT 9. A		. API Well No. 30-025-27105-00-S1					
3a. Address	o. (include area code) 63-3355		10. Field and Pool, or Exploratory WARREN					
MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)								
				unty or Parish, and State				
Sec 33 T20S R38E NENW 66	OFNL 1920FWL /				LEA CO	UNTY, NM		
12. CHECK APPE	ROPRIATE BOX(ES) TO IN	DICATE	NATURE OF 1	NOTICE, REPO	ORT, OR	OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION								
☑ Notice of Intent	☐ Acidize	□ Deepen		☐ Production (Start/R		INT TO PA	×	
	☐ Alter Casing	☐ Fracture Treat		☐ Reclamation		P&A NR		
☐ Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recomplete		P&A R		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon		☐ Temporarily Aband				
	☐ Convert to Injection	☐ Plug Back		□ Water Disposal				
testing has been completed. Final Abdetermined that the site is ready for final Abdetermined The Section 1. 1) MIRU, NDWH, NUBOP. PC 2) RIH WL - Set 5-1/2" CIBP (3) RIH Tbg Tag BP (3) 4150' - 35 5) Spot 70sx cmt (3000' - 25 6) Spot 25sx cmt (3000' to su 8) POOH, fill wellbore. RDMO	inal inspection.) OOH w/ Prod Equip Sept 2 2 4900' Circ hole w/ MLF. Cap BP w/ 2 500'. WOC-Tag 520'. WOC-Tag 597'. WOC-Tag rface.	35 5x 25sx cmt	on GBP a	F 5709 +	535	O (Gloriettana)	5405)	
SEE ATTACHE								
	SEE ATTACHED FOR							
LAC COAS Attack	CONDITIONS OF APPROVAL							
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #3355: For CONOCOPHIL mitted to AFMSS for processin	LIPS CO	d by the BLM We MPANY, sent to t	II Information Sy the Hobbs	stem			
Name (Printed/Typed) GREG BRYANT			Title AGENT					
Signature (Electronic Submission)			Date 04/05/2016					
	THIS SPACE FOR F	EDERA	L OR STATE	OFFICE USE				
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Title Eng Date \$18/16 Office CFO					
Title 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent s					o any depar	rtment or agency of the Unite	d	

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

FOR RECORD ONLY
MW/OCD 05/23/2014

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU / Permian Operations

Date March 21, 2016 RKB @ _ 3525 DF @ GL @ 3513 Subarea Hobbs Lease & Well No. Warren Unit # 84 Legal Description 660' FNL & 1920' FWL, Sec. 33, T20S, R38E, UL "C 12-1/4° Hole County State New Mexico Warren Blinebry / Tubb O&G Field 9/5/81 Spot 35sx cmt @ 300'-3' Date Spudded Rel. Rig: 8/9/81 API Number 30-025-27105 Temporarily Abandoned Status LC-031695B Lease Serial No. Stimulation History: 1 hs Max Max Interval Date Туре Gals Sand Press ISIP Rate Down 10/1/1981 Perforate 5792-6078, 18 holes 5792-6078 10/3/1981 15% NEFE HCI 1,500 2350 8-5/8" 24# K-55 ST&C @ 1447" 10/31/1981 40# Gelled TFW 86,000 111,000 Cmt'd w/ 696 sx, circ 100 sx 4/26/1993 Uneconomical to produce, shut in TOC @ Surface 6/6/1996 CIBP set @ 5740', TA'd Top Sait @ 1500' 2/25/2008 Log well from 5740' to 3500', tag CIBP @ 5740' Spot 25sx cmt @ 1550'-1397' - Tag 2/25/2008 Dump 35' cmt on top of CIBP; TOC @ 5705' 2/26/2008 Perforate 5270-5280; 5196-5206; 5082-5092; & 5000-5015 w/ 2 SPF 5000-5280 2/27/2008 15% Ferchek 4500 3059 1671 8 0 5000-5280 2/28/2008 GW 61,600 92,000 Set RBP @ 4951'; circulate packer fluid 11/4/2008 Retrieve RBP @ 4951' 1/28/2011 Base Salt @ 2570' Spot 55sx cmt @ 3000'-2520' - Tag Spot 70sx cmt @ 4150'-3500' - Tag DV Tool @ 3814' Spot 25sx cmt @ 4900'-4750' Set CIBP @ 4900 Lower San Andres 5000-5015 5082-5092 5196-5206 Pot 35 5x @ 5705-5350 5270-5280 Formation Tops: Rustler 1410 Penrose 3695 Salado 1500 Grayburg 3880 CIBP @ 5740'; TOC @ 5705' Tansill 2570 San Andres 4112 Blinebry Vates 2610 Gloneta 5405 5792 5803 5826 5833 5862 == Seven Rivers 2990 Blinebry Mkr 5777 5865 5871 5875 5939 5943 == Queen 3550 Blinebry Mkr 5852 5949 6015 6021 6026 6031

==

PETD

TD

6123

6170

6038 3071 6078 - 18 hicles

5-1/2" 15.5# K-55 LT&C @ 6170"

1st Stg Cmt 850 sx Class C, circ 100 sx

2nd Stg Cmt 1500 sx Class C, circ 100 sx

7-7/8" Hole

TOC @ Surface

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU / Permian Operations

Date: March 21, 2016 Subarea Hobbs Lease & Well No. Warren Unit # 84 660' FNL & 1920' FWL, Sec. 33, T20S, R38E, UL °C Legal Description New Mexico County State Field Warren Blinebry / Tubb O&G 9/5/81 Date Spudded 8/9/81 Rel. Rig API Number 30-025-27105 Status Temporarily Abandoned LC-031695B Lease Serial No Stimulation History: Lbs. Max Max ISIP Rate Down Date Gals Press Interval Type Sand Perforate 5792-6078, 18 holes 10/1/1981 10/3/1981 2350 5792-6078 15% NEFE HCI 1.500 10/31/1981 40# Gelled TFW 86,000 111.000 4/26/1993 Uneconomical to produce, shut in CIBP set @ 5740', TA'd 6/6/1996 Log well from 5740', 1A'd Log well from 5740' to 3500'; tag CIBP @ 5740' Dump 35' cmt on top of CIBP; TOC @ 5705' Perforate 5270-5280; 5196-5206; 5082-5092; & 5000-5015 w/ 2 SPF 2/25/2008 2/25/2008 2/26/2008 5000-5280 2/27/2008 15% Ferchek 4500 3059 1671 B O 5000-5280 2/28/2008 GW 61,600 92.000 11/4/2008 Set RBP @ 4951'; circulate packer fluid 1/28/2011 Retrieve RBP @ 4951' Formation Tops: 1410 Penrose Rustler 3695 Salado 1500 Grayburg 3880 San Andres 2570 Tansill 4112

Glorieta

Blinebry Mkr

Blinebry Mkr

Yates

Queen

Seven Rivers

2610

2990

3550

RKB @ 3526'
DF @ 3525'
GL @ 3513' 12-1/4" Hole 8-5/8" 24# K-55 ST&C @ 1447" Cmt'd w/ 696 sx, circ 100 sx TOC @ Surface Top Salt @ 1500' Base Salt @ 2570" DV Tool @ 3814" Lower San Andres 5000-5015 5082-5092 5196-5206 5270-5280 CIBP @ 5740'; TOC @ 5705' Blinebry 5792 5803 5826 5833 5862 5865 5871 5875 5939 5943 5949 6015 6021 6026 6031 6038 3071 6078 - 18 hioles

7-7/8" Hole

PBTD

TD

6123

6170

5-1/2" 15.5# K-55 LT&C @ 6170"

1st Stg Cmt 850 sx Class C, circ 100 sx 2nd Stg Cmt 1500 sx Class C, circ 100 sx TOC & Surface 5405

5777

5852

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass Environmental Protection Specialist 575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979