

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

**SUBMIT IN TRIPLICATE- Other instructions on reverse side.**1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator  
Xeric Oil & Gas Corporation3a. Address  
PO Box 352 Midland, Tx 797023b. Phone No. (include area code)  
432-683-3171

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

785' FNL &amp; 1980' FWL

Sec. 33-25S-37E

5. Lease Serial No.

LC-054667

6. If Indian, Allottee or Tribe Name

7. If Unit or CA Agreement, Name and/or No.

SW876

8. Well Name and No.

Crosby Deep #4

9. API Well No.

30-025-25985

10. Field and Pool, or Exploratory Area

Crosby Fusselman

11. County or Parish, State

Lea Co., NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. MIRU Pulling unit
2. Circulate hole w/9# mud
3. Set 50 sx plug @ 8700' & tag
4. Set 50 sx plug @ 4000'
5. Cut 5 1/2" casing at free point (+/- 2000'-3000') & lay down
6. Set stub plug 50' in and out of 5 1/2" stub & tag
7. Set 50 sx plug @ 1500'
8. Set 10 sx plug @ 40'
9. Install dry hole marker & restore location

**THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.**

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Glenda Hunt

Title Production Analyst

Signature

*Glenda Hunt*

Date 1/30/06

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

*Les Babjak*

Title

P.E.

Date

5/30/06

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43, U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW

cc: OGD