Submit 3 copies to Appropriate District Office

State of New Mexico

Form C-103 Revised 1-1-8

District Office	Energy, Minerals and Natur	ai re	sources Department	Revised '	1-1-89
OIL CONSERVATION DIVISION			WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240			30-025-30829		
Santa Fe, Now Meyico 87504-2088			5. Indicate Type of Lease		
P.O. Box Drawer DD, Artesia, NW 66210				E 🗀	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil / Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS				B-9613	all v
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO			7. Lease Name or Unit Agreement Name	10 mg	
	RVOIR. USE "APPLICATION F C-101) FOR SUCH PROPOSAL		ERMI	WEST DOLLARHIDE DRINKARD UNIT	
1. Type of Well: OIL GAS	2-101)1 OK ODOITI NOT OOAL				
WELL WELL	L U OTHER				
2. Name of Operator CHEVRON USA INC				8. Well No. 107	
				9. Pool Name or Wildcat	
3. Address of Operator 15 SMITH RD, MIDLAND, TX 79705				DOLLARHIDE TUBB DRINKARD ABO	
4. Well Location					
Unit Letter :	1435 Feet From The	SOUT	H Line and 1211	Feet From TheEASTLine	
Section 32 Township 24S Range 38E NMPM LEA COUNTY					
10. Elevation (Show whether DF, RKB, RT,GR, etc.)					
	Ex	1110,	1(1,01(, 610.)		44
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTIO	ON TO:		SU	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OP	ERATION PLUG AND ABANDONMENT	
PULL OR ALTER CASING		_	CASING TEST AND CEMEN	NT JOB	
OTHER:			OTHER:	TBG LEAK-INSPECT	V
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-13-06: NMOCD IDLE WELL. MIRU. TIH W/RODS. TIH W/3/4" RODS. TAC DID NOT RELEASE. 2-14-06: TBG PARTED. SET TBG DN ON FISH. TIH W/OVERSHOT & NEW RODS. TAG @ 5175. TIH W/NEW COUPLING. TAG UP @ 5193. 2-15-06: LD 20 JTS. 2-16-06: TIH W/OS W/GRAPPLE, BMPR SUB & TBG. TAG FISH @ 5259. WORK OS DN TO 5263. TIH W/OS W/MILL CONTROL. 2-17-06: TAG FISH @ 5263. LATCH ON @ 5275. FISH PARTED. TAG TOP OF FISH @ 5298 & MILL OVER FISH TO 5295 & LATCH ON FISH. FISH PARTED @ 72000#. 2-18-06: TOO FISH @ 6144. TOP OF RODS @ 5850. TAG UP @ 5850. SWALLOW RODS TO 5966. PUH TO 5200. 2-20-06: TIH W/OVERSOCKET. TAG @ 5976. TOOK DOWN TO 6000*. TOP OF TAC @ 6140. TIH W/CATCHER SHOE, 1 JT 4 1/2" WP, JARS, DC'S & TBG. 2-21-06: TAG FILL @ 6000. C/O FR 6000 TO TAC @ 6160. MILL ON TAC 1 HR. PUH TO 5970. 2-22-06: TIH W/SHOE TO 6160. MILL 5 HW/SHOE TO 6160. MILL 5 HW/SHOE TO 6162. MILL OVER TAC TO 6175. PUH TO 5970. 2-27-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 2-28-06: TIH W/FLUTED SHOE, GRAPPLE, WP, JARS, & DC'S TO 5970. 3-07-06: TAG @ 6218. MILL OVER TBG TO 6225. FELL OUT @ 6225. TOOK SHOE D					
Thereby certify that the intermation above is true and complete to the best of my knowledge and belief.					
SIGNATURE WWW M		Regu	latory Specialist	DATE <u>3/20/2006</u>	
TYPE OR PRINT NAME D	enise Pinkerton			Telephone No. 432-687-	7375
	<u> </u>				

APPROVED Have W. W. CONDITIONS OF APPROVAL, IF ANY: