Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District 1 - (575) 393-6161	gy, Minerals and Natural Reso	WELL API NO.	Revised August 1, 2011
Dietrict 11 - (\$75) 749-1293	Ch .	20 025 07270	
811 S. First St., Artesia, NM 88210 25 OIL	CONSERVATION DIVIS	5. Indicate Type of 1	Lease
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE	FEE 🛛
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas L	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DRI DIFFERENT RESERVOIR, USE "APPLICATION FOR	ILL OR TO DEEPEN OR PLUG BACK	North Hobbs (G/SA)	nit Agreement Name Unit
PROPOSALS.)		Section 19 8. Well Number: 41	1
	Other: Injector		
Name of Operator Occidental Permian Ltd.		9. OGRID Number:	
3. Address of Operator		10. Pool name or W	ildcat Hobbs (G/SA)
HCR I Box 90 Denver City, TX 79323			
4. Well Location			
	from theNorth line and		
Section 19	Township 18S Range		Lea County
	tion (Show whether DR, RKB, RT	GR, etc.)	
3679' DF			
12 (1-1-4	. D I E N	N. d. B. d. Od. B.	
12. Check Appropria	te Box to Indicate Nature of	Notice, Report of Other Da	ata
NOTICE OF INTENTIO	NTO:	SUBSEQUENT REPO	ORT OF:
18 1940 18 19 19 19 19 19 19 19 19 19 19 19 19 19			LTERING CASING
TEMPORARILY ABANDON CHANGE	PLANS COMMI	ENCE DRILLING OPNS. P	AND A
PULL OR ALTER CASING MULTIPL	E COMPL CASING	S/CEMENT JOB	
DOWNHOLE COMMINGLE			
	G OTHER		
			the state of the s
OTHER:	tions (Clearly state all pertinent		including estimated date
13. Describe proposed or completed opera	tions. (Clearly state all pertinent	details, and give pertinent dates,	
	tions. (Clearly state all pertinent	details, and give pertinent dates,	
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 	tions. (Clearly state all pertinent RULE 19,15.7,14 NMAC. For M	details, and give pertinent dates, ultiple Completions: Attach wel	lbore diagram of
Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit	tions. (Clearly state all pertinent RULE 19,15.7,14 NMAC. For M	details, and give pertinent dates, ultiple Completions: Attach wel	lbore diagram of
Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly	tions. (Clearly state all pertinent RULE 19,15.7,14 NMAC, For M	details, and give pertinent dates, ultiple Completions: Attach wel	lbore diagram of n to use
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF	tions. (Clearly state all pertinent RULE 19.15.7.14 NMAC. For M Du	details, and give pertinent dates, ultiple Completions: Attach well aring this procedure we place closed-loop system with a	lbore diagram of n to use a steel
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF injection assembly consisting of two packets.	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du With reconfigured the rs. Upper packer tail	details, and give pertinent dates, ultiple Completions: Attach well aring this procedure we play closed-loop system with a lake and haul contents to the	n to use a steel e required
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du I with reconfigured the rs. Upper packer tailer at 4250'. Intent is to	details, and give pertinent dates, ultiple Completions: Attach well aring this procedure we place closed-loop system with a	n to use a steel e required
Of starting any proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RII-injection assembly consisting of two packet expected to be set at 3929' and lower packet.	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du I with reconfigured the rs. Upper packer tailer at 4250'. Intent is to	details, and give pertinent dates, ultiple Completions: Attach well aring this procedure we play closed-loop system with a lake and haul contents to the	n to use a steel e required
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RII-injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du I with reconfigured the rs. Upper packer tailer at 4250'. Intent is to	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a land haul contents to the sposal per ODC Rule 19.15	n to use a steel e required 5.17
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RIF injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze Return well to injection. Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du I with reconfigured the rs. Upper packer tailer at 4250'. Intent is to	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a land haul contents to the sposal per ODC Rule 19.15 Condition of Approval:	n to use a steel required 5.17
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze 4. Return well to injection. 5. 6.	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured the rs. Upper packer er at 4250'. Intent is to ad perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a lake and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 in the latest states and the latest states are latest states.	n to use a steel e required 5.17 notify
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RII-injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze Return well to injection. Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured the rs. Upper packer er at 4250'. Intent is to ed perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a land haul contents to the sposal per ODC Rule 19.15 Condition of Approval:	n to use a steel e required 5.17 notify
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RIF injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze Return well to injection. Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured the rs. Upper packer er at 4250'. Intent is to ad perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a lake and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 in the latest states and the latest states are latest states.	n to use a steel e required 5.17 notify
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RII-injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze Return well to injection. Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured the rs. Upper packer er at 4250'. Intent is to ed perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a lake and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 in the latest states and the latest states are latest states.	n to use a steel e required 5.17 notify
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RII-injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8.	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured rs. Upper packer er at 4250'. Intent is to ed perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a large and haul contents to the sposal per ODC Rule 19.15. Condition of Approval: OCD Hobbs office 24 brior of running MIT Test	n to use a steel e required 5.17 notify
 Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. MIRU Pulling Unit POOH with injection assembly After testing casing and squeeze holes, RII-injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze Return well to injection. Return well to injection. 	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured rs. Upper packer er at 4250'. Intent is to ed perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a large and haul contents to the sposal per ODC Rule 19.15. Condition of Approval: OCD Hobbs office 24 brior of running MIT Test	n to use a steel e required 5.17 notify
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RII-injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8.	tions. (Clearly state all pertinent RULE 19,15.7.14 NMAC. For M Du the with reconfigured rs. Upper packer er at 4250'. Intent is to ed perforations.	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a large and haul contents to the sposal per ODC Rule 19.15. Condition of Approval: OCD Hobbs office 24 brior of running MIT Test	n to use a steel e required 5.17 notify
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RII-injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8. Spud Date:	Clearly state all pertinent RULE 19,15.7.14 NMAC. For M With reconfigured the rs. Upper packer er at 4250'. Intent is to ed perforations. Rig Release Date:	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a land haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 brior of running MIT Test	n to use a steel e required 5.17 notify
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeezed. Return well to injection. 5. 6. 7. 8. Spud Date: I hereby certify that the information above is true.	Clearly state all pertinent RULE 19,15.7.14 NMAC. For M With reconfigured the rs. Upper packer er at 4250'. Intent is to ed perforations. Rig Release Date: P Rig Release Date:	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a rink and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 I rior of running MIT Test knowledge and belief.	n to use a steel e required 5.17 notify nours t & Chart
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF-injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8. Spud Date: I hereby certify that the information above is true. SIGNATURE Type or print name Rick Reeves	Clearly state all pertinent RULE 19,15.7.14 NMAC. For M With reconfigured the rs. Upper packer er at 4250'. Intent is to ed perforations. Rig Release Date:	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a rink and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 I rior of running MIT Test knowledge and belief.	n to use a steel e required 5.17 notify nours t & Chart
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RIF injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeezed. Return well to injection. 5. 6. 7. 8. Spud Date: I hereby certify that the information above is true.	Du with reconfigured the reconfigured th	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a large and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 in a large and belief. ATE 7/21/6	n to use a steel e required 5.17 notify nours t & Chart
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RII-injection assembly consisting of two packet expected to be set at 3929' and lower packet isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8. Spud Date: I hereby certify that the information above is true. Type or print name Rick Reeves For State Use-Only	Du with reconfigured the reconfigured th	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a large and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 in a large and belief. ATE 7/21/6	n to use a steel e required 5.17 notify nours t & Chart
13. Describe proposed or completed opera of starting any proposed work). SEE F proposed completion or recompletion. 1. MIRU Pulling Unit 2. POOH with injection assembly 3. After testing casing and squeeze holes, RII-injection assembly consisting of two packe expected to be set at 3929' and lower packe isolate between packers previously squeeze 4. Return well to injection. 5. 6. 7. 8. Spud Date: I hereby certify that the information above is true. SIGNATURE Type or print name Rick Reeves For State Use-Only	Du with reconfigured the reconfigured th	details, and give pertinent dates, ultiple Completions: Attach well ring this procedure we plate closed-loop system with a rink and haul contents to the sposal per ODC Rule 19.15 Condition of Approval: OCD Hobbs office 24 I rior of running MIT Test knowledge and belief.	n to use a steel e required 5.17 notify nours t & Chart