

Submit 1 Copy to Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06785
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name S. J. Sarkeys B
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☒ Other

2. Name of Operator
Acoma Oil Corp.

3. Address of Operator
6300 Ridglea Place, Ste. 904, Ft. Worth, Texas 76116

4. Well Location
Unit Letter **B** : **660** feet from the **N** line and **1980** feet from the **E** line
Section **26** Township **21-S** Range **37-E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3381 GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING/CEMENT JOB

OTHER: ☐

INT TO PA ☒
P&A NR
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @ 6100'. Spot 25sx cement on CIBP

1A Set CIBP @ 5700'. Circulate hole w/ mud laden fluid. Spot 20²⁵ sx cement on top of CIBP.

2. Perf & Sqz 45 sx @ 3960-3860. WOC & Tag (San Andres)

3. Perf & Sqz 45 sx @ 3710-3610. (Grayburg) WOC/TAG

4. Perf & Sqz 100 sx @ 2830-2530. WOC & Tag (shoe and btm of salt)

5. Perf & Sqz 45 sx @ 1425-1325. (salt) *WOC/TAG

6. Perf & Sqz 75 sx @ 312-212. WOC & Tag (shoe) *open bradenhead valves

7. Perf & Sqz 75 sx @ 100-surface. *

8. Cut off wellhead and weld on Dry Hole Marker.

verify cement to surface all strings

13 3/8 x 9 5/8
9 5/8 x 5 1/2

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING
PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bernie Montgomery TITLE Agent DATE 8-2-16
Type or print name Bernie Montgomery E-mail address: bern@bcmadassociates.com PHONE: 932-580-7161
For State Use Only
APPROVED BY: Mark Whitaker TITLE Petroleum Engr. Specialist DATE 8-4-2016
Conditions of Approval (if any):

LAKELAND PETROLEUM CORPORATION

P. O. BOX 3500

JE 6-6812

FORT WORTH 5, TEXAS

PROPOSED BLINEBRY OIL - TUBS GAS DUAL

S.J. SARKEYS 1-B SEC 26-T215-R37E

