HOBBS OCD DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS SEP 0 6 204 bot use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. RECEIVEMENT IN TRIPLICATE - Other instructions on reverse side.		5. Lease Serial No. NMNM122622	2		
		6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name		
		7. If Unit or CA/Ag	<ul> <li>7. If Unit or CA/Agreement, Name and/or No.</li> <li>8. Well Name and No.</li> <li>ENDURANCE 36 STATE COM 704H</li> </ul>		
Oil Well Gas Well Other     Contact: STAN WAGNER     Contact: STAN WAGNER     Contact: STAN WAGNER     /		9. API Well No.	9. API Well No. 30-025-43015-00-X1		
3a. Address	ORATEDE-Mail: stan_wagne	3b. Phone No. (include area code			
MIDLAND, TX 79702		Ph: 432-686-3689		WC025G09S263327G-UP WOLFCAM	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description,			11. County or Paris	11. County or Parish, and State	
Sec 36 T26S R33E Lot 4 360FSL 1020FWL			LEA COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
	Acidize	Deepen	□ Production (Start/Resume)	U Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	□ Reclamation	U Well Integrity	
Subsequent Report	Casing Repair	New Construction	□ Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	Drilling Operations	
	Convert to Injection	Plug Back	□ Water Disposal		
<ol> <li>Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f</li> </ol>	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation res bandonment Notices shall be file	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec	A. Required subsequent reports shall completion in a new interval, a Form	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pe VVL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000?. Unable to estat 8/24/2016 RIH with perf guns Pulled to 16,467?, fired guns,	ally or recomplete horizontally, j rk will be performed or provide operations. If the operation res bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD 0 failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted blish circulation. on coiled tubing. Perforat no communication. Pulled	give subsurface locations and meas the Bond No. on file with BL/M/BI ults in a multiple completion or rea d only after all requirements, inclu ?d well ~250? of the origina 5-1/2" 23# HCP-110 VAM S planned TD). < tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, red casing at 16,600?, no co	A. Required subsequent reports shall per A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect b. POOH. 18,500?, 18,300? mmunication.	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pt WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000? Unable to estat 8/24/2016 RIH with perf guns Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is Comm	ally or recomplete horizontally, j rk will be performed or provide d operations. If the operation res- bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD of failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled s true and correct. Electronic Submission #3 For EOG RESOU	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rea d only after all requirements, inclu ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM S planned TD). c tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no	A. Required subsequent reports shall pe A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect s. POOH. 18,500?, 18,300? mmunication. communication. communication.	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pr WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000?. Unable to estat 8/24/2016 RIH with perf guns, Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is	ally or recomplete horizontally, j rk will be performed or provide d operations. If the operation res- bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD of failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled s true and correct. Electronic Submission #3 For EOG RESOU	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rea d only after all requirements, inclu ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM S planned TD). c tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no	A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete lly planned TD). SG casing. Stuck casing d to disconnect s. POOH. 18,500?, 18,300? mmunication. communication.	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pt WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000? Unable to estat 8/24/2016 RIH with perf guns Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is Comm	ally or recomplete horizontally, j rk will be performed or provide (operations. If the operation res- bandonment Notices shall be file inal inspection.) 2?, MD / 12,588? TVD (TD of failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled s true and correct. Electronic Submission #3 For EOG RESOU nitted to AFMSS for process (GNER	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rea d only after all requirements, inclu ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM S planned TD). c tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no	aured and true vertical depths of all pe A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect s. POOH. 18,500?, 18,300? mmunication. communication. communication. ell Information System to the Hobbs on 08/29/2016 (16JAS0511SE) LATORY ANALYST	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pr WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000?. Unable to estat 8/24/2016 RIH with perf guns, Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is Name (Printed/Typed) STAN WA	ally or recomplete horizontally, j rk will be performed or provide d operations. If the operation res- bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD of failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled s true and correct. Electronic Submission #3 For EOG RESOU nitted to AFMSS for process (GNER	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or red d only after all requirements, inclu ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM S planned TD). < tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no 499176 verified by the BLM We RCES INCORPORATED, sent sing by JENNIFER SANCHEZ Title REGU	A. Required subsequent reports shall pe A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect S. POOH. 18,500?, 18,300? mmunication. communication. communication. ell Information System to the Hobbs on 08/29/2016 (16JAS0511SE) LATORY ANALYST 2016	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pe WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000?. Unable to estat 8/24/2016 RIH with perf guns, Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is Signature (Electronic S	ally or recomplete horizontally, j rk will be performed or provide operations. If the operation res- bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD ol failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled strue and correct. Electronic Submission #3 For EOG RESOU nitted to AFMSS for process (GNER Submission) THIS SPACE FO	give subsurface locations and meass the Bond No. on file with BLM/BI ults in a multiple completion or rea d only after all requirements, inclu ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM 3 planned TD). < tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no 449176 verified by the BLM Wa RCES INCORPORATED, sent sing by JENNIFER SANCHEZ Title REGU Date 08/26/2 R FEDERAL OR STATE	A. Required subsequent reports shall pe A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect S. POOH. 18,500?, 18,300? mmunication. communication. communication. ell Information System to the Hobbs on 08/29/2016 (16JAS0511SE) LATORY ANALYST 2016	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once ed, and the operator has	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8/16/2016 TD?d well at 19,65 Called TD early due to DH too 8/19/2016 RIH with 5-1/2" 23# @ 18,955' MD (697? from TD 8/20/2016 RIH w/ Tractor & pr WL from Tractor. TOH to 222 8/22/2016 RU coiled tubing un Recovered 100% of fish. 8/23/2016 RIH with perf guns and 18,000?. Unable to estat 8/24/2016 RIH with perf guns, Pulled to 16,467?, fired guns, 14. I hereby certify that the foregoing is Name (Printed/Typed) STAN WA	ally or recomplete horizontally, j rk will be performed or provide operations. If the operation res- bandonment Notices shall be file inal inspection.) 2? MD / 12,588? TVD (TD of failure. # HCP-110 VAM Top HT 8 , ~947? from the originally erf guns on wireline - stuck ? and dropped tractor and nit. RIH with fishing tools. on coiled tubing attempted olish circulation. on coiled tubing. Perforat no communication. Pulled s true and correct. Electronic Submission #3 For EOG RESOU nitted to AFMSS for process (GNER Submission) THIS SPACE FO	give subsurface locations and meass the Bond No. on file with BLM/BI ults in a multiple completion or rea d only after all requirements, inclue ?d well ~250? of the origina a 5-1/2" 23# HCP-110 VAM S planned TD). a tools @ 16,694'. Attempte I tools. Fished WL tractor and tools d to punch holes at 18,700?, ed casing at 16,600?, no co d to 16,130?, fired guns, no casing at 16,600?, no co d to 16,130?, fired guns, no casing by JENNIFER SANCHEZ Title REGU Date 08/26/2 R FEDERAL OR STATE	A. Required subsequent reports shall per A. Required subsequent reports shall completion in a new interval, a Form ding reclamation, have been complete Ily planned TD). SG casing. Stuck casing d to disconnect s. POOH. 18,500?, 18,300? mmunication. communication. communication. ell Information System to the Hobbs on 08/29/2016 (16JAS0511SE) LATORY ANALYST	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	

## Additional data for EC transaction #349176 that would not fit on the form

## 32. Additional remarks, continued

Pulled to 15,760?, fired guns, established circulation. 8/25/2016 RIH with jet cutter on coiled tubing. Cut casing at 13,600? MD. POH and lay down casing.

Plan Forward:

1. Will perform an ?open hole sidetrack? at ~12,800? MD/12,585? TVD (at the base of the curve)

Win periodic and ropen hole side factor at 12,000 miles 12,0000 miles 12,000 miles 12,000 miles 12,000 miles 12,000 miles