

Submit 1 Copy to Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-40933 ✓
1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD		5. Indicate Type of Lease STATE ☒ FEE ☐ ✓
2. Name of Operator COG Operating LLC		6. State Oil & Gas Lease No.
3. Address of Operator 600 W Illinois, Midland, TX 79701		7. Lease Name or Unit Agreement Name Wild Cobra 1 State SWD ✓
4. Well Location Unit Letter C : 660 feet from the N line and 1980 feet from the W line Section 1 Township 19S Range 34E NMPM County Lea ✓		8. Well Number 1 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3962 GR		9. OGRID Number 229137 ✓
		10. Pool name or Wildcat SWD; Delaware ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK	INT TO PA Pm x P&A NR _____ P&A R _____
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE ☐			
OTHER: ☐		OTHER: _____	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 7" CIBP @ 6610'. Circ hole w/ MLF. Spot 25 sx cmt @ 6610-6510. **Pressure test csg.**
2. Spot 25 sx cmt @ 5556-5456. Tag (DV tool)
3. Spot 65 sx cmt @ 3570-3225. Tag (9 5/8 shoe and btm of salt)
4. Spot 45 sx cmt @ 2025-1825. Tag (top of salt and 13 3/8 shoe)
5. Spot 25 sx cmt @ 100-surface.
6. Cut off wellhead and weld on Dry Hole Marker. **(URRIGHT MKR)**

**VERIFY CMT TO
SURFACE ALL STRINGS**

**NOTIFY OCD 24 HOURS PRIOR TO BEGINNING
PLUGGING OPERATIONS**

Spud Date: _____

Rig 1 _____

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 10-17-16
Type or print name Ben Montgomery E-mail address: Benm@bcrmandassociates.com PHONE: 432-580-7161
For State Use Only

APPROVED BY: Maheshwari TITLE Petroleum Engr. Specialist DATE 10/17/2016
Conditions of Approval (if any):

mw

30-025-40933

Wild Cobra 1 State SWP 1
660' FNL, 1980' FWL
C-1-19s-34e
Lea, NM

Zepo: 17' AGL
KB: 3979'
GL: 3962'

SWD-1377
6300-7750'
Max Press 1260psi

17 1/2"

12 1/4"

8 3/4"

13 3/8" / 54.5 / J55 / LTC @ 1072' 1025sx"C" 4% gel + 250sx"C" (circ 2A 5x)

9 5/8" / 36 / J55 / LTC @ 3519' 800sx"C" 4% gel + 250sx"C" (circ 9 5/8x)

DV/ECP 5506'

6640

Delaware Sand

7690'

7" / 26 / J55 / LTC @ 8000'

8000'

1st: 400sx Super C (circ 166sx)

2nd: 500sx HLC + 100sx"C" (circ 112sx)

30-022-40933

Wild Cat 1 Spot 510' - 1
660' P/L, 1800' P/L
C-1-14x-37x
LWC, NM

3rd: 17' AGL
KB: 3179'
GL: 3162'

5. Spot 25 sx cmt @ 100'-Surface

SVD-1377
6300-7750'
Max Press 1260psi

4. Spot 45 sxs smt @ 2025-1825' TAG (13 3/8 shoe, top of Salt)

13 3/8" / 59.5 / 355 / LTC @ 1872' 1000sx"C" 47gal + 250sx"C" (Cmt 20%)

3. Spot 65 sxs cmt @ 3570-3225' TAG (9 5/8 shoe, btm of Salt)

9 5/8" / 36 / 355 / LTC @ 3519' 1000sx"C" 47gal + 250sx"C" (Cmt 20%)

2. Spot 25 sxs cmt @ 5556-5456' *TAG (DV Tool)

1. Set 7" CIBP w/ 25 sxs cmt @ 6610-6510'

Delaware Sand

1st: 400sx Super C Cmt 100%

2nd: 500sx HLC + 100sx"C" (Cmt 1125x)

700ps
35000