

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO.
30-025-28204

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

E W WALDEN

8. Well Number #14

9. OGRID Number
4323

10. Pool name or Wildcat
GRAYBURG

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
1616 W. BENDER BLVD HOBBS, NM 88240

4. Well Location

Unit Letter N : 550' feet from the SOUTH line and 2125' feet from the WEST line
Section 15 Township 22S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3889' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: T/A ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

~~CHEVRON USA INC. RESPECTFULLY REREQUESTING TO PLUG AND ABANDON THE ABOVE WELL. THIS WELL INITIALLY DOWN DUE TO A BI LEAK. PLEASE FIND ATTACHED PLUGGING PROCEDURE AND CURRENT WELLBORE DIAGRAM.~~

MIRU

UNSEAT PUMP AND LAY DOWN RODS/PUMP.

INSTALL BOP AND POOH WITH THE TUBING, RIG UP WIRELINE AND RIH WITH CIBP TO 3600'.
RUN IN HOLE AND DUMP 35' OF CEMENT ON CIBP. CIRCULATE PACKER FLUID.

Please find attached wellbore diagrams.

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cindy Herrera-Murillo TITLE Permitting Specialist DATE 12/12/2016

Type or print name Cindy Herrera-Murillo E-mail address: Cherreramurillo@chevron.com PHONE: 575-263-0431


For State Use Only

APPROVED BY: Marky Brown TITLE AO/II DATE 12/13/2016
Conditions of Approval (if any):

NO PRODUCTION REPORTED IN
2 MONTHS.

Chevron U.S.A. Inc. Wellbore Diagram : EW WALDEN 14

Lease: OEU EUNICE FMT		Well No.: E W WALDEN 14 14		Field: PENROSE SKELLY	
Location: 550FSL2125FWL		Sec.: N/A		Blk:	Survey: N/A
County: Lea	St.: New Mexico	Refno: DP4617		API: 3002528204	Cost Center: UCU497700
Section: E037		Township: 15			Range: S022
Current Status: ACTIVE				Dead Man Anchors Test Date: NONE	
Directions:					



Ground Elevation (MSL): 3383.00	Spud Date: 05/11/1983	Compl. Date: 01/01/1800
Well Depth Datum: Kelly Bushing	Elevation (MSL): 3391.00	Correction Factor: 8.00
Last Updated by: kqhc	Date: 12/11/2016	