

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35297
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CrownQuest Operating, LLC		6. State Oil & Gas Lease No. B-9358
3. Address of Operator 500 W. Texas Ave., Ste 500 Midland, TX 79710		7. Lease Name or Unit Agreement Name New Mexico "AN" State
4. Well Location Unit Letter F : 1980 feet from the N line and 1980 feet from the W line Section 22 Township 14S Range 33E NMPM County Lea		8. Well Number 19
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 213190
		10. Pool name or Wildcat Saunders Permo Upper Penn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK	INT TO PA <u>Am.x</u> P&A NR _____ P&A R _____
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE ☐			
OTHER: ☐		OTHER: _____	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag CIBP @ 8950 w/ 35 sxs cmt. - Pressure test csg.

2. Spot 25 sx cmt @ 6800-6700.

3. Perf & Sqz 80 sx cmt @ 4200-4100'. WOC & Tag

4. Perf & Sqz 50 sx cmt @ 2580-2490. WOC & Tag - Perf & Sqz 50 sx @ 1700'

5. Perf & Sqz 250 sx cmt @ 580-Surface.

6. Cut off Well head, verify cmt to surface, weld on Dry Hole Marker.

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 12/14/16
Type or print name Ben Montgomery E-mail address: Benm@bcmadassociates.com PHONE: 432-580-7161
For State Use Only
APPROVED BY: Neale Whitaker TITLE Petroleum Engr. Specialist DATE 12/14/2016
Conditions of Approval (if any):

Wellbore Schematic (From Surface to TD)

Printed: 12/9/2016

Page 1

New Mexico AN State # 19



