Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-025-25833
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease FEDERAL STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
300 M 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIO	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Glenn Ryan
PROPOSALS.)  1. Type of Well: Oil Well X	Gas Well  Other	8. Well Number 25
2. Name of Operator BLM for Patterson Operating &	2 Pumping Inc. DBA/Penergy	9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
NMOCD 1625 N. French Dr	ive Hobbs, NM 88240	Leonard:Queen, South
4. Well Location		
Unit Letter N : 660 feet from the South line and 1980 feet from the West line  Section 14 Township 26S Range 37E NMPM County LEA		
Section 14	11. Elevation (Show whether DR, RKB, RT, GR, e	
12. Check Appropriate Pay to Indicate Nature of Notice Papart or Other Date		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN		JBSEQUENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON 🖾 REMEDIAL WO	ORK INT TO PA PAX DRILLING OPNS. P&A NR
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMI	P&A R
DOWNHOLE COMMINGLE		FOLK
CLOSED-LOOP SYSTEM  OTHER:	□ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion		
SEE ATTACHED PROCEDURE AND SCHEMATIC		
CONTACT NMOCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS		
		HOBBS OCD
		JAN <b>2</b> 5 2017
		DEOCH (CD
Spud Date:	Rig Release Date:	RECEIVED
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
100		
SIGNATURE Mallutalan TITLE Petroleum Engineering Specialist DATE 1/25/2017		
Type or print name Mark Whitaker E-mail address: marka.whitaker@state.nm.us PHONE: <u>575-393-6161</u>		
For State Use Only  A  A  T  I  I  I  I  I  I  I  I  I  I  I  I		
APPROVED BY: DATE 125/2017		
Conditions of Approval (if any):		

Patterson Operating & Pumping Inc DBA as Penergy Glenn Ryan No. 25 30-025-25833 UL – N, Sec. 14, T26S, R37E

8 5/8" @ 520' w/ 550 sx cmt 5 1/2" @ 3671' w/ 1130'. Perforations 3418'-3604'

- 1. MIRU. POOH w/ production equipment.
- 2. Set CIBP at 3350'. Circulate hole with mud laden fluid. Spot 25 sx cement on CIBP. Pressure test casing to 500 psi. WOC and tag.
- 3. POOH to 2500'. Spot 25 sx cement.
- 4. POOH to 1150. Spot 25 sx cement.
- 5. POOH to 570'. Spot 60 sx cement.
- 6. Cut off wellhead 3' below ground level and verify cement to surface all strings.
- 7. Install below ground P&A marker. Photos should be taken prior to and after welding on plate. OCD should be notified prior to cut off so it can be witnessed.

NOTES: Mud laden fluid consists of 9.5 ppg brine with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

## Patterson Operating Pumping Inc DBA/Penergy Glenn Ryan # 25

