Office Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-05448
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION BIVISION	5 Indicate Tune of Lance
District III - (505) 334-6178	1220 Couth St Francis To	STATE A FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505 06 2017	or state on the state peace into
87505 SUNDRY NOTI	CES AND REPORTS ON WELER	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Dease Name of One Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM C-101) FOR SUCH	North Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other Temporarily Abandoned	8. Well Number 131
2. Name of Operator	das well other remporarily / bandoned	9. OGRID Number 157984
Occidental Permian, Ltd	,	
3. Address of Operator		10. Pool name or Wildcat
HCR 1 Box 90 Denver Cit	ty, TX 79323	Hobbs (G/SA)
4. Well Location		
Unit Letter L :	330feet from theWest line and	1980feet from theSouthline
Section 13	Township 18-S Range 37-E	NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
1000年,在1980年,1980年	3691' KB	美国的大学
12. Check A	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF IN	TENTION TO:	SECUENT DEDORT OF
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE	INIOETH EE COMME	
CLOSED-LOOP SYSTEM		
OTHER: TA status extension r	request T OTHER:	
	leted operations. (Clearly state all pertinent details, and	
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
proposed completion or reco	ompletion.	
5 - 10 - 11 - 1		
Run MI test to gain exter	nsion on temporary abandoned status.	
	Conc	ition of A
Condition of Approval: notify		
OCD Hobbs office 24 hours		
	prior of	running MIT Test & Chart
Spud Date:	Rig Release Date:	
Spud Date.	Rig Release Date.	
I hereby certify that the information	above is true and complete to the best of my knowled	ge and helief
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.
I hereby certify that the information a	above is true and complete to the best of my knowled	ge and belief.
I hereby certify that the information a	above is true and complete to the best of my knowled	ge and belief. DATE 02/03/2017
SIGNATURE Mendly a	Admin. Associate	DATE 02/03/2017
SIGNATURE Mendy A. Jol	Admin. Associate	DATE 02/03/2017
SIGNATURE Mendly a	Admin. Associate	DATE 02/03/2017
SIGNATURE Mendy A. Jol	Admin. Associate	DATE 02/03/2017
SIGNATURE Mendy A. John For State Use Only	hnsen E-mail address: mendy_johns	DATE 02/03/2017
SIGNATURE Mendy A. John Type or print name Mendy A. John For State Use Only APPROVED BY:	hnson E-mail address: mendy_johns Brown PITLE AO/II NO PRODUCTION REPORTED IN	DATE 02/03/2017
SIGNATURE Mendy A. John Type or print name Mendy A. John For State Use Only APPROVED BY:	hnsen E-mail address: mendy_johns	DATE 02/03/2017