
Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (575) 334 6128	Form C-103
District I – (575) 393-6161 Energy Junerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 HOBPOIL CONSERVATION DIVISION	30-25-26605
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 FEB 2 1220 South St. Francis Dr. Senta Fe, NM 87505	5. Indicate Type of Lease STATE STATE 7
<u>District IV</u> $= (505) 4/6-3460$	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Bobbi State Waterflood Unit
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 8
2. Name of Operator / SUNDOWN ENERGY LP	9. OGRID Number 232611
3. Address of Operator	10. Pool name or Wildcat
16400 DALLAS PARKWAY, STE. 100 DALLAS, TX 75248	W, Arkansas Juction SA
4. Well Location	
Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u>	
Section 28 Township 18S Range 36E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM LEA County
3830' RT	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK Z PLUG AND ABANDON	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	JOB []
CLOSED-LOOP SYSTEM	
OTHER: Convert Producer to Injection OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. MI RU Well service Rig	
2. POOH w/ production equipment	
 RIH & drill out CIBP @ 5335' Clean out well to PBTD (5620') 	
5. Run 2-3/8" IPC tubing and plastic coated packer to 5300'	
6. Perform MIT & put well into injection service	
OPEN PERFS: 5320' - 5326'; 5428' - 5433' & 5574'- 5584'	
R-13731	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Thereby certify that the information above is the and complete to the best of my knowledge and bench.	
SIGNATURE Belinda Gradley TITLE Admin. Asst DATEATE ATEDATEDATEATE ATEDATEDATE	
Type or print name <u>Belinda Bradley</u> E-mail address: <u>bbradley@sundownenergy.com</u> PHONE <u>432-943-8770</u>	
For State Use Only	
APPROVED BY:	

WELL DATA SHEET



WELL DATA SHEET

