Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Re	sources Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St. Artesia NM 8200 RBS OIL CONSERVATION DIVI	20.025.21924
811 S. First St., Artesia, NM 8220 BBB OIL CONSERVATION DIVI District III – (505) 334-6178 1220 South St. Francis D	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 MAR 1 0 2017 Santa Fe, NM 87505	STATE     FEE       6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCI	
PROPOSALS.)         1. Type of Well: Oil Well         Gas Well         Other INJECTION	8. Well Number #5
2. Name of Operator	9. OGRID Number 4323
CHEVRON USA INC	10. Declarance of Wildorf
3. Address of Operator 6301 DEAUVILLE BLVD; MIDLAND, TX 79706	10. Pool name or Wildcat Vacuum;Glorieta
4. Well Location	
Unit Letter_N: 1209_feet from the _SOUTHline and _2582feet from the _WESTline	
Section 24 Township 17S Range 34E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4001' GL	
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	EDIAL WORK
TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB       I	
CLOSED-LOOP SYSTEM	
OTHER:       OTHER:       REPAIR WELL       Image: Constraint of the second s	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
CHEVRON USA INC HAS REPAIRED THE ABOVE WELL. THIS WELL FAILED AN ANNUAL MIT TEST.	
01/26/2017 RIG UP WORK OVER RIG	
01/27/2017 RIG UP APOLLO AND SET 1.43 PROFILE PLUG AND IT WOULD NOT HOLD PRESSURE. INSTALL BOP	
TRY TO TEST. 01/30/2017 CHECK PRESSURE, TEST BOP, RIG UP SCANNERS, POOH WITH FIBER LINED TUBING.	
01/31/2017 FINISH POOH WITH PRODUCITON, RIH WITH PACKER AND START LOOKING FOR AND ISOLATE	
HOLE IN CASING. CASING IN TESTING GOOD FROM 3200' AND BELOW.	
CONTINUED ON NEXT PAGE ORIGINAL MIT	CHARTAND COPY ATTACHED
[]	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of m	w knowledge and belief
SIGNATURE Anna Mullo TITLE Permitting Specialist DATE 03/07/2017	
Type or print name <u>Cindy Herrera-Murillo</u> E-mail address: <u>eeof@chevron.com</u> PHONE: <u>575-263-0431</u>	
For State Use Only Maluk	
APPROVED BY: CARY DIOWNITE HOLA DATE S/13/2017	
Conditions of Approval (if any)!	
NODIN CILLEN -	

## VACUUM GLORIETA WEST UNIT #5

02/01/2017 RELEASE PACKER AND POOH. PICK UP A TENTION PACKER AND START TESTING. 02/02/2017 RUN IN WITH 7 JOINTS AND TAG SAND, PULL OUT. RUN IN WITH 10'FIBERGLASS SUB, TUBING HEAD HANGER, SET IT AND RUN IN LOCKING PINS, PUMP CEMENT AND CLOSE WELL. 02/03/2017 CHECK PIS0#, PULL HANGER ANS SUBS, RIH/WITH TUBING, TAG TOC @41;, KB, APPLY 550# ON CASING, LOST 150# IN 2 ½ MINUTES. RIG UP STRIPPER RUBBER AND P SWIVEL DRILL OUT CEMENT FROM 41' FELL OUT OF CEMENT @ 50 KBM. TEST CASING 540# FOR 30 MINUTES PSI 440#, RETEST CASING 540# IN 30 MINUTES PIS 510#.

02/6/2017 RUN IN WITH 60' OF PIPE, CIRCULATE CEMENT @ 12.5#, PULL OUT WITH TUBING. PRESSUE UP TO HELP SQUEEZE CEMENT BACK BEHIND PIPE. CLOSE WELL IN AND LEAVE PRESSURE ON IT.

02/7/2017 CHECK PRESSURE, PICK UP COLLARS AND RUN IN AND DRILL OUT CEMENT AND TEST CASING. TESTED BEFORE STARTING TO DRILL. 500 PSI AND 350 PSI IN 2 MINUTES. GO AHEAD AND DRILL OUT CEMENT.

02/8/2017 RUN IN AND RETREIVE RBP @ 275', RUN CHART TO DOUBLE CHECK CASING, POOH, RUN BACK IN AFTER BOTTOM RBP @5921'; PULL OUT LAYING DOWN WORK STRING. 02/9/2017 RIH WITH INJECTION PACKER AND TUBING AND SET /TEST PACKER, CIRCULATE PACKER FLUID.

02/10/2017 RUN MIT TEST FOR NMOCD/GEORGE BOWER WITNESSED. RUN CHART @ 620 PSI FOR 30 MINUTES. PRESSURE GOOD AND HELD. RIG DOWN.



