

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-11985
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEDERAL <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		7. Lease Name or Unit Agreement Name Glenn Ryan
2. Name of Operator BLM for Patterson Operating & Pumping Inc. DBA/Penergy		8. Well Number 006
3. Address of Operator NMOCD 1625 North French Drive Hobbs, NM 88240		9. OGRID Number
4. Well Location Unit Letter <u>B</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>14</u> Township <u>26S</u> Range <u>37E</u> NMPM Lea County		10. Pool name or Wildcat Leonard;Queen, South
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION

PERFORM REMEDIAL WORK
 TEMPORARILY ABANDON
 PULL OR ALTER CASING
 DOWNHOLE COMMINGLE

INT TO PA _____
 P&A NR _____
 P&A R pm-x

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A XX
 CASING/CEMENT JOB

OTHER: _____ OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Mark Whitman TITLE P.E.S. DATE 04/04/2017

Conditions of Approval (if any):

Plugging Report

Glenn Ryan #6

Lat: 32.0486881285 Lon: -103.131619232

3/27/2017 Move in equipment and rig up. Repaired wellhead and installed BOP. Made gauge ring run to 3250'. Picked up 5 ½" CIBP and RIH with workstring. Set CIBP at 3250'. SION.

3/28/2017 Circulate MLF. Tested casing to 350#. Good. Spot 25 sx Class C cement on CIBP with CaCl. WOC and tag at 3093'. POOH to 2502' and spotted 25 sx cement. POOH to 1170' and spot 25 sx cement. POOH to 325' and circulate cement to surface with 35 sx. SION

3/29/2017 Rigged down and cut off wellhead. Filled both strings to surface with 10 sx cement. Installed marker and cleared location.