Submit 1 Copy To Appropriate District OfficeState of New MexicoDistrict I – (575) 393-6161Energy, Minerals and Natural Resources1625 N. French Dr., Hobbs, NM 88240Image: Comparison of the second seco	Form C-103 Revised July 18, 2013 WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88214 OBBS OF CONSERVATION DIVISION District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 MAY 11 2017 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	30-025-27841 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Langlie Jal Unit	
PROPOSALS.) 1. Type of Well: <u>Oil Well X</u> Gas Well Other	8. Well Number #96	
2. Name of Operator Pogo Oil & Gas Operating, Inc.	9. OGRID Number 372000	
 Address of Operator 1515 Calle Sur, Ste. 174 Hobbs, New Mexico 88240 USA 	10. Pool name or Wildcat Langlie Mattix; 7 Rvrs-Queen-Grayburg	
4. Well Location		
Unit Letter <u>N</u> <u>140</u> feet from the <u>SOUTH</u> line and <u>2600</u> feet from the <u>WES</u>	ST line \checkmark	
Section <u>32</u> Township <u>24S</u> Range <u>37E</u> NMPM	M County <u>LEA</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3246 GL		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK X ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB	
DOWNHOLE COMMINGLE				5/2/DDIA PM-	
CLOSED-LOOP SYSTEM				1 2/2/2011	
OTHER:				OTHER Returned TA'd well back to production.	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Pogo Oil & Gas Operating, Inc returned this TA'd well to production on 5/2/2017. Average well test at time of this report is 6 BOPD and 175 BWPD. Attached is a step list of the work that was performed. Pogo Oil & Gas Operating respectfully requests that this well be reclassified as an active producer.

4/19/2017: Held safety meeting, rigged up workover unit. ND wellhead, NU BOP. Well had no pressure on it. TIH w/ 4-3/4" bit, 6 3-1/2" drill collars, and 93 jts of 2-7/8" tbg. Tagged TOC @ 3,118'. Stood back one stand, secured well and SDFN.

4/20/2017: Held safety meeting. PU swivel, pumped 25 bbl of FW to establish circulation. Drill out 31' of cement w/ good returns and tagged CIBP @ 3149'. Drilled on plug, lost circulation after drilling through and uncovering top set of perfs. Lay down swivel. POOH w/ 93 jts of tbg, 6 drill collars, and bit. RIH w/ kill string, clean location, and shut down for weekend.

Spud Date:		Rig Release I	Date:					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNATURE Type or print	name Kyle Townsend	TITLE E-mail address:	Operations Manager kyle@pogoresources.com	DATE 5/8/2017 Phone: 713-305-9886				
For State Use APPROVED Conditions of	Nahan Mthan	WTAULE	AO/IL	DATE 5/11/2017				

LJU #96 Time Log Continued:

4/24/2017: Held safety meeting. RIH w/ BPMA, 4' perf sub, SN, 14 jts of 2-7/8" J-55, TAC, 86 jts of 2-7/8" J-55. Landed tbg and set TAC with no issues. Bottom of tubing is 3258'. Built out wellhead and hooked up flowline. Prepped rods. RIH w/ 4' gas anchor, 25-175-RHBC-20-5 insert pump, 2' lift sub, 4 K-bars, 74 ³/₄" rods, 48 7/8" rods, 2' pony and 26' polish rod. NU stuffing box and checked well for pump action, good test. Left pump barely tagging bottom to be picked up when we set pumping unit. Cleaned up location, could not rig down due to high winds, will RDMO in AM.

4/25/2017: RDMO WO rig.

4/27/2017: Move/set pumping unit and set up electrical at the location.

5/1/2017: Well did not show good pump action over the weekend. Decision was made to load tbg with fresh water, RU WO unit and respace the pump. Held safety meeting, rigged up. Loading tbg, tbg held good to 500 psi. Added 8' pony sub, reseated the pump. Well would not pump, secure well, SDFN.

5/2/2017: Held safety meeting. POOH w/ rods and pump. Very little fluid inside pump, appears we received a bad pump from the shop. RIH w/ replacement pump and same rod design from before. Felt pump seat good, hung on well. Loaded tbg w/ pump truck and pumped up to 500# in 4 strokes. Good pump action, rigged down, cleaned location, and moved out WO rig.

This well has been pumping since 5/2/2017 and has been added to the daily routine of wells to check within the field. This well is now an active producer w/ 2-7/8" tbg and 5-1/2" 14# csg.