

Submit One Copy To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised November 3, 2011

HOBBBS  
 MAR 16 2017  
 RECEIVED

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. <b>30-025-21916</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-9560</b>
7. Lease Name or Unit Agreement Name <b>New Mexico AQ State NCT 11</b>
8. Well Number <b>1</b>
9. OGRID Number <b>213190</b>
10. Pool name or Wildcat <b>Lazy J. Penn</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  Oil Well  Gas Well  Other

2. Name of Operator  
**CrownQuest Operating**

3. Address of Operator  
**PO Box 53310, Midland, TX 79710**

4. Well Location

Unit Letter   **J**   :   **1980**   feet from the   **S**   line and   **1980**   feet from the   **E**   line

Section   **3**   Township   **14S**   Range   **33E**   NMPM \_\_\_\_\_ County   **Lea**  

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**4210' GL**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p style="text-align: center;"><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p style="text-align: center;"><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/></p> <p>CASING/CEMENT JOB <input type="checkbox"/></p> <p><input checked="" type="checkbox"/> Location is ready for OCD inspection after P&amp;A <span style="float: right; color: blue;">pmv</span></p>
---	---

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE   *Saul Leyva*   TITLE   **Lease Manager**   DATE   **3/13/2017**  

TYPE OR PRINT NAME   **Saul Leyva**   E-MAIL:   **sleyva@crowquest.com**   PHONE:   **432-559-9066**  

For State Use Only

APPROVED BY:   *Mark Whitzler*   TITLE   **P.E.S.**   DATE   **05/11/2017**

## Whitaker, Mark A, EMNRD

---

**From:** Saul Leyva <sleyva@crowquest.com>  
**Sent:** Tuesday, April 18, 2017 6:45 AM  
**To:** rengland@targaresources.com  
**Cc:** Whitaker, Mark A, EMNRD  
**Subject:** AQ Battery

Ralph,  
CrownQuest is requesting the removal of the gas meter housing and concrete bases on the New Mexico AQ State 11 #1 lease at your earliest convenience.

Thanks.

Saul Leyva  
CrownQuest Operating, LLC