Ļ					
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103			
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Re	esources	Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240	ke-		WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV	ISION	30-025-07864 5. Indicate Type of Lease		
District III - (505) 334-6178	1220 South St. Francis D	Dr.	STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	2 (6 State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	P	502012	FEDERAL LEASE		
87505 SUNDRY NOT	TICES AND REPORTS ON WELLS	-1/	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROP	DSALS TO DRILL OR TO DEEPEN OR PLUG BAC ICATION FOR PERMIT" (FORM C-101) FOR SUC		SEMU PERMIAN		
1. Type of Well: Oil Well Gas Well Other INJ WELL			8. Well Number 026		
2. Name of Operator ConocoPhillips Company			9. OGRID Number 217817		
3. Address of Operator _{P. O. Box 51810}			10. Pool name or Wildcat		
Midland,	TX 79710		SKAGGS; GRAYBURG		
4. Well Location					
Unit Letter E	1980 feet from the NORTH	line and 660	feet from the WEST line		
Section 30	Township 20S Range 3	8E	NMPM County LEA		
	11. Elevation (Show whether DR, RKB,				
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: ISOLATE & REPAIR FO 13. Describe proposed or comp of starting any proposed w proposed completion or rem	CHANGE PLANS COM MULTIPLE COMPL CASE OR LOV ON FAILED BH TST OTH pleted operations. (Clearly state all pertinen ork). SEE RULE 19.15.7.14 NMAC. For completion. Y WILL LIKE TO ISOLATE AND REPAI VELLBORE SCHEMATIC.	SUBS IEDIAL WORK IMENCE DRII ING/CEMENT ER: nt details, and Multiple Con IR FROM A F IR FROM A F	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING P AND A P AND A T JOB A give pertinent dates, including estimated date npletions: Attach wellbore diagram of FAILDED BH TEST PER ATTACHED Approval: notify office 24 hours		
	prior of	of running	MIT Test & Chart		
Spud Date:	Rig Release Date:				
	1	1 1 1	11.1.6		
I hereby certify that the information	above is true and complete to the best of n	ny knowledge	and belief.		
SIGNATURE Mon	TITLE Staff Regulate	ory Technicia	nDATE 05/25/2017		
Tyme or print name Dianda Da	Empiled	ma	billing com DUONE: (422)(00 0174		
Type or print name <u>Rhonda Rogers</u> <u>C</u> E-mail address: <u>rogerrs@conocophillips.com</u> PHONE: <u>(432)688-9174</u> For State Use Only <u>A</u> <u>O</u>					
APPROVED BY:	Shown TITLE AC)/II	DATE 5/30/2017		
Conditions of Approval (if any):		1			

/

SEMU PERMIAN 26 API 30-025-07864 Isolate and repair

Project Scope

Justification and Background:

The SEMU 26 failed Braiden head testing on 03/09/17 and is currently shut in. This procedure calls for determining and isolating the source of the leak. If economic, the leak will be repaired and a new MIT/BH will be performed. Otherwise, the well will be prepared for P&A.

This job is a high priority as the well is under a LOV repair by date of 6/12/17.

Perforations				
Туре	Formation	Тор	Bottom	
Perforations	San Andres	3680'	3908'	
PBTD		3908'		
TD	3908'			

PROCEDURE:

- 1) Confirm with Eng/Regulatory that OCD has approved NOI to move packer.
- 2) Prior to moving in rig, MIRU slick line and pump truck.
- 3) Rig up lubricator. RIH with profile plug and set in profile nipple.
- 4) Pressure test tubing to 550 PSI. Contact PE to discuss test results and potentially altering the following procedure.
- 5) RDMO slick line services.
- 6) MIRU well service unit. Kill well if necessary.
- 7) Install Class 1 Hydraulic BOP. Function test BOP.
- 8) Pull tension on packer and attempt to load and test backside.
 - a. If casing holds pressure, ND BOPE, NU wellhead, and contact Prod. Spec. to perform MIT.b. If casing does not hold, proceed to next step.
- 9) Release packer. Pick up 1 joint and reset packer. Note: Packer must be within 100' of top perf to perform MIT.
- 10) Attempt to load and test backside.
 - a. If casing holds pressure, ND BOP, NU wellhead, and contact Prod. Spec. to perform MIT.
 - b. If casing does not hold, proceed to next step.
- 11) Release packer and scan tubing OOH standing back. Stand back yellow and blue band tbg.
- 12) Visually inspect IPC coating while TOOH. Call PE after 5 double stands to discuss results and potentially laydown tubing. Inspect packer and send in for servicing if needed.
- 13) RU hydro-testers & RIH w/ new redressed inj pkr hydro testing tbg to 5000 psi. Set packer at original depth (3598'). Packer must be within 100' of to perf.
- 14) RU pump truck. Load backside and test pkr to 500 psi surface pressure. If pkr holds then proceed.
- 15) RU pump truck. Circulate packer fluid to surface (3600' x 0.0158 bbl/ft = 57 bbls).
- 16) ND BOP, NU wellhead.
- 17) RU chart recorder w/ 1,000 psi chart to casing. Pressure test backside to 500 psi for 35 mins.
 - a. Notify the NMOCD of impending test. (MIT/BH)
 - b. If test fails, notify Production Eng. for possible job scope change.
- 18) RDMO well service unit.

