

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-04529
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name:	Graham Orcutt Gas Com
8. Well Number	3
9. OGRID Number	005380
10. Pool name or Wildcat	Eumont; Yates-7 Rvrs-Queen (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☒

2. Name of Operator
XTO Energy, Inc

3. Address of Operator
500 W. Illinois St Ste 100 Midland, Texas 79701

4. Well Location

Unit Letter **J** : **1980** feet from the **South** line and **1980** feet from the **East** line

Section **6** Township **21S** Range **36E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC.. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

XTO Energy, Inc respectfully requests to temporarily abandon the referenced location for 5-years with the following procedure:

1. Tag CIBP @ 3650 .
 2. Dump 25sx cmt thru tbq or 35' via wireline. WOC 4 hours. Tag.
 3. Set CIBP @ 3305 . Cap w/25sx cmt thru tbq or 35' via wireline. WOC 4 hours. Tag.
 4. Run good MIT.
- A closed-loop system will be used for this operation.

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephanie Rabadue TITLE Regulatory Analyst DATE 05/20/2017

Type or print name Stephanie Rabadue E-mail address: stephanie_rabadue@xtoenergy.com PHONE 432-620-6714


For State Use Only
APPROVED BY Mary Brown TITLE AO/II DATE 5/30/2017

Conditions of Approval (if any):

Current

Graham Orcutt Gas Com 3
30-025-04529

GL: 3578'
KB TO GL:



propose

Graham Orcutt Gas Com 3
30-025-04529

GL: 3578'
KB TO GL:

