Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			Revised July 18, 2013 WELL API NO.		
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 HOBBS DCD SERVATION DIVISION			30-025-05215		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410 MAY 3 0 2017 Santa Fe, NM 87505			6. State Oil & O	FEE X	
1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & G	ras Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7 1 1	TT '. A	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Denton North Wolfcamp Unit		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			TO POPE 36		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other (Injection)			8. Well Number		,
2. Name of Operator			9. OGRID Num	ber 247128	
Wishbone Texas Operating Company LLC.				370	256
3. Address of Operator			10. Pool name or Wildcat		
10613 W. Sam Houston Pkwy N #400, Houston, Texas, 77064			Denton Wolfcamp		
4. Well Location	1000 0 0 0		1.5501		
	1980feet from theSouth			rom theWest_	line
Section 36 Township 14S Range 37E NMPM County Lea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check	Appropriate Box to Indicate N	Nature of Notice,	Report or Other	r Data	
			•		
			SEQUENT F		
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			K LLING OPNS.□	INT TO PA AM	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN'				P&A NR	X
DOWNHOLE COMMINGLE				P&A R	
CLOSED-LOOP SYSTEM					
OTHER: OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
proposed completion of recompletion.					
Procedure to P&A wellbore: Tag cn	at @ 8025' Spot 25 sv amt @ 8025	Y Tag omt Display	as WP with mud le	den fluid. Cut and n	ull 5
½" casing @7500'. Spot 36 sx cmt f	from 7600' across 5 ½" casing to.	Tag cmt. Spot 30 sx	cmt across 7 5/8"	casing shoe from 689	00'. TAG
Perf circ holes @4823'. Circ cmt to		cmt from 2700' in	7 5/8" casing. Tag		
380' to surf with cmt. Well P&A'd	Tage .	@3100'(BS	SALT)	Spot 25 sx	@ Z700°
CUT OFF WOULD	eal à			Spot 25 sx (T. SALT) TAC	-
Verify ant to	Surface all strings			c months of the	
Trachil PEAW	surface all strings				
Mud Laden Fluid mix ratio					
			05 Sy Cal	tgel per 1001	hh/s Bri
			23 3X Sar	riger per 1001	יום בונונו
Spud Date:	Rig Release D	ate:			
I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.		
	_				
SIGNATURE / W	TITLE	and a community	mt DA	TE 05/22/2017	
SIGNATURE / W	IIILEE	Engineering Consulta	int DA	TE05/22/2017	
Type or print name _Tim Wall	E-mail addre	ss:twall@wishl	ooneep.com PH	ONE: _832-807-221:	5
For State Use Only	\wedge		_		
ADDROVED BY MI . I /.	VIII PI	In En So	minded a	ATE 05/30/20	17
APPROVED BY: Conditions of Approval (if any):	MARL HILLETTO	neum Linger. of	D	ALE 03/30/20	
Conditions of Approval (if any).					



