Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		30-025-36149	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Leas	/
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE X  6. State Oil & Gas Lease	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	2 2 3, 2 1 2 27 2 2 2		19552	a No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit A	Agreement Name
(DO NOT LISE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEDEN OR DILLIG RACK TO A			North Hobbs Unit (G/SA	/
PROPOSALS.)  1. Type of Well: Oil Well X	X Gas Well Other		8. Well Number 537	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR COAP PROPOSALS.)  1. Type of Well: Oil Well X Gas Well Other  2. Name of Operator Occidental Permian Ltd  3. Address of Operator P.O. Box 4294, Houston, TX 77210  4. Well Location Unit Letter B: 876 feet from the North line and			9. OGRID Number 157984	
3. Address of Operator	III	WED	10. Pool name or Wilder	at
P.O. Box 4294, Houston	, TX 77210	CEI	Hobbs (G/SA)	
4. Well Location	: 876 feet from the North	E	1403 feet from the	East line
Unit Letter B Section 32				mine
Section 32	Township 18S Ra  11. Elevation (Show whether DR,	0		ty Lea
	3641' GR	rand, rat, ora, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK				RING CASING
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRIL				) A 🗆
PULL OR ALTER CASING				
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER:		OTHER: R		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed completion of recompletion.				
MIRU x NDWH x NUBOP. RIH 4 ¾" bit x tagged cmt @ 3934'. Drilled through both CIBP to 4361'. RIH 5 ½" CIBP @ 4290' x perf'd well 4049' – 4254' x dumped 10' cmt on CIBP.				
Ran acid job w/ $3800$ gals $15\%$ HCL. RIH pkr @ $3960'$ x pumped $55$ gals of PAW $3900$ w/ $34$ bbls FW, 605 gals of SCW261 w/ $72$ bbls FW x flushed w/ $700$ bbls FW. POOH pkr x RIH $122$ jts tbg @ $3910'$ x ESP @ $3999'$ .				
RD x NDBOP x NUWH. Return well to production.				
NO X NOBOL X NOWN. Neturn well to production.				
Spud Date: 06/08/17	Rig Release Da	ite: 06/15/17		
L				
X1 1 (C d d d C d	1	-1 · C · · 1 · · 1 · 1	11.1.6	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
$h i / \sqrt{m} d$				
SIGNATURE FIFTH U	TITLE Regula	atory Specialist	DATE	07/11/2017
Type or print name April Hood E-mail address: April_Hood@Oxy.com PHONE: 713-366-5771				
For State Use Only				
Wal MKM2 4 An/T 4/13/2012				
APPROVED BY: DATE DATE DATE				
Conditions of Approval (many)				