

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-005-60802	✓
5. Indicate Type of Lease STATE FEE X	✓
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit	✓
8. Well Number 042	✓
9. OGRID Number	
10. Pool name or Wildcat Twin Lakes; San Andres (Assoc)	✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other ✓

2. Name of Operator
State of New Mexico formerly Canyon E&P Company

3. Address of Operator
811 South 1st Street, Artesia, NM 88210

4. Well Location
Unit Letter I : 1650 feet from the South line and 990 feet from the East line ✓
 Section 31 Township 8S Range 29E NMPM Chaves County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK [INT TO PA <u>BCX</u> P&A NR _____ P&A R _____
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. [
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB [
DOWNHOLE COMMINGLE <input type="checkbox"/>				
OTHER: <input type="checkbox"/>		OTHER:		

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD
 JUL 20 2017
RECEIVED

SEE ATTACHED

**NOTIFY OCD 24 HOURS PRIOR TO
 BEGINNING PLUGGING OPERATIONS**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Whitaker TITLE P.E.S. DATE 07/20/2017

Type or print name Mark Whitaker E-mail address: _____ PHONE: 575 393-6161

For State Use Only
 APPROVED BY: Mary Brown TITLE AO/II DATE 7/20/2017
 Conditions of Approval (if any): _____

Procedure to Finish Plugging TLSAU #42

1. RIH and tag fill at 894'.
2. Establish circulation and spot 45 sx Class C cement with CaCl from 894'. WOC and tag at or above 220'. Will repeat process if necessary.
3. If cement is tagged at or above 220' then test 4 ½" casing. If casing tests good, will perforate at 180' and circulated cement down 4 ½" casing to perfs at 180' and up annulus to surface.
4. Remove wellhead and verify cement is to surface on both strings of casing. Install Marker and cut off anchors.