New Mexico Oil Conservation Division, District | FORM APPROVED

UNITED STATES DEPARTMENT OF THE INTERIOR

OMB NO. 1004-0137 Expires March 31, 2007

BUREAU OF LAND MANAGEMENT

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

LC-032511-F 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well X Oil Well Gas Well Other 2. Name of Operator Energen Resources Corporation 3a. Address 3300 N. A St., Bldg. 4, Ste. 100, Midland, TX 79705 (432) 687-1155 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL and 1980' FWL Section 11, T25S, R37E				7. If Unit or CA/Agreement, Name and/or No Stuart Langlie Mattix 8. Well Name and No. 109 9. API Well No. 30-025-11535 10. Field and Pool, or Exploratory Area Langlie Mattix 7 RVRS Queen Grayburg 11. County or Parish, State							
						12. CHECK APPROPRIATE	BOX(ES) TO INDI	CATE NATURE OF I	NOTICE, REP	Lea ORT, OR OT	NM THER DATA
						TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomple	te ly Abandon	Water Shut-Off Well Integrity Other						
 Describe Proposed or Completed Operation (clear If the proposal is to deepen directionally or recomposated the Bond under which the work will be perfollowing completion of the involved operations. 	plete horizontally, give sub rformed or provide the Bo	surface locations and meas and No. on file with BLM	sured and true ver	rtical depths of a	all pertinent markers and zones.						


testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

MIRU pulling unit

- Install rod stripper. Unseat pump and POOH laying downrods and pump.
- 3. Install BOPE. POOH w/tubing.
- RIH w/CIBP and tubing. Set at 3200'. Tag CIBP.
- Circulate hole w/treated 2% KCl water. Pressure test casing to 500 psi

Load casing w/treated 2% KCl water.

Notify NMOCD and perform MIT to 500 psig.



APPROVED FOR MONTH PERIOD ENDING

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Well is non-utilized. Approve TA for one Regulatory Analyst year ending (11/18/2006). Is well justified 11-16-05 under Unit Plan of Operations"? Last unuer on Francis or plug well by deadline produced 1990. Utilize or plug well by THIS SPACE FOR FEDERAL OR STAT Approved by Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Office certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person know States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdict

my to make to any department or agency of the United

down tubing.