Submit 1 Copy To Appropriate District  Office  State of New Mexico	Form C-103
Energy Minerals and Natural Resources	Revised July 18, 2013
District I = (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240  District II = (575) 748-1283  811 S. First St., Artesia, NM 88210  District III = (505) 334-6178  1000 Rio Brazos Rd., Aztec, NM 87410  District IV = (505) 476-3460  1220 S. St. Francis Dr., Santa Fe, NM  2 8 20\$\frac{1}{2}\$ anta Fe, NM 87505	WELL API NO. 30-025- 38145
811 S. First St., Artesia, NM 88210	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE S FEE .
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410  District IV – (505) 476-3460 1220 South St. Francis Dr.  87505	6. State Oil & Gas Lease No.
87505	V-2522
SUNDRY NOTICES AND THINK SON WELLS (DO NOT USE THIS FORM FOR PROPOSAL SUDDRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Fox A State
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	,
2. Name of Operator  ROCKCLIFF OPERATING NEW MEXICO LLC	9. OGRID Number 371115
3. Address of Operator	10. Pool name or Wildcat
1301 McKinney St Suite 1300, Houston, TX 77010	Allison San Andres
4. Well Location	
Unit LetterK_:1650feet from theSouth line and210	
Section 2 Township 9S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
GL: 4049	And the second s
10. Charles American Demonstrate National National States	December Other Date
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT RFT 1-
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK	
TEMPORARILY ABANDON	LLING OPNS. INT TO PA
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	JOB P&A NR
DOWNHOLE COMMINGLE   NOTICE	P&A R
CLOSED-LOOP SYSTEM    DECLIFICATION OCT	
BEGIAN	24 HOLL
OTHER:	24 HOURS PRIOR TO THE HOLD TO
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent up)  of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Confidence of Starting any proposed work.	P&A R  24 HOURS PRIOR TO date
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent uccomproposed completion or recompletion.)  SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	24 HOURS PRIOR TO and date of
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent ucon of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	24 HOURS PRIOR TO and date
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only periods.	TRATIONS
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period.  2. MIRU and Remove rods/pump and production tubing	od complete the following: Pressure
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only periodic MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production.	od complete the following:  Test Csg  Tion string
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production tubing  4. Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4	od complete the following:  Test Csg  Tion string
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'	od complete the following:  Test Csg  Tion string
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)	od complete the following:  Test Csg  Tion string
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance. MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2	and complete the following:  The pressure first Csg  1,835'-4,735', WOC for 4hrs then Tag
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance 2. MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG	nod complete the following:  Pressure  Test Csg  1,835'-4,735', WOC for 4hrs then Tag  1,162', If can circulate, pump 55sxs Cl C in/out
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance. MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in production to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt	nod complete the following: Pressure tion string .,835'-4,735', WOC for 4hrs then Tag
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance. MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface. Verify	nod complete the following:  Pressure  Test Csg  ,835'-4,735', WOC for 4hrs then Tag  ,162', If can circulate, pump 55sxs Cl C in/out  pills
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance of MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product of the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  7. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker*  VERIFY CMT TO 5	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs Cl C in/out pills
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance. MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product to the set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface. Verify	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs Cl C in/out pills
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance of MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product of Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  7. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' WOC TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker **  VERIFY CMT TO 5  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent recompleted in the start of the start of the surface of	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs Cl C in/out pills
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only perilogologologologologologologologologolog	iod complete the following: Pressure tion string 1,835'-4,735', WOC for 4hrs then Tag 1,162', If can circulate, pump 55sxs Cl C in/out pills  URFACE.  eport of P&A", have location inspected by the
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only perilogologologologologologologologologolog	iod complete the following: Pressure tion string 1,835'-4,735', WOC for 4hrs then Tag 1,162', If can circulate, pump 55sxs Cl C in/out pills  URFACE.  eport of P&A", have location inspected by the
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only performance of MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product of the start of the start of the start of the performance of the start o	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs CI C in/out pills  URFACE.  eport of P&A", have location inspected by the
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only perilogologologologologologologologologolog	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs CI C in/out pills  URFACE.  eport of P&A", have location inspected by the
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only peri 2. MIRU and Remove rods/pump and production tubing 3. Run a CBL since no there is no indication of cement to surface on the 5.5in product 4. Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153' 6. Spot 25 sxs Cl C @ 4,253' - 4,153' 6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#) 7. Spot 25 sxs Cl C @ 2,855' - 2,705' 8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc FTAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify 11. Cut off WH & anchors install P&A marker*  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs CI C in/out pills  URFACE.  eport of P&A", have location inspected by the
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only peri 2. MIRU and Remove rods/pump and production tubing 3. Run a CBL since no there is no indication of cement to surface on the 5.5in product 4. Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153' 6. Spot 25 sxs Cl C @ 4,253' - 4,153' 6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#) 7. Spot 25 sxs Cl C @ 2,855' - 2,705' 8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc FTAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify 11. Cut off WH & anchors install P&A marker*  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD	iod complete the following: Pressure tion string ,835'-4,735', WOC for 4hrs then Tag ,835'-4,735', WOC for 4hrs then Tag ,162', If can circulate, pump 55sxs CI C in/out pills  URFACE.  eport of P&A", have location inspected by the
1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4.253' - 4,153'  6. Spot 25 sxs Cl C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' WOC TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker VERIFY CMT TO S  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD  I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE CMA DULLING TITLE: Operations Analyst	iod complete the following: Pressure tion string 1,835'-4,735', WOC for 4hrs then Tag 1,162', If can circulate, pump 55sxs Cl C in/out pills  URFACE.  eport of P&A", have location inspected by the eport of P&A", have location inspected by the eport of P&A".
1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period of MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker VERIFY CMT TO S  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD  Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE CLARACTER COLOR TITLE: Operations Analyst  Type or print name: Michal A. Weesner E-mail address: mweesner@rockcliffenergy.cc	iod complete the following: Pressure tion string 1,835'-4,735', WOC for 4hrs then Tag 1,162', If can circulate, pump 55sxs Cl C in/out pills  URFACE.  eport of P&A", have location inspected by the eport of P&A", have location inspected by the eport of P&A".
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs CI C @ 4,253' - 4,153'  6. Spot 25 sxs CI C @ 4,253' - 4,153'  7. Spot 25 sxs CI C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs CI C at 2,262' to 2 from 2,262' to 2,162' Woc FAC  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs CI C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker VERIFY CMT TO S  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD  Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE USE OF TITLE: Operations Analyst  Type or print name: Michal A. Weesner  E-mail address: mweesner@rockcliffenergy.co	iod complete the following: Pressure tion string (835'-4,735', WOC for 4hrs then Tag (162', If can circulate, pump 55sxs Cl C in/out pills  URFACE .  eport of P&A", have location inspected by the Photo e and belief.  DATE: 07/26/17  PHONE: (713)351-0535
proposed completion or recompletion.  1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs CI C @ 4,253' - 4,153'  6. Spot 25 sxs CI C @ 4,253' - 4,153'  7. Spot 25 sxs CI C @ 3,678' - 3,528', WOC then tag & circ hole w/ MLF (10#)  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs CI C at 2,262' to 2 from 2,262' to 2,162' Woc FAC  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs CI C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker VERIFY CMT TO S  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD  Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE USE OF TITLE: Operations Analyst  Type or print name: Michal A. Weesner  E-mail address: mweesner@rockcliffenergy.co	iod complete the following: Pressure tion string (835'-4,735', WOC for 4hrs then Tag (162', If can circulate, pump 55sxs CI C in/out pills  URFACE .  eport of P&A", have location inspected by the Photo e and belief.  DATE: 07/26/17  PHONE: (713)351-0535
1. Estimated start time is the middle of August 2017 and over a 3-4 daylight only period of MIRU and Remove rods/pump and production tubing  3. Run a CBL since no there is no indication of cement to surface on the 5.5in product Set 5.5in CIBP @ 4,836', Tag CIBP circ hole w/ MLF (10#), Spot 25 sxs Cl C @ 4,253' - 4,153'  6. Spot 25 sxs Cl C @ 4,253' - 4,153'  7. Spot 25 sxs Cl C @ 2,855' - 2,705'  8. Perf at 2,212'. Attempt to circulate; If can't circulate spot 25 sxs Cl C at 2,262' to 2 from 2,262' to 2,162' Woc TAG  9. The CBL will determine if additional perf / squeeze is needed or only spotting cmt 10. Spot 55 sxs Cl C @ 200' - Surface, Verify  11. Cut off WH & anchors install P&A marker VERIFY CMT TO S  12. Reclaim location as per OCD instructions, Return OCD form C-103 "Subsequent r OCD.  13. *See attached WBD  Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE CLARACTER COLOR TITLE: Operations Analyst  Type or print name: Michal A. Weesner E-mail address: mweesner@rockcliffenergy.cc	iod complete the following: Pressure tion string (835'-4,735', WOC for 4hrs then Tag (162', If can circulate, pump 55sxs Cl C in/out pills  URFACE .  eport of P&A", have location inspected by the Photo e and belief.  DATE: 07/26/17  PHONE: (713)351-0535



