	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT <b>arisbad Field</b> Department <b>arisbad Field</b> Department Lease Senta No.							
		TS ON WE	LLS OC	DA	5. Lease Serial No. NMLC071949			
Do not use th abandoned we	NOTICES AND REPOR is form for proposals to d II. Use form 3160-3 (APD)	for such p			6. If Indian, Allottee or	Tribe Na	ime	
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.							
SUBMIT IN TRIPLICATE - Other instructions on page 2       2 0 2011       7. If Unit or 0         1. Type of Well       0CT       8. Well Name							7	
1. Type of Well       0C1         □ Oil Well ⊠ Gas Well □ Other       8. Well Name and No. ANTELOPE RIDGE UNIT 7         2. Name of Operator       Contact: DAVID STEWART         0. OVID VID A UNIC       9. API Well No.								
OXY USA INC. / E-Mail: david_stewart@oxy.com 30-025-27047								
3a. Address P.O. BOX 50250 MIDLAND, TX 79710		10. Field and Pool or Exploratory Area ANTELOPE RIDGE STRAWN						
4. Location of Well (Footage, Sec., 7					11. County or Parish, State			
Sec 27 T23S R34E SWNE 16 32.278347 N Lat, 103.455765					LEA COUNTY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES) T	O INDICA	TE NATURE O	F NOTICE	, REPORT, OR OTH	IER DA	TA	
TYPE OF SUBMISSION			TYPE OI	F ACTION				
🛛 Notice of Intent	Acidize	Dee	pen	Produc	tion (Start/Resume)	🗆 Wa	ater Shut-Off	
	□ Alter Casing		raulic Fracturing	Reclam	nation	U Well Integrity		
Subsequent Report	Casing Repair	_	Construction	🛛 Recom		D Otl	ner	
			Plug and Abandon		rarily Abandon Disposal			
Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for 1. Pull Tubing and insert pum 2. Install CIBP @ 12070' isola 3. Perforate Strawn at approx 4. Cleanout well with BHA.	d operations. If the operation resu bandonment Notices must be filed final inspection. p. Send tubing for scanner ating Atoka perfs @ 12079-	lts in a multip l only after all	e completion or recorrequirements, includ	CLASS H	new interval, a Form 316 on, have been completed a	0-4 must and the op	be filed once perator has	
<ul> <li>4. Cleanout well with BHA.</li> <li>5. RIH with 10K packer and set above new perforations and do stimulation with 100 gaves of the flow back unit.</li> <li>6. Breduce with natural flow to the flow back unit.</li> </ul>								
6. Produce with natural flow t	o the flow back unit.	3		CONDI	ITIONS OF A	APPR	OVAL	
14. I hereby certify that the foregoing i	Electronic Submission #38				n System			
For OXY USA INC., sent to the Hobbs Committed to AFMSS for processing by MUSTAFA HAQUE on 10/05/2017 ()								
Name(Printed/Typed) DAVID S	TEWART		Title SR. RE	GULATOR	Y ADVISOR			
Signature (Electronic	Submission)		Date 08/09/2	017 A	PPROVED			
	THIS SPACE FOR	R FEDERA			E Company and the company and			
_Approved By	Hagne		Title	ETROLEU	MENGINEER		Date 10-05-201	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Office								
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any department or	agency of	f the United	
(Instructions on page 2) <b>** OPERA</b>	TOR-SUBMITTED ** OP	ERATOR	SUBMITTED *	** OPERA	TOR-SUBMITTED	**		

MUB/000 10/23/2017

# Additional data for EC transaction #384240 that would not fit on the form

#### 32. Additional remarks, continued

7. Produce to the facility after 4 days.

District 1 1625 N French Dr. Hobbs NM 88240 Phone (575) 393-6161 Fax (575) 393-0720 District II 811 S First St. Artesia, NM 88210 Phone (575) 748-1283 Fax (575) 748-9720 District III 1000 Rio Brazos Road. Aztec. NM 87410 Phone (505) 334-6178 Fax (505) 334-6170 District IV 1220 S St. Francis Dr. Santa Fe. NM 87505 Phone (505) 476-3460 Fax (505) 476-3462

# State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

12

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT										
14	API Number <sup>2</sup> Pool Code <sup>3</sup> Pool Name							1.	(	
30-02	5-27	047	-	10450		Antelope Ridge Struwn (Gas)				
<sup>4</sup> Property (	Code		<sup>5</sup> Property Name						<sup>6</sup> Well Number	
			Antelope Ridge Unit 7						7	
OGRID 1	No.		8 Operator Name					<sup>9</sup> Elevation		
166	96				OXY USI	USIA Inc. 3471'				
<sup>10</sup> Surface Location										
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line		County
G	27	235	34E		1650	north	1980	east		Lea
"Bottom Hole Location If Different From Surface										
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line		County
<sup>12</sup> Dedicated Acres <sup>13</sup> Joint or Infill <sup>14</sup> Consolidation Code <sup>15</sup> Order No.										
320	N	7								

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

)¢	1650		<sup>17</sup> <b>OPERATOR CERTIFICATION</b> I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief and that this organization either owns a working interest or unleased mineral interest in the land including the propised hottom hole locution or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest or to a voluntary pooling agreement or a compilisory pooling order heretofore entered by the division
		. 1980'	Bigliance David Stewart SR. Bas. Adv. Printed Name david Stewart BOXY. Com E-mail Address
×			"SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief Date of Survey
		4	Signature and Seal of Professional Surveyor Certificate Number

**OXY USA Inc. - Current** Antelope Ridge Unit #7 API No. 30-025-27047 20" hole @ 465' 16" csg @ 465' w/ 850sx-TOC-Surf-Circ WC= 11/460' Pern = 11/784' Den Moiren = 11/882' Atoka = 12/075' Mor now = 12,892' 14-3/4" hole @ 5060' 10-3/4" csg @ 5060' DVT @ 1138' w/ 1950sx-TOC-Surf-Circ 9-1/2" hole @ 11650' 7-5/8" csg @ 11650' w/ 800 sx-TOC-4570'-Calc 6-1/2" hole @ 13574' 5" liner @ 11435-13574' w/ 285sx-TOC-11435'-Circ Perfs @ 12079-12626' CIBP @ 12900' w/ 35' cmt to 12865' DB Pkr @ 13140' Perfs @ 13183-13413' PB-13485' TD-13574'

OXY USA Inc. - Proposed Antelope Ridge Unit #7 API No. 30-025-27047

> 20" hole @ 465' 16" csg @ 465' w/ 850sx-TOC-Surf-Circ

14-3/4" hole @ 5060' 10-3/4" csg @ 5060' DVT @ 1138' w/ 1950sx-TOC-Surf-Circ

9-1/2" hole @ 11650' 7-5/8" csg @ 11650' w/ 800 sx-TOC-4570'-Calc

6-1/2" hole @ 13574' 5" liner @ 11435-13574' w/ 285sx-TOC-11435'-Circ

Perfs @ 11983-12026'

Perfs @ 12079-12626'

Perfs @ 13183-13413'

CIBP @ 12070' & 25 socks of Class H cement on to of CIBP. was & Tog.

CIBP @ 12900' w/ 35' cmt to 12865' DB Pkr @ 13140'

PB-13485'

TD-13574'

## Antelope Ridge Unit 7 30-025-27047 Oxy USA Conditions of Approval

# Notify BLM at 575-361-2822 (Eddy County) or 575-393-3612 (Lea County) a minimum of 24 hours prior to commencing work.

### Work to be completed by January 05, 2019.

- Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.

9. See attached for General Plugback Guidelines

MHH 10052017

.

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "**C**", for up to 7,500 feet of depth or **Neat Class** "**H**", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>. If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.