

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88241
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OCD
OIL CONSERVATION DIVISION
OCT 25 2017 220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-29931
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other: -----		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 4294, Houston, TX 77210		7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit
4. Well Location <u>SHL/BHL</u> Unit Letter <u>B/O</u> <u>202/1057</u> feet from the <u>North/South</u> line and <u>1764/1666</u> feet from the <u>East</u> line Section <u>33/28</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County		8. Well Number: <u>28-342</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3641' GL		9. OGRID Number: 157984
		10. Pool name or Wildcat: Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU PU
2. POOH with ESP Equipment
3. PU and RIH with 7" bit and 2 7/8" WS (tag PBTD)
4. Circulate hole clean
5. POOH with tubing
6. RIH with ESP equipment (intake TBD)
7. RDMO PU

During this procedure we plan to use
the closed-loop system with a steel
tank and haul contents to the required
disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Alison Cramer TITLE: Prod Eng DATE: 10/24/17

Type or print name Alison Cramer E-mail address alison_cramer@oxy.com PHONE: 713-840-3024

For State Use Only

APPROVED BY: Mary Brown TITLE: AO/II DATE: 10/25/2017

Conditions of Approval (if any):

MB