

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
HOBBBS OCD
FEB 01 2018
RECEIVED
 OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-21783
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator JAY MANAGEMENT COMPANY, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 1001 WEST LOOP SOUTH, SUITE 750 HOUSTON, TX 77027		7. Lease Name or Unit Agreement Name BELL A
4. Well Location Unit Letter <u>C</u> : <u>720</u> feet from the <u>NORTH</u> line and <u>1980'</u> feet from the <u>WEST</u> line Section <u>21</u> Township <u>11S</u> Range <u>33E</u> NMPM County <u>LEA</u>		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4210' KB		9. OGRID Number 247692
10. Pool name or Wildcat BAGLEY PERMO PENN NORTH		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
 PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Plan to enter well, remove down hole production equipment.
2. TD the well and check for fill.
3. Run a retrievable bridge plug or packer to within 100 feet of uppermost perforations.
4. Pressure test to 500 psi for 30 minute.

**Condition of Approval: notify
 OCD Hobbs office 24 hours
 prior of running MIT Test & Chart**

C.O.A
*SUBMIT CURRENT
 WELLBORE DIAGRAM
 WITH SUBSEQUENT C-103*

Spud Date:

Rig Release Date:

MEB

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Clayton Griffin* TITLE District Manager DATE 01/31/2018

Type or print name Clay Griffin E-mail address: griffin@jaymgt.com PHONE: 574-707-5691

For State Use Only

APPROVED BY: *Maley Brown* TITLE *AO/II* DATE *2/1/2018*

Conditions of Approval (if any):

NO REPORTED PROD - 68 MONTHS