0.1 1.2 1	State of I	New Me	exico			F 0 400
Submit 3 copies to Appropriate District Office	Energy, Minerals and Natu	ural Res	sources Department			Form C-103 Revised 1-1-8
<u>DISTRICT I</u>	OIL CONSERVA	TÎC	N DIAMPION	WELL ARINO		
P.O. Box 1980, Hobbs, NM 88240	P.O. Box			R.	30-025-35643	
DISTRICT II	Santa Fe, New M		/ ==	5. Indicate Typ		
P.O. Box Drawer DD, Artesia, NM 88210	Cana i c, i toli iii		~ \$ 60	B	STATE [FEE 🗹
DISTRICT III			3 10 1	6. State Oil / G	as Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410	FIGURE AND DEDODTO ON	14/51 1			t ve partie	Year of the same of the same
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM (FORM C-101) FOR SUCH PROPOSALS.				7. Asse Name or Unit Agreement Name HARRISON 'B'		
1. Type of Well: OIL GAS WELL WELL	L OTHER		SI-1808			
2. Name of Operator CHEVRON U	ISA INC			8. Well No.	28	
Address of Operator 15 SMITH RI	D, MIDLAND, TX 79705			9. Pool Name	or Wildcat DRINKARD ABO NOR	TH/TGE TUBB
4. Well Location				-		
Unit Letter 1 ::	1650' Feet From The _	SOUTI	H Line and 840'	Feet From 1	The <u>EAST</u> L	ine
Section 5	Township 23-S	Ra	ange <u>37-E</u> NN	ИРМ	LEA CO	DUNTY
	10. Elevation (Show whether DF	F, RKB, I	RT,GR, etc.) 3334' GR			
11. Check Ap	ppropriate Box to Indicate	e Natu	re of Notice, Report	, or Other D	ata	
NOTICE OF INTENTION TO:				UBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OP	ERATION 🗌	PLUG AND ABANDO	NMENT
			CASING TEST AND CEMEI	NT JOB		
OTHER:			OTHER:	CIDIZE & RETU	IRN TO PRODUCTION	~
12. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 3-01-06: MIRU. UNSET PKR. 3-02-06: SET TBG OUT. SET IN WS. T3-03-06: TIH W/RBP, PKR, 220 JTS, T40-06: UNSET PKR. TIH W/RBP & P6697 W/8000 GALS 15% ANTI-SLUDGI 3-08-06: TOH W/RBP TO 6400. SET R13-10-06: TIH W/PPI TOOLS, 203 JTS, BBLS. SET PKR @ 6197. 3-13-06: SWAB. REL PKR. TIH W/PKR 3-14-06: SWAB. 3-15-06: SWAB. TIH W/6 JTS TO 5380 3-16-06: SWAB. 3-20-06: SWAB. 3-21-06: PUMP 30 BBLS. KILL WELL. SN @ 7111. TAC @ 6142. SET TAC. 3-23-06: RU TONGS & FLOOR. PU PU 3-24-06: RIG DOWN. FINAL REPORT 3-27-06: ON 24 HR OPT. PUMPING 0 TEAGUE DRINKARD ABO NORTH OIL	TIH W/BIT. TAG 5' BRIDGE. WO 6911. RBP HIT TITE SPOT KR, 214 JTS, TO 6716. SET FE HCL. BP. TOH W/PKR 15 STANDS TO 6380. MARK SETTINGS. AR W/RETR TOOL FOR RBP, 190. LATCH ON TO RBP. UNSET LD 93 JTS WS, PKR, & RBP. JMP & RODS. STACE OUT WOMEN AND TEST. OIL, 3 GAS, & 134 WATER. I	/ORK T IN CSG RBP. TO TO 544 ACIDIZI 97 JTS T RBP. MI PRO	THRU BRIDGE. TIH TO 7 G. WORK RBP LOOSE. T DH W/11 JTS TO 6376. S 40. E 6214-6326 W/6500 GA , TO 6197. SET PKR. CU SET PKR @ 6380. SWA DDUCTION TBG. TIH W/I	175, 228 JTS. TH W/PKR, 50 ET PKR. ACII LS 15% ANTI- IT SANDLINE. B.	BAIL TO 7180. D STANDS TO 3154. DIZE DRINKARD PE SLUDGE HCL. REV	RFS 6448- CIRC 160
TEAGUE TUBB NORTH ASSOC. OIL)					

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

SIGNATURE

Denise Pinkerton

Regulatory Specialist

DATE 4/6/2006

Telephone No. 432-687-7375

(This space for State Use)

APPROVED CONDITIONS OF APPROVAL IF ANY TITL

PETROLEUM ENGINEER

APR O 7006 DeSoto/Nichols 12-93 ver 1.0