State of New Mexico Energy, Minerals & Natural Resources Form C-101 May 27, 2004

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Divsiion 1220 S. St. Francis Dr.

Submit to appropriate District Office

☐ AMENDED REPORT Santa Fe, NM 87505

APPLIC	CATION	FOR P	 ERMIT 1	O DRI	LL, RE-EN	NTER	, DE	EPEN,	PLUGBACI	K, OR ADI	A ZONE
***************************************			erator Name ar				,		B 1 2 2	² OGRID Numbe	
OXY USA WTP	Limited	Partners	hip						<u> </u>	192463 ³ API Number	
P.O. Box 502		lland, TX	79710-	0250					30- 025-	3782	Ч
355.5	rty Code			OXY 6	⁵ Property Great Horned	Name d Owl	State	Com		⁶ We	ll Nò. 1
	1dca+	⁹ Proposed Morrow 1	Pool 1		96996				¹⁰ Proposed Po	0012	
					⁷ Surface I	Locati	on			"	
UL or lot no.	Section	Township	Range	Lot. Idn				outh Line	Feet from the	East/West line	County
0	31	16S	32E		1120			outh	1930	east	Eddy
		8 I	roposed l	Bottom :	Hole Locati	ion If	Differ	ent Fro	m Surface		
UL or lot no.	Section	Township	Range	Lot. Idn	Feet from t	the	North/S	outh Line	Feet from the	East/West line	County
			······•	A	dditional W	ell Lo	cation	n			
¹¹ Work Ty _l			² Well Type Co-	de	13 Cable/R				e Type Code E-7177		evel Elevation
¹⁶ Multi		1	7 Proposed Dep	th	¹⁸ Forma			19 C	Contractor		ud Date
Depth to ground			13000'	Distance fr	Morr om nearest fresh		ell	<u> </u>	N/A Distance from neare		1/06
*									2000000		
Pit: Liner: Syn	nthetic	mils	thick Cla	у	Pit Volume	в	bls D	rilling Meth	iod:		
Closed-Lo	oop System				I	Fresh Wa	ater 🔲	Brine	Diesel/O	il-based 🔲	Gas/Air 🔲
			21]	Propose	d Casing an	d Cer	nent F	rogram	\$ P	C. C.	
Hole S	ize	Cas	ing Size	Casing	g weight/foot	Setting Depth		Sacks of Cemer		stimated TOC	
17-1/	2"	13	-3/8"	48#		600' (52		600sx	surfa	ce-circulate	
12-1/	4"	9.	5/8"	36#		4500'		1300sx 5	surfa	ce-circulate	
8-3/4	4"	5	1/2"	<u> </u>	17#		13000'		ک. 1000sx	1 ' . /	TOC-8000'
					···			C. C	97		
				<u> </u>							
Describe the properties of the properties of the blown and the properties of the	proposed prog	gram. If this	application is	to DEEPEN	N or PLUG BAC	K, give	the data	on the pre	sent productive zon	ne and proposed	new productive zone.
			From Ap		is it necessary.						
Penti	te linies	s Drillin	g Underv	V er y							
	,				See Attach	nment					
*-C-144	(Atta	ched									
²³ I hereby certify my knowledge an					te to the best of	OIL CONSERVATION DIVISION					
constructed acco				general per	mit 🔲 , or	Approved by:					
an (attached) alternative OCD-annraved plan Signature:						Ž		STOWNER	É.	-	
Printed name: Da	avid Stew	vart				Title:	PET	ROLEU	AI EIVOIVAL		
Title: Si	r. Regula	itory Ana	lyst				val Date		E E	epiration Date:	
E-mail Address:	david_st	ewart@ox					APR ?	200	JU .		
Date:	.1		Phone:	0 605 55		li .		Approval:			
5128	306		43	2-685-57	/1/	Attach	ed _]			

OXY USA WTP LP
OXY Great Horned Owl State #1
1120 FSL 1930 FEL SWSE(O) SEC 31 T16S R32E Lea County, NM
State Lease No. E-7177

PROPOSED TD:

4

13000' TVD

BOP PROGRAM:

0-600'

None

600-4500'

13-3/8" 3M annular preventer, to be used as

divertor only.

4500-13000'

11" 5M blind pipe rams with 5M annular

preventer and rotating head below 8500'.

CASING:

Surface:

13-3/8" OD 48# H40 ST&C new casing set at 600'

17-1/2" hole

Intermediate:

9-5/8" OD 36# K55 ST&C new casing from 0-4500'

12-1/4" hole

Production:

5-1/2" OD 17# N80-HP110 LT&C new casing from 0-13000'

8-3/4" hole 9400'-N80 3600'-HP110

CEMENT:

Surface - Circulate cement with 350sx HES light PP w/ 2% $CaCl_2$ + .25#/sx Flocele followed by 250sx PP w/ 2% $CaCl_2$ + .25#/sx Flocele.

Intermediate - Circulate cement with 1100sx IFC w/ .25#/sx Flocele followed by 200sx PP w/ 2% CaCl₂.

Production - Cement with 600sx Interfill H w/ .1% HR-7 followed by 400sx Super H w/ .5% HR-344 + .4% CFR-3 + 5#/sx Gilsonite + 1#/sx salt + .2% HR-7. Estimated top of cement is 8000'.

Note: Cement volumes may need to be adjusted to hole caliper.

MUD:

0-600'

Fresh water/native mud. Lime for pH control

(9-10). Paper for seepage.

Wt 8.7-9.2 ppg, Vis 32-34 sec

600-45001

Fresh/*Brine water. Lime for pH control (10.0-

10.5). Paper for seepage.

Wt 8.3-9.0/10.0-10.1ppg, Vis 28-29 sec

*Fresh water will be used unless chlorides in

the mud system increases to 20000PPM.

4500-8500'

Fresh water. Lime for pH control(9-9.5). Paper

for seepage.

Wt 8.3-8.5 ppg, Vis 28-29 sec

8500-10000'

Cut brine. Lime for pH control (10-10.5).

Wt 9.6-10.0 ppg, Vis 28-29sec

10000-13000'

Mud up with an Duo Vis/Flo Trol mud system.

Wt 9.6-10.0ppg, Vis 32-36sec, WL<10cc

SPACING UNIT: S/2

POOL NAME: Undesignated Fren Morrow Northeast - 96996

ESTIMATED FORMATION TOPS: Texmack 36 St-3 - 3001530947 - 36-16-31 Morrow-12014' Atoka-11742' Strawn-11426' Penn-10293' Wolfcamp-8838' Robinson Ut Tr 5-15 - 30-025-00423 - 31-16-32 San Andres-3858' Grayburg-3540' Queen-3120' Yates-2210'

SPUD DATE: 7/1/06

ARCH SURVEY: N/A

DIRECTIONS TO LOCATION: From the intersection of USH 82 and CR 124, go northwest on CR 124 for approximately 1.2 miles. Turn right and go north approx. 0.1 mile, turn left and go northwest approx. 0.1 miles, Turn right and go northeast approx. 0.2 miles. The location ia approx. 450' east.

WELLSITE LAYOUT: V-Door - East Pits - North

SURFACE OWNER: State of NM

LEASEE: Olane & LaDoyce Caswell, 1702 Gillham Dr., Brownfield, TX 79316

LEASE RESPONSIBILTY STATEMENT: N/A

PRIVATE SURFACE OWNER'S AGREEMENT OR STATEMENT THAT AN AGREEMENT CONCERNING SURFACE USE: $\rm N/A$

NEAREST RESIDENCE OR OTHER STRUCTURE: None within 2 miles

SOURCE OF CONSTRUCTION MATERIALS - Caliche for surfacing the well pad will be obtained from onsite materials.

H₂S CONTINGENCY PLAN: 3/28/06

PIT PERMIT: 3/28/06

DIRECTIONAL SURVEY PLAN: N/A

State of New Mexico

DISTRICT I 1625 N. FRENCH DR., HOBBS, NM 88240

1000 Rio Brazos Rd., Aztec, NM 87410

Energy, Minerals and Natural Resources Department

DISTRICT II
1301 W. GRAND AVENUE, ARTESIA, NM 68210

OIL CONSERVATION DIVISION

1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505

Form C-102 Revised October 12, 2005

Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT IV

DISTRICT III

WELL LOCATION AND ACREAGE DEDICATION PLAT

AMENDED REPORT

API Number	Pool Code	Pool Name	O AMENDED REP
30 - 025- 37\$ 24	-96996	Wildcal Pool Name Undesignated Fren Morr	ow, Northeast
Property Code 355557	-	ORNED OWL Com	Well Number
ogrid no. 192463	-	rator Name SA WTP LP	Elevation 4087

Surface Location


ĺ	UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
	0	31	16-S	32-E		1120	SOUTH	1930	EAST	LEA

Bottom Hole Location If Different From Surface


UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acres	Joint or	Infill Cor	nsolidation (Code Ore	der No.				
320	N								

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

LOT 1		
f01 1		OPERATOR CERTIFICATION
40.59 AC		I hereby certify that the information herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
	GEODETIC COORDINATES NAD 27 NME	Signature Date
1	Y=682050.1 N X=662808.1 E	David Stewart Printed Name
40.61 AC	LAT.=32*52'26.09" N LONG.=103*48'10.98" W	Sr. Regulatory Analyst SURVEYOR CERTIFICATION
10T 3		SORVETOR CERTIFICATION
		I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
40.63 AC LOT 4	30-025-00423	FEBRUARY 23, 2006 Date Surveyed E/D MR Signature & Seal of O MR Professional Surveyor. 06.41.0363
40.65 AC		Certificate NoGARY BUSSON 1264



VICINITY MAP



SEC. 31 TWP. 16-S RGE. 32-E

SURVEY N.M.P.M.

COUNTY LEA STATE NEW MEXICO

DESCRIPTION 1120' FSL & 1930' FEL

ELEVATION 4087'

OPERATOR OXY USA WTP LP


LEASE GREAT HORNED OWL



PROVIDING SURVEYING SERVICES
SINCE 1946
JOHN WEST SURVEYING COMPANY
412 N. DAL PASO
HOBBS, N.M. 88240
(505) 393-3117



LOCATION VERIFICATION MAP



SCALE: 1" = 2000'

CONTOUR INTERVAL: MALJAMAR, N.M. - 10'

SEC. 31 TWP. 16-S RGE. 32-E

SURVEY N.M.P.M.

COUNTY LEA STATE NEW MEXICO

DESCRIPTION 1120' FSL & 1930' FEL

ELEVATION 4087'

OPERATOR OXY USA WTP LP


LEASE GREAT HORNED OWL


U.S.G.S. TOPOGRAPHIC MAP

MALJAMAR, N.M.



PROVIDING SURVEYING SERVICES SINCE 1946 JOHN WEST SURVEYING COMPANY 412 N. DAL PASO HOBBS, N.M. 88240 (505) 393-3117





Choke Manifold

OXY USA WTP Limited Partnership PO Box 50250 Midland, TX 79710

Hydrogen Sulfide (H₂S) Contingency Plan

For

OXY Great Horned Owl No. 1 1120 FSL, 1930 FEL Sec 20, T16S, R32E Lea County, NM

And

McVay Rig 5

TABLE OF CONTENTS

<u>ITEM</u>	<u>PAGE</u>
PREFACE	3
LOCATION MAP	4
RIG SKETCH	. 5
EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES	6
SPECIFIC EMERGENCY GUIDANCE - H2S Release - Well Control	
PUBLIC RELATIONS	13
PHONE CONTACTS – OP DOWNHOLE SERVICES GROUP	14
EMERGENCY PERSONELL NOTIFICATION NUMBERS	15
PHONE CONTACTS – OP PRODUCTION AND PLANT PERSONNEL	16
PHONE CONTACTS - OP HES PERSONNEL	16

PREFACE

An effective and viable Contingency Plan is intended to provide prior planning and guidance in responding to emergency incidents. The primary considerations in its development are protection of personnel, the public, company and public property, and the environment.

Although the plan addresses varied emergency situations which may occur, it recognizes that flexibility and the use of the organization's knowledge and experience is critical to safe resolution of emergency incidents. Response actions outlined in the plan provide a framework, which may be placed into operation without confusion. These actions should promote quick and decisive actions during the critical initial period and immediately following an emergency. As the response progresses, additional guidelines and procedures may need to be implemented as the situation dictates. In addition, all emergency incidents must be properly reported per the Oxy Incident Reporting and Notification Policy, state and federal requirements, etc.


This Contingency Plan is intended for use on Oxy Downhole Services Group projects and the operations within their area of responsibility, such as drilling, critical well work, etc.

A copy of the Plan shall be maintained in the Top Dog House, Rig Managers trailer, and Company Representative's trailer if applicable.

Oxy Great Horned Owl St. No. 1 Y = 682050.1 N X = 662808.1 E Lat. 32°52'26.09"N Long. 103°48'10.98" W




NORTH



DIRECTIONS TO LOCATION: From the intersection of USH 82 and CR 124, go northwest on CR 124 for approximately 1.2 miles. Turn right and go north approx. 0.1 mile, turn left and go northwest approx. 0.1 miles, Turn right and go northeast approx. 0.2 miles. The location ia approx. 450' east.

McVay Drilling Rig No. 5



EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES

Activation of the Emergency Action Plan

- A. In the event of any emergency situation, all personnel on location should first ensure that the following items are initiated. After that, they should refer to the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document for further responsibilities:
 - 1. Notify the senior ranking contract representative on site.

2. Notify Oxy representative in charge.

- 3. Notify civil authorities if the Oxy Representative can not be contacted and the situation dictates.
- 4. Perform rescue and first aid as required (without jeopardizing additional personnel).

General Responsibilities

Oxy Permian Personnel:

- A. Operations Specialist: The Oxy Drilling/Critical Well Servicing Operations Specialist or contract personnel serving in that capacity will serve as Operations Chief Officer for all emergency incidents. The Operations Chief Officer is responsible for:
 - 1. Notification to the Downhole Services Team Leader of the incident occurrence.
 - 2. Notification to the local RMT/PMT leader of the incident occurrence, and the need for the designated local RMT/PMT Incident Commander to act in that capacity for the response effort.
 - Sole control of all tactical activities directed toward reducing the immediate hazard, establishing situational control and restoring the operations to a non-emergency state.
- B. Local RMT/PMT Designated Incident Commander: The Oxy local RMT/PMT Designated Incident Commander will serve as the overall Incident Commander for the drilling or critical well servicing emergency incident. The Incident Commander is responsible for:
 - 1. Coordinating with the Downhole Services Team Leader for notification to the Oxy Crisis Management team of the incident occurrence.
 - Establishing and managing the overall incident command structure and response from inception through restoration of normal activities in the area.
- C. Downhole Services HES Tech: The Downhole Services HES Tech (or his designate) is responsible for reporting to the incident as soon as reasonably possible, to provide support to the response effort as required by the Operations Chief Officer or the Incident Commander.

Contract Drilling Personnel will immediately report to their assigned stations and perform their duties as outlined in the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document.

Other Contractor Personnel will report to the safe briefing area to assist Oxy personnel and civil authorities as requested when it is safe to do so and if they have been adequately trained in their assigned duties.

Civil Authorities (Law Enforcement, Fire, and EMS) will be responsible for:

- 1. Establishing membership in the Unified Incident Command.
- 2. As directed by the Incident Commander and the Unified Command, control site access, re-route traffic, and provide escort services for response personnel.
- 3. Perform all fire control activities in coordination with the Unified Command.
- 4. Initiate public evacuation plans as instructed by the Incident Commander.
- 5. Perform rescue or recovery activities with coordination from the Unified Command.
- 6. Provide medical assistance as dictated by the situation at hand.

H2S RELEASE

The following procedures and responsibilities will be implemented on activation of the H2S siren and lights.

All Personnel:

1. On alarm, don escape unit (if available) and report to upwind briefing area.

Rig Manager/Tool Pusher:

- 1. Check that all personnel are accounted for and their condition.
- 2. Administer or arrange for first aid treatment, and /or call EMTs as needed.
- 3. Identify two people best suited to secure well and perform rescue, and instruct them to don SCBA.
- 4. Notify Contractor management and Oxy Representative.
- 5. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.

Two People Responsible For Shut-in and Rescue:

- 1. Don SCBA and acquire tools to secure well and perform rescue, i.e., wrenches, retrieval ropes, etc.
- 2. Utilize the buddy system to secure well and perform rescue(s).
- 3. Return to the briefing area and stand by for further instructions.

All Other Personnel:

1. Isolate the area and prevent entry by other persons into the 100 ppm ROE. Additionally the first responder(s) must evacuate any public places encompassed by the 100 ppm ROE. First responder(s) must take care not to injure themselves during this operation. Company and/or local officials must be contacted to aid in this operation. Evacuation of the public should be beyond the 100 ppm ROE.

Oxy Representative:

- 1. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.
- 2. Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Training

There will be an initial training session prior to encountering a known or probable H2S zone (within 3 days or 500 feet) and weekly H2S and well control drills for all personnel in each crew. The initial training session shall include a review of the site specific H2S Drilling Operations Plan and the Public Protection Plan (Contingency Plan). This plan shall be available at the well site. All personnel will be required to carry documentation that they have received the proper training.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO2). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police shall be the Incident Command of any major release. Ignition of the well will be with the concurrence of the drilling team leader and the Oxy Crisis Management Team as time allows.

Characteristics of H2S and SO2

Common Name	Chemical Formula	Specific Gravity	Threshold Limit	Hazardous Limit	Lethal Concentration
Hydrogen Sulfide	H ₂ S	1.189 Air = 1	10 ppm	100 ppm	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air = 1	2 ppm	N/A	1000 ppm

Contacting Authorities

Oxy Permian personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as; type and volume of release, wind direction, location of release, etc. Be prepared with all information available. The following call list of essential and potential responders has been prepared for use during a release. This response plan must be in coordination with the State of New Mexico's 'Hazardous Materials Emergency Response Plan' (HMER).

WELL CONTROL

The following procedures will be implemented when a loss of primary control is indicated. Indicators of loss of primary control are flow from the well, an increase in pit volume, or when the drilling fluid used to fill the hole on trips is less than the calculated pipe displacement volume. The emergency signal for well control procedures will be a single long blast of the rig air horn.

Kick While Drilling - Procedures And Responsibilities

Driller:

- 1. Stop the rotary and hoist the kelly above the rotary table.
- 2. Stop the mud pump(s).
- 3. Check for flow.
- 4. If flowing, sound the alarm immediately.
- 5. Ensure that all crew members fill their responsibilities to secure the well.
- 6. Record drill pipe and casing shut-in pressures and pit volume increase and begin kill sheet.

Derrickman:

- 1. Go to BOP/choke manifold area.
- 2. Open choke line valve on BOP.
- 3. Signal to Floorman #1 that the choke line is open.
- 4. Close chokes after annular or pipe rams are closed.
- 5. Record shut-in casing pressure and pit volume increase.
- 6. Report readings and observations to Driller.
- 7. Verify actual mud weight in suction pit and report to Driller.
- 8. Be readily available as required for additional tasks.

Floorman # 1:

- 1. Go to accumulator control station and await signal from Derrickman.
- 2. Close annular preventer and HCR on signal (if available, if not then close pipe rams).
- 3. Record accumulator pressures and check for leaks in the BOP or accumulator system.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman # 2:

- 1. Start water on motor exhausts.
- 2. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 3. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman #3:

1. Stand-by with Driller, and be readily available as required for additional tasks.

Tool Pusher/Rig Manager:

- 1. Notify Oxy Representative and report to rig floor.
- 2. Review and verify all pertinent information.
- 3. Communicate information to Oxy Representative, and confer on an action plan.
- 4. Finalize well control worksheets, calculations and preparatory work for action plan.
- 5. Initiate and ensure the action plan is carried out.
- 6. Communicate any changes in well or site conditions, or any indications that the action plan needs to be revised to the Oxy representative.

Oxy Representative:

 Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Kick While Tripping - Procedures and Responsibilities

Driller:

- 1. Sound the alarm immediately when pipe displacement volume is less than 75% of calculated.
- 2. Position the upper tool joint just above rotary table and set slips.
- 3. Check for flow.
- 4. Ensure that all crew members fill their responsibilities to secure the well.
- 5. Record drill pipe and casing shut-in pressures and pit volume increase, and begin kill sheets.

<u>Derrickman:</u> (same as while drilling)

Floor Man # 1:

- 1. Install full opening valve (with help from Floorman #2) in top drill string connection.
- 2. Tighten valve with make up tongs.
- 3. Go to accumulator control station and await signal from Derrickman.
- 4. Close annular preventer and HCR valve on signal (if available, if not then close pipe rams).
- 5. Record accumulator pressures and check for leaks in the BOP and accumulator system.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floor Man # 2:

- 1. Assist installing full opening valve in drill string.
- 2. Position back-up tongs for valve make-up.
- 3. Start water on motor exhausts.
- 4. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 5. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floorman # 3, Rig Manager/Tool Pusher, and Oxy Representative: (same as while drilling)

PUBLIC RELATIONS

Oxy recognizes that the news media have a legitimate interest in incidents at Oxy facilities that could affect the public. It is to the company's benefit to cooperate with the news media when incidents occur because these media are our best liaison with the public.

Our objective is to see that all reports of any emergency are factual and represent the company's position fairly and accurately. Cooperation with news media representatives is the most reliable guarantee that this objective will be met.

All contract and Oxy employees are instructed <u>NOT</u> to make any statement to the media concerning the emergency incident. If a media representative contacts any employee, they should refer them to the designated Emergency Command Center where they should contact the Incident Commander or his designated relief for any information concerning the incident.

OXY PERMIAN DOWNHOLE SERVICES GROUP

,	LOCATION	OFFICE	HOME	CELL	PAGER
Manager Operations	Support				
Hardesty, Steve	Midland	432-685-5880	432/694-6441	713-560-8095	
Team Leader					
Pennington, Randy	Midland	432-685-5684	432/689-7642	432-556-0207	
			Toledo Bend =	318-590-2349	
Operations Specialis	ts				
Fleming, Joe	Midland	432-685-5858	432/699-0875	432-425-6075	
Ray, Fred	Midland	432-685-5683	432/362-2857	432-661-3893	
HES Tech					
Thompson, Don	Midland	432-685-5719	432/684-3900	432-556-1505	

Emergency Notification Numbers

Pub	Public Authorities						
New Mexico State Police	Artesia	505/746-2704					
New Mexico State Police	Carlsbad	505/885-3137					
New Mexico State Police	Hobbs	505/392-5588					
Eddy County Sheriff's Office	Artesia	505/746-2704					
Eddy County Sheriff's Office	Carlsbad	505/887-7551					
Lea County Sheriff's Office	Hobbs	505/393-2515					
Local Emergency Planning Center	Eddy County	505/887-9511					
Local Emergency Planning Center	Lea County	505/397-9231					
New Mexico Oil & Gas Commission	Artesia	505/748-1283					
New Mexico Oil & Gas Commission	Hobbs	505/393-6161					
NM Emergency Response Center	Hobbs	505/827-9222					

Emergency Services							
Fire Fighting, Rescue, Ambulance, Police	Artesia	911					
Fire Fighting, Rescue, Ambulance, Police	Carlsbad	911					
Fire Fighting, Rescue, Ambulance, Police	Hobbs	911					
Flight For Life	Lubbock	806/743-9911					
Aerocare	Lubbock	806/7478923					
Med Flight Air Ambulance	Albuquerque	505/842-4433					

Other Emergency Services							
Boots and Coots		1/800-256-9688					
Cudd Pressure Control	Midland	432/699-0139					
B.J. Services	Artesia	505/746-3569					
Halliburton	Artesia	505/746-2757					

OXY Permian Production and Plant Personnel OXY Permian Crisis Team Hotline Notification (713) 935-7210

PERSON	LOCATION	OFFICE	FAX	CELL	PAGER
Asset Management-Operations Areas					
OXY Permian General Manager:	Houston	(281)	(281)	(713)	
Tom Menges	·	552-1147	552-1484	560-8038	
South Permian Asset:	Midland	(432)	(432)	(432)	
Matt Hyde		685-5802	685-5930	556-5016	
RMT/PMT Leaders: South Permian Ass	set				
Frontier RMT:	Midland	(432)	(432)	(432)	(432)
John Nicholas		685-5600	` ′	, ,	,
		1	1		
			:	;	
PERSON	LOCATION	OFFICE	FAX	CELL	PAGER
Production Coordinators: S. Permian	Asset			1	**
New Mexico: John Erickson	Hobbs	(505)	(505)	(505)	(505)
		393-2174	397-2671	560-8038 (432) 556-5016 (432)	370-6836
	OXY Permian HES Pers	sonnel			-
OXY Permian	Crisis Team Hotline Notif	ication (713) 9	35-7210	1	

PERSON	LOCATION	OFFICE	FAX	CELL	PAGER
HES Coordinators & Area of Responsibility					
HES Techs & Area of Responsibility			<u>!</u> .		
Hobbs RMT: Steve Bishop	Hobbs	(505) 397-8251	(505) 397-8204	(505) 390-4784	(877) 339-1954- 1118#
Frontier-New Mexico: Rick Kerby	Hobbs	(505) 393-2174	(505) 393-2671	(505) 390-8639	(505) 370-6527

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources


Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144

March 12, 2004

Pit or Below-Grade Tank Registration or Closure
Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \) No \(\subseteq \)

Type of action: Registration of a pit o	r below-grade tank 🛛 Closure of a pit or below-g	rade tank	
Operator: _OXY U.S.A. W.T.P. Limited PartnershipTelephone: 432.685 Address: _P.O. Box 50250 Midland, TX 79710	-37824 _{U/L or Qtr/Qtr_} SWSE (O) Sec3		
Pit Type: Drilling Production Disposal Workover Emergency Lined Unlined Liner type: Synthetic Thickness 12_mil Clay Volume 11000 bbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes		
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points) 0	
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points) 0	
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) 0	
	Ranking Score (Total Points)	0	
If this is a pit closure: (1) attach a diagram of the facility showing the pit's onsite ☐ offsite ☐ If offsite, name of facility	(3) Attach a general description of remedial ac	ction taken including remediation start date and end	
I hereby certify that the information above is true and complete to the best of a been/will be constructed or closed according to NMOCD guidelines , a Date: March 28, 2006	general permit , or an (attached) alternative (Signature Signature	OCD-approved plan	
Approval: Date: Printed Name/Title PETROLEUM ENGINEER APR 2 0 2006	Signature Signature		



Sent: Thu 4/20/2006 8:25 AM

The sender of this message has requested a read receipt. Click here to send a receipt.

Muli, Donna, EMNRD

From:

Phillips, Dorothy, EMNRD

To:

Mull, Donna, EMNRD

Cc:

Subject:

RE: Financial Assurance Requirement

Attachments:

All have blanket and none appear on Jane's list.

From: Mull, Donna, EMNRD

Sent: Thursday, April 20, 2006 8:15 AM

To: Phillips, Dorothy, EMNRD

Cc: Macquesten, Gail, EMNRD; Sanchez, Daniel J., EMNRD

Subject: Financial Assurance Requirement

Dorothy,

Is the Financial Assurance Requirement for these Operators OK?

Petrohawk Operating Co (194849) Pride Energy Co (151323) COG Operating LLC (229137) OXY USA WTP Limited Partnership (192463) Chevron USA Inc (4323) John H Hendrix Corp (12024) Latigo Petroleum Inc (227001)

Please let me know. Thanks and have a nice day. Donna