

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-27487</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator <b>Kevin O. Butler &amp; Associates, Inc.</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>P.O. Box 1171, Midland, TX 79702</b>		7. Lease Name or Unit Agreement Name <b>Delmont L. Hatfield</b>
4. Well Location Unit Letter <b>J</b> : <b>1980</b> feet from the <b>South</b> line and <b>1765</b> feet from the <b>East</b> line Section <b>23</b> Township <b>16S</b> Range <b>38E</b> NMPM County <b>Lea</b>		8. Well Number <b>1</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3696 GR</b>		9. OGRID Number <b>012627</b>
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT I  
REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

INT TO PA **PM**  
P&A NR  
P&A R

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RU well service, LD rods &  
NU BOP, TDH w/ 1'  
RU WL. 5'  
YTH w/  
Set 35'

SEE ATTACHED  
CONDITIONS OF APPROVAL

TDH w/ 1' - 20 SXS-class H' cement plug, WOC 4 hrs. Tag top of this plug  
TDH w/ 1' - 340' spot 30 SXS  
ND BOP, RD WISU. Cut off well  
... (no earthen pit)  
... cement plug to surface.  
... marker. Cut off anchors.  
... clean & rehab. loc.

Spud Date:

Rig Release Date:

NOTIFY OCD 24 HOURS PRIOR TO  
BEGINNING PLUGGING OPERATIONS


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **M. Y. Merchant** TITLE **Agent** DATE **3.1.18**  
Type or print name **M. Y. Merchant** E-mail address: **mymerchant@pnmca.com** PHONE: **(575) 492-1236**  
For State Use Only  
APPROVED BY: **Manuel Furtado** TITLE **Petroleum Engr. Specialist** DATE **03-06-2018**  
Conditions of Approval (if any):

C103 INTENT TO P&A EXPIRES  
**03-06-2019**

Mym 3/1/18

Hatfield well # 4  
ULJ, Sec. 23 T16 S. R. 38. E  
La County, New Mexico  
API # 30.025-27487



## CONDITIONS OF APPROVAL

Delmont L Hatfield #1

30-025-27487

UL – J, Sec 23, T16S, R38E

1980' FSL 1765' FEL

13 3/8" 48 # @ 342' w/ 375 sx (circ)

9 5/8" 36 & 40 # @ 4229' w/ 1700 sx

5 1/2" 15.5 & 17 # @ 8625' w/ 3025 sx (circ)

Perfs 8314' – 8337'

Set CIBP at 8250'.

Circulate mud laden fluid. Pressure test casing.

Spot 30 sx Class H cement on CIBP.

POOH to 6250'. Spot 30 sx Class C cement.

POOH to 4279'. Spot 30 sx Class C cement. WOC & Tag. (Shoe Plug)

POOH to 3200'. Spot 30 sx Class C cement. (Base Salt)

POOH to 2200'. Spot 30 sx Class C cement (Top Salt)

POOH to 396'. Fill to surface w/ Class C cement. (Shoe Plug, Water Board Plug)

Cut off wellhead 3' below GL. Verify cement to surface all strings.

Install upright P&A marker.