A						
Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018	
SUNDRY NOTICES AND REPORTS ON WELLS NMOCD					5. Lease Serial No. NMNM26079	
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name					
SUBMIT IN	TRIPLICATE - Other instru	uctions on pa	HOBB	s oci	7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well MAR 2 2 2018 ☑ Oil Well □ Gas Well □ Other					8. Well Name and No. OCHOA FEDERAL 1H	
2. Name of Operator EOG RESOURCES INCORF	Contact: K ORATEDE-Mail: Kay_Maddo	AY MADDOX x@EOGRESOU		EIVED	 API Well No. 30-025-27623 	
3a. Address 3b. Phone No. (include area PO BOX 2267 Ph: 432-686-3658 MIDLAND, TX 79702 Ph: 432-686-3658					10. Field and Pool or Exploratory Area DRAPER MILL; BONE SPRING	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 15 T25S R33E SWNE 1979FNL 1979FEL 32.132365 N Lat, 103.546470 W Lon					LEA COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES) T	O INDICAT	E NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION TYPE OF ACTION						
⊠ Notice of Intent	Acidize	Deepe	n	Product	ion (Start/Resume)	□ Water Shut-Off
□ Subsequent Report	□ Alter Casing		ulic Fracturing	C Reclam		U Well Integrity
☐ Final Abandonment Notice	Casing Repair Change Plans	_	Construction nd Abandon	Recomp	nplete 🗖 Other prarily Abandon	
	Convert to Injection			Water D		
following completion of the involve testing has been completed. Final A determined that the site is ready for EOG proposes to temporarily 1. Set 5 1/2" CIBP @ 11,600 2. Dump bail 4 sxs sand, and 3. TA well for purpose of usin monitoring 4. NU wellhead and secure fo 5. Perform MIT test to ensure	final inspection. y abandon this well using the ; 5.5" liner top is at 11,519' d 20' cmt of top of CIBP ng it later in field development or shut-in.	e following pro	ocedure:	CEE A	ГТАСНЕД В	
Please reference attached cu	irrent and proposed wellbor	e diagrams.		\bigcap		
This well makes a small amt	of oil (avg 6 BOPD in 2017)	Recent comp	etion of the Str	eetcar Fede	eral	
14. I hereby certify that the foregoing	Electronic Submission #40 For EOG RESOUR	RCES INCORIPO	DRATED. sent t	o the Hobbs	N	
Committed to AFMSS for processing by JENNIFER SANCHEZ on 03/12/2018 () Name (Printed/Typed) KAY MADDOX Title REGULATORY ANALYST						
Signature (Electronic Submission) Date 03/02/2018						
	THIS SPACE FOR	R FEDERAL			SEAR 1 2 2018	
Approved By Conditions of approval, if any, are attach certify that the applicant holds legal or et which would entitle the applicant to cond	quitable title to those rights in the s		Office	BURE	AU OF LAND MANAG	CE Part
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulent	3 U.S.C. Section 1212, make it a ci	rime for any pers o any matter with	on knowingly and	willfully to ma	ake to any department cr	agency of the United
(Instructions on page 2) ** OPERA	TOR-SUBMITTED ** OP	ERATOR-S		* OPERAT	OR-SUBMITTED	**
		1				
MUB/OCD 3/26/2018						

1

Additional data for EC transaction #406403 that would not fit on the form

32. Additional remarks, continued

ŝ


ø


#602H & 603H will replace production from this well at a lower operational cost via these 2 new horizontal wells. The Ochoa well is strategically located to monitor the BHP throughout the life of the Bone Spring production from the Streetcar wells.

Ochoa Federal #1 R/E Red Hills (Bone Springs) Field Lea County, NM

API #: 30-025-27623

1,979' FNL





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 03/13/2019 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ochoa Federal 1H

- 1. Well is approved to be TA/SI for a period of 12 months or until 03/13/2019
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 03/13/2019
- 4. COA's met at this time.