

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.  
30-025-26646

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Maralo "16" State

8. Well Number 4

9. OGRID Number  
281085

10. Pool name or Wildcat  
Sioux Tansill (Yates 7 Rivers)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
RMR Operating, LLC

3. Address of Operator  
14282 Gillis Rd. Farmers Branch, Texas 75244-3715

4. Well Location

Unit Letter F : 1980 feet from the North line and 1980 feet from the West line  
Section 16 Township 26S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
2943'GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT FURTHER ACTION

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐ INT TO PA PM  
CASING/CEMENT JOB ☐ P&A NR           
P&A R         

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Pressure test casing to 500 psig  
Circulate hole with 9.5# Brine w/ 12.5# gel/BB1  
Spot 30 sx on top CIBP at 3135'. ~~Spot 25 sx at 2950'~~

Perf 5-1/2" casing (4 SPF) @2050'. Sqz with 75 sxs. Displace to 1950'. WOC and Tag ✓  
Perf at 722'. SQZ w/ 40 SX. TAG at 622' OR BETTER  
Perf at 200'. Circulate cement to surface inside/outside 5.5" casing

verify cement to surface  
Cut-off wellhead. Install marker. Clean Location

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO  
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ross Pearson TITLE V.P. Operations DATE 4/3/18

Type or print name Ross Pearson E-mail address: ross@redmountainresources.com PHONE: 469-995-0425  
For State Use Only

APPROVED BY: Mahe Pritchard TITLE P.E.S. DATE 04/09/2018

Conditions of Approval (if any):

C103 INTENT TO P&A EXPIRES  
1 YEAR FROM DATE OF APPROVAL

Maralo "16" State #4  
1980' FNL, 1980' FWL  
Section 16, T-26-S, R-36-E, Unit F  
Lea County, New Mexico  
API- 300-25-26646

Date: 02/08/2012

WELLBORE DIAGRAM - NOT TO SCALE

