Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources		May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-03469	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type	of Lease
District III	1220 South St. Francis Dr.			STATE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1167		
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name o	r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Ct. t. III	
PROPOSALS.)				State H 8. Well Number 7	
1. Type of Well: Oil Well Gas Well Other				9. OGRID Number 004537	
2. Name of Operator Citation Oil & Gas Corp.				9. OGRID Numb	per 00453/
3. Address of Operator				10. Pool name or Wildcat	
P.O. Box 690688, Houston, Texas 77269-0688				Eumont Yates Seven Rivers Queen	
4. Well Location					
Unit Letter _J : _1980 _ feet from the _South _ line and1980 _ feet from the _East _ line					
Section 13 Township 21S Range 35E NMPM Lea County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3595' DF					
Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Distance from nearest surface water					
					rface water
Pit Liner Thickness: mi			··· · · · · · · · · · · · · · · · · ·	onstruction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK		N 🗆	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	ING OPNS 🗆	PLUG AND ABANDON
					1 FOO AIND ADAINDON
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	JOB	
OTHER:		П	OTHER: Temps	carily Abandon wel	I the to
13. Describe proposed or com	pleted operations. (Clear				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
MIRU – ND WH / NU BOP and POOH with tubing. RIH with bit to 3817'. Set CIBP @3750' and capped with 2 sx class "C" cement.					
Isolated casing leaks and set RBP @1575' + 2 sx sand and set cement retainer @604'. Squeezed leak 1078' – 1182' with 125 sx "C";					
squeezed leak 480' - 578' with 100 sx "C". Drilled out cement and attempted to set packer @1260' - could not get a good seat. TIH, set					
packer @1562' and tested RBP - OK. Released and moved packer uphole testing for casing leaks - isolated leak 1087' - 1150' and					
squeezed with 60 sx "C". Drilled out cement to 1130', fell through and circ'd sand off RBP. CHC, released RBP and POOH. RDMO—well Temporarily Abandoned 3/2/2006.					
well reliiporarily Abalidolled 3/2/2000.					
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
				(5.5	20 10 Al 20
				199	\$ 27 B
					(S) (S) (S)
					~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-					
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .					
SIGNATURE MULLA	Sarrie	TITLE	Production Analys	t III DAT	E <u>April 19, 2006</u>
Type or print name Debra Har	arris		address: dharis@co	•	ne No (281) 517-7194
9/					
APPROVED BY:	101	OCH	ELD REPRESENTATIV	E IVSTAFF MANA	GER DATAPR 2 5 2006