UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS BBS	OCD
Oo not use this form for proposals to drill or to re-enter an	

NMLC031670B

Do not use this form for proposals to drill or to re-enter an								
abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit	or CA/Agreement, Na	ame and/or No.	
1. Type of Well			THE COLUMN	/ED		ame and No.	100	
☑ Oil Well ☐ Gas Well ☐ Oth					WARREN MCKEE UNIT 128			
2. Name of Operator Contact: GREG BRYANT CONOCOPHILLIPS COMPANY E-Mail: GREG.BRYANT@BASICENERGYSERVICES.COM					9. API Well No. 30-025-34158-00-S3			
3a. Address 3b. Phone Ph: 432- MIDLAND, TX 79710 Fx: 432-1						 Field and Pool or Exploratory Area WARREN 		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description				11. County or Parish, State			
Sec 29 T20S R38E NWNE 330FNL 1650FEL 32.550397 N Lat, 103.167437 W Lon					LEA C	COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	, REPORT	, OR OTHER DA	ATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	☐ Acidize	□ Dee	pen	☐ Produc	tion (Star		Da	
	☐ Alter Casing	□ Нус	Iraulic Fracturing	☐ Reclam	nation	INT TO PA		
☐ Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recom	plete	P&A NR _		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug	g and Abandon	☐ Tempo	rarily Ab	P&A R		
	☐ Convert to Injection	Plug	g Back	□ Water I	Disposal			
following completion of the involved testing has been completed. Final At determined that the site is ready for final At determined that the site is ready for final At determined that the site is ready for final fina	pandonment Notices must be filinal inspection. OOH rods & Prod. Tbg rc hole w/ MLF. Cap w/ 6 280' 280' 280' 280' 280' 280' 280' 280'	Osx cmt to 64	400'. WOC-Tag	SEI CO	E ATTA NDITIO	CHED FOR	PROVAL	
14. I hereby certify that the foregoing is Name(Printed/Typed) GREG BR	Electronic Submission # For CONOCO Committed to AFMSS for p	PHILLIPS CO	MPANY, sent to t	he Hobbs /02/2018 (18				
Signature (Electronic S			Date 04/27/2					
	THIS SPACE FO	OR FEDERA	AL OR STATE	OFFICE U	ISE			
Approved By	a.C. Com	2	Title 5	e col	PET	-	5.278 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conduct the applicant	uitable title to those rights in the	subject lease	Office (arls d	bad			
Title 18 U.S.O. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any pe	erson knowingly and	willfully to m	ake to any de	epartment or agency of	of the United	

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

17/2"

Date 3/26/13 Subarea lease & West No ega. Description 330' FNL - 1650' FEL P&S 55sx cmt @ 60 3 13-5/6" 40#/ft, 400" County State New Mexico Field Cmt'd w/ 440 SX TOC - Circld to surface Date Spudded P&S B0sx cmt @ 450'-330' Tag API Number P&S 65sx cmt @ 1500' 1380' Tay Spot 30sx cmt @ 2450 -2350 10-3/4" 40 5#/ft, 3000" 2997 - Spot 30sx cmt @ 2450'-2330' Tag Lease ID Cmt'd w/ 455 SX,TOC 1430' - Temp survey Field Number Spot 75sk cmt @ 3000"-2700" Tag Spot 30sx cmt @ 1850" 1500" Tag Spot 30sx smt @ 4150'-4030' Tag T/Salt 7-5/8" 29 7#11.9428" 9320 Cmt'd wi 2330 SX TOC Surface ? 2530 Spot 30sx cmt @ 5400'-5280 6170 TOC TIS Spc: 30sx cmt @ 5900' 5780' Yates 2962 773 Spot 60sx cmt @ 6656'-6400' Tag Set CIBP @ 6656 3532 Qu Penrose GB 3840 SA 414/ PBTD g7328 Sqz/d Coment Retainer @7463* 9075/9200 BP 5384 Open Hole TD @ 10,294 6682 5+ 7806 8162 8760 sim

9217

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

					Date: 3/26/18	
RKB @	3556.5'					
DF @	3556 5					
GL @	3539'	Subarea	SENM / Hobbs	East		
		Lease & Well No	. W	arren Unit 128		
		Logal Descriptio	n: 298 2	OS 38E NE NW NE	330' FNL - 1650' FEL	
1111	Surface	County	LEA	State	New Mexico	_
	13-5/8", 40#/ft	Field	WARREN	0.0.0	TOW INDAIDO	_
	Cmt'd w/ 440 SX	Date Spudded	2/17/	no.		_
,				90		_
	TOC - Circ'd to surface	API Number	3002534158			_
111	Intermediate			Operator Nun	nber	
111	10-3/4", 40 5#/ft			Lease ID		
	Cmt'd w/ 455 SX			Field Number	T.	
	TOC - 1430' - Temp survey					
11						
11						
11						
11	Production					
11	7-5/8", 29.7#/R					
11						
	Cmt'd w/ 2330 SX					
11	No plug down, DV opened early. No second stage. TOC ut	nknown				
11						
11						
11	Rods & pump detailed					
11	on Tubing & Rods Tab					
=						
=	■ Dnnkard					
1.1	Perfd					
=	=6756' - 6900'					
	-					
	■ =					
11						
<u> </u>						
=						
11						
11	П					
	HII					
	_					
25	PBTD @7328					
SE I	FX Soz'd					
TX	Cement Retainer @7463					
1	5-3					
	331					
1 14						
1	Open Hole					
,	TD @ 10,294'.					

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.