

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

**HOBBS OGD CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 07 2018

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36247
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other: -----		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 30
4. Well Location Unit Letter <u>N</u> : <u>627</u> feet from the <u>South</u> line and <u>1782</u> feet from the <u>West</u> Line Section <u>30</u> Township <u>18-S</u> Range <u>38-E</u> NMPM Lea County		8. Well Number: 527
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3649' (KB)		9. OGRID Number: 157984
		10. Pool name or Wildcat Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Pulling Unit and reverse unit.
2. Check pressure, ND WH and NU BOP
3. POOH with ESP.
4. RIH with CIBP and set below perfs (~4206') POOH
5. RIH with packer, Test CIBP and get injection rate into the perfs POOH
6. RIH w/ CICR and cement squeeze Perfs
7. RIH with bit and Drill out CICR, Cement and CIBP.
8. CO to PBTD POOH
9. RIH with new ESP design
10. ND BOP - NU WH
11. Place well back on production.
12. RDMO.

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Production Engineer DATE 06/06/2018

Type or print name Carlos Restrepo E-mail address carlos\_restrepo@oxy.com PHONE: 713-366-5147

For State Use Only

APPROVED BY:  TITLE AO/II DATE 6/7/2018  
Conditions of Approval (if any):

MB