

Submit 1 Copy To Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised August 1, 2011

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87401
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD
OIL CONSERVATION DIVISION
JUL 31 2018
RECEIVED

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-07543
5. Indicate Type of Lease STATE [X] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 29
8. Well Number: 141
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [] Other: -----
2. Name of Operator Occidental Permian Ltd.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323
4. Well Location Unit Letter M : 660 feet from the South line and 660 feet from the West Line
Section 33 Township 18-S Range 38-E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3635' (DF)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [X] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1. POOH with production equipment.
2. Clean out to 4316' (TD)
3. Perf following intervals: 4143' to 4146', 4117' to 4120', 4090' to 4100', 4060' to 4070', 4035' to 4047'
4. Acid Treat new perfs with ~ 3000 gals of 15% HCL PAD acid
5. RIH with production equipment
6. Return well to production

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date: []

Rig Release Date: []

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Engineer DATE 07/30/2018

Type or print name Carlos Restrepo E-mail address carlos_restrepo@oxy.com PHONE: 713-366-5147

For State Use Only
APPROVED BY: [Signature] TITLE AO/I DATE 7/31/2018

Conditions of Approval (if any):
Additional Data that would not fit on the form.

MB