Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	Energy Minerals and Natural Descurres		Form C-103 Revised July 18, 2013	
$\frac{District 1}{1625 \text{ N. French Dr., Hobbs, NM 88240}}$ District II – (575) 748-1283	5 N. French Dr., Hobbs, NM 88240		WELL API NO.	30-025-42448
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FEE 🛛
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, IN	IVI 87303	6. State Oil & Gas I	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name	
PROPOSALS.)			MADERA SWD 8. Well Number #1	
1. Type of Well: Oil Well Gas Well Other SWD HOBECCCD 2. Name of Operator			9. OGRID Number	
. OWL	SWD OPERATING, LLC	AUG 28 2018		308339
3. Address of Operator	Dollar TV 75255	1100 - 0 2010	10. Pool name or W	
8214 Westchester Drive, Ste 850 4. Well Location	, Dallas, IX 75255	RECEIVED	SWD; DEVO	NIAIN (90101)
Unit Letter_N: 433 feet from the <u>SOUTH</u> line and <u>1970</u> feet from the <u>WEST</u> line				
Section 14	Township 24 S			unty LEA
	11. Elevation (Show whethe	er DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
		-		
				_
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				
CLOSED-LOOP SYSTEM [OTHER:				-
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 7/12/2015 – Intermediate Casing				
TIH fill drill pipe every 20 STDS T/6872				
Wash & ream to btm @ 6915				
Circ hole clean pump 2 hi vis sweeps around spot LCM pill on bottom				
POOH F/6915' to BHA (Hole in good condition)				
POOH with BHA break bit and bit sub				
Pull wear bushing and clean floor				
Hold saftey meeting w/ Rig crew, Franks, Rodgers, and Timco on casing R/U and running csg				
R/U casing crew and L/D truck M/U Two jt Shoe track and test (test good) and three jts. Total of 5 jts				
R/U CRT tool				
Running 13.625 casing a	t 9 jts (374')			
Continued on attachment Submitted to complete well file documentation on 8/24/2018				
Spud Date: 6/23/20	Rig Releas	e Date: 2/2	22/2016	
0/25/20	15		22/2010	
			11.11.0	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
20				
SIGNATURE Sen J	TITLE	Agent for Owl	DATE	8/24/18
Type or print name	E-mail add	iress:	PHON	E:
ABAGE TO STATE USE ONLY MALEY LAW TITLE AO/I DATE 8/28/2018				
Conditions of Approval (if any):				
Accepted for Record Only				

Madera SWD No.1 -- Intermediate Casing Sundry Report, continued...

7/13/2015

•

Run three jts of casing Change out single latch elevators Run 13.625 casing Change dies in Timco casing elevators Run 13.625 casing Change out single door elevators Run 13.625 casing Run casing @ 5909'. Tagged up with casing @ 5909'. Working casing with CRT. (Diff Sticking)

7/14/2015

Circulate and work casing @ 5909'. Preform derrick inspection and service rig. Circulate and work casing @ 5909'. Spot fresh water pill @ 5909'. Work casing and casing became free @ 5909'. Attempt to remove CRT tool from casing. (No success) Waiting on 500 ton bells and elevators. Cut 2" off top casing collar. Try to release CRT (no success) L/D 350 ton bells and elevators R/U 500 ton Bales and elevators

7/15/2015

Inspect & 500 Ton Bells and elevators. R/U L/D pole, Work casing Circulate B/U with rig pump. Inspect derrick and service top drive Circulate and work casing Corculate and spot fresh water pill. Broke out CRT tool & L/D Break 13.625 collar, M/U fill up tool Circulate a B/U Remove casing collar, P/U jt of casing, M/U collar, L/D JT Run 13.625 casing R/D fill up tool & R/U circulate swedge and hose Circulate hole to cement and R/D caing tools and L/D truck

7/16/2015

Circulate hole Hole PJSM with Allied cement personal and rig crew. R/U cement head and lines. test lines to 5000k (Lines Tested) Pump 30 bbl H2O spacer, 20 bbl gel spacer, pump 375 bbl lead cement, 75 bbl tail cement, drop plug, pump 20 bbl H2O displacement and 970 bbl brine, 26 bbl H2O. (Bump Plug) FCP 1800 psi and 500 psi over after bumping plug. (Float did not hold) pressure back up on cement with pump truck and shut in. (No Cement To Surface). Waiting on cement. Shut Down due to bad weather R/D cement head and lines