

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00941
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> <b>HOBBS OCD</b>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico for Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88249		7. Lease Name or Unit Agreement Name Artesia Metex Unit
4. Well Location Unit Letter <u>K</u> : <u>1650</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>24</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>Eddy</u> County		8. Well Number <u>006</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864
10. Pool name or Wildcat Artesia QU-GB-SA		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENT</b> PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: _____	<b>INT TO PA</b> P&A NR <u>PM</u> P&A R _____	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A XX CASING/CEMENT JOB <input type="checkbox"/> OTHER: _____
---	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mark Whitaker TITLE P.E.S. DATE 9/27/18

Conditions of Approval (if any):

**Plugging Report**  
**Artesia Metex Unit #6**  
**API 30-015-00941**

8/29/2018 Cleared location and filled in void around the wellhead. Rigged up. Nipped down the wellhead and welded a 2 3/8" collar on the joint of tubing running through the wellhead. Worked to get the wellhead cap off. Installed BOP. Worked packer free. Well started to kick up the tubing. Pumped 10 bbls brine down the tubing and 30 down the casing. SION

8/30/2018 Moved in remaining equipment. Killed well and POOH with tubing. 57 joints 2 3/8" fiberglass lined tubing. Packer was set at 1768'. Set 5 1/2" CIBP at 1750' as per OCD. Circulated MLF and tested casing to 550#. Casing good. Spotted 50 sx cement on top of CIBP and POOH. Perforated casing at 548'. Closed BOP and loaded casing. Pressured up on perfs. Perfs would not take fluid. RIH with tubing to 602' and spotted 25 sx cement. POOH and SION.

8/31/2018 Tagged cement at 380'. POOH to 101' and circulated cement to surface with 15 sx. Rigged down and cut off wellhead. Cement was to surface in both strings of casing. Installed marker and cut off anchors. Cleaned pit and cleared location.