Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Expires: January 31, 20
, 5 .	Lease Serial No. NMNM0149957

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

apandoned we	II. USE TORM 3160-3 (AP			,		
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. Official ame and No. BRSOKS FEDERAL 06 10. API Well No.					
1. Type of Well			NC r	Welf Name and No. BROOKS FEDER		
☑ Oil Well ☐ Gas Well ☐ Oth Name of Operator	Contact:	MELISSA SZUDERA	00/242	Welf Name and No. BROOKS FEDER 018. API Well No. 30-025-01713-0		
MARATHON OIL PERMIAN L	LC E-Mail: mszudera(@marathonoil.com	RECE.	30-025-01713-0)0-S1	
a. Address 5555 SAN FELIPE STREET HOUSTON, TX 77056		3b. Phone No. (include area Ph: 713-296-3179	code)	10. Field and Pool or SALT LAKE	Exploratory Area	
Location of Well (Footage, Sec., 7)		11. County or Parish, State			
Sec 7 T20S R33E SESW 660		•	LEA COUNTY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATUR	EE OF NOTICE	L, REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deepen	, 🔲 Produ	ction (Start/Resume)	☐ Water Shu	t-Off
	☐ Alter Casing	☐ Hydraulic Fractu	ring 🗖 Reclai	nation	☐ Well Integr	rity
Subsequent Report	□ Casing Repair	■ New Construction	n 🗸 📋 Recon	plete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abando	on 🚰 🗖 Tempe	orarily Abandon		
	☐ Convert to Injection	Plug Back	□ Water	Disposal		
9/27/2018 -MIRU. Laid down 1-11/16" and tagged @ 4290' 9/28 -Ran in hole w/ to check wireline down. RIH 140 jts of every 25 jts. Failed attempt. E Liad down 8 jts of 2 3/8" tbg a 9/29 - Nipple up BOP and tes Log good. Tested BOP, flang but injected 2 bbls/min_Notifie 4494. Tagged same spot, laid	117 rods. Pulled 96 jts of POOH. for casing obstructions. To 2 3/8" tbg and AD1 packet and AD1 packet and AD1 packet and Stood to Test fail due to leaking the Bull plug below surface ad BLM. RIH open ended down 1 jt. Pumped 120 to true and correct.	agged @ 4235', Pulled o er. Attempt to set AD1 ten g. Loaded csg with 10 bb back 132 jts. Nipple dov flange. RU wireline run co washed out. Test failed. without tension packer a	ut and rigged tion set packer Is of brine wate vn BOP. ement bond log Flange and BO nd verify stack ovn 44jts. Leavin	REC DUE P held out @ g 95	ATION PROCEI ATIACHED LAMATI	ION
	For MARATHI itted to AFMSS for process	ON OIL PERMAN LLC, se sing by DEBORAH MCKIN	nt to the Hobbs NEY on 10/04/20	18 (19DLM0022SE)		
Name (Printed/Typed) MELISSA	SZUDERA	Title RE	GULATURY	OMPLIANCE REP		
Signature (Electronic			/04/2018			1
	THIS SPACE FO	OR FEDERAL OR STA	TE OFFICA	JEEPTED FOR	RECORD	
Approved By		Title			Date	
nditions of approval, if any, are attache	d Approval of this notice does			1 OCT 1 1 2	2018	
tify that the applicant holds legal or equich would entitle the applicant to condu	uitable title to those rights in the act operations thereon.	e subject lease Office		AMCKinney	LIE	
le 18 U.S.C. Section 1001 and Title 43 tates any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	crime for any person knowing	ly and willful y to a	CARLSBAD FIELD	NAGEMBING Uni OFFICE	ed
						<u> </u>

Additional data for EC transaction #438335 that would not fit on the form

32. Additional remarks, continued

jts of 2 3/8" in well @ 3052. Pumped 60sx cement. 9bbls fresh water. Stood back 40 jts leaving 55 jts 2 3/8" @ 1770.75'. WOC.

9/30 -RIH w/18 stds and a single tag TOC @ 2961'. Test csg to 1500psi, held. Notified BLM. Attempted to find surface casing valve to perf. Unable to locate. Only have 9 5/8" up to surface. Cellas is cased in cement. Notified BLM, Obtained approval to run cement up to surface without perforating. Spot 120sx of cement. Stood back 17 stands, laid down 6jts.

10/1 -TIH and tag TOC @ 2585', Spot 120sx, Class C to 2225'. LD tbg out of hole to 2188'. Spot 120sx cement to 1865'. LD tbg to 1738' and spot 120sx cement to 1377'. LD tbg to 1287' Spotted 120sx, class C cement, to 927'. Circulated. POOH.

10/2 TIH w/30 its tag TOC @ 965', LD 1 it tbg, spot 120sx, class C cement. LD 14its. Spot 150sx, class C cement. POOH tbg fillup wellbor to surface w/30sx clas C cement. RD WOR.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted