

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOB
09/29/2018
RECEIVED

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21603
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1311
7. Lease Name or Unit Agreement Name New Mexico "X" State
8. Well Number 1
9. OGRID Number 247692
10. Pool name or Wildcat Mescalero San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4324' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
JAY MANAGEMENT COMPANY, LLC

3. Address of Operator
2425 WEST LOOP SOUTH, SUITE 810 HOUSTON, TX 77027

4. Well Location
Unit Letter P : 400 feet from the EAST line and 330 feet from the SOUTH line
Section 10 Township 10S Range 32E NMPM County LEA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.
Restoration Due By 09-14-2019

SUBSEQUENT REPORT OF:

DON REMEDIAL WORK ALTERING CASING
 L COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER:

PNR

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 09/11/2018 : Set CIBP at 4000'. Circulate MLF. Spot 25 sacks class C cement on CIBP.
Pressure test casing to 500 psi don't hold. Tag at 3965' Call OCD for instruction.
Pull packer to 3665' and pump 25 sacks class C cement to 3965'. (Per Mark w/OCD).
POOH with tuning without packer. Packer left at 3965'. (Call OCD).
- 09/13/2018 : Perforate at 2275' attempted to squeeze. Call OCD for instruction.
Pump balance plug at 2325' with 25 sx class C cmt (Per Mark w/OCD). Tag at 1940'.
Perforate at 1616'. Squeeze 40 sx class C cmt. Tag at 1445'.
- 09/14/2018 : Perforate at 200' . Squeeze 80 sx class C cmt. Circulate cmt to surface.
- 10/03/2018 : Cut off wellhead 3' below ground level and install below ground level P&A marker.

Spud Date: 09/10/2018 Rig Release Date: 09/14/2018

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Clayton Griffin TITLE District Manager DATE 10/25/2018

Type or print name Clay Griffin E-mail address: cgriffin@jaymgt.com PHONE: 574-707-5691

For State Use Only
APPROVED BY: Mark Whittem TITLE P.E.S. DATE 10/30/2018

Conditions of Approval (if any):