Submit I Copy To Appropriate District	State of Now M	(autoa		E	
Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-041-10553		
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE S FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			K-1276		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Jennifer Chaveroo SA Unit		
			8. Well Number		
1. Type of Well: Oil Well 📓 Gas Well 🗌 Other 💷			#42		
2. Name of Operator			9. OGRID Number		
Ridgeway Arizona Oil Corp         3. Address of Operator			164557     10. Pool name or Wildcat		
1250 Wood Branch Park Dr. Suite 400, Houston, TX 77079			Chaveroo San Andres		
4. Well Location	·				
M - Unit Letter_: 660_feet from	n the South line and 660 feet from	the West line			
Section 25	Township 7S	Range 33E	NMPM	Roosevelt County	
	11. Elevation (Show whether DI 4,337' KB	R, RKB, RT, GR, etc.			
an a	4,557 KD		and the second		
12. Check A	ppropriate Box to Indicate N	Nature of Notice,	Report or Othe	r Data	
NOTICE OF IN	TENTION TO	SUP	SEQUENT R		
NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☑       REMEDIAL WORK ☑ ALTERING CASING ☑					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	Т ЈОВ		
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
	eted operations. (Clearly state all				
proposed completion or reco	rk). SEE RULE 19.15.7.14 NMA	C. For Multiple Co	mpletions: Attach	wellbore diagram of	
	, in proceeding to the second s				
	I. with tubing and existing down I				
<ol> <li>RIH with bit and scraper to bottom and clean out fill if necessary. RDMO pulling unit.</li> <li>Move in and rig up wireline unit.</li> </ol>					
	00' of top perforation. Fill casing	with water. Test to 5	500 psi for 30 min.	, R	
5. Test chart will be furnished	with final report.			COI-311-B 10/4/2018	
,			1	M	
Condition of Ap	movel -			1/2010	
Spud Date: OCD Hobbs off		)ate:			
prior of running M	T Test & Chart	/aic.			
I hereby certify that the information a	bove is true and complete to the l	best of my knowledg	ge and belief.		
$\sim$					
SIGNATURE	TITLE	Operations Manag	er DATE	10-31-2018	
			× •		
Type or print name Kevin Go	E-mail address:	kgoebel(a	pedevco.com	PHONE: /13-5/4-/90/	
For State Use Only	NR.	1-1-			
APPROVED BY:	Shown title	AU/I	D	ATE 11/8/2018	
Conditions of Approval (if any):		1			